KMI Sports Construction

7070 US 290 Dripping Springs, TX, 78620 512-962-3955

info@kmisportsconstruction.com

www.KMIconnect.com

Instagram: @KMITurf - Facebook: @KMIsports



Date	1/3/2023] [Quote#	11171	VCv3
Bill to Address:			Remit to Address:		
Name	WHLL - Hatley Infield Dirt/Grass		7070 US 290		
Address	1314 Exposition Blvd Austin TX 78703		Dripping Springs, TX, 78620		
Email & Phone	512-695-6709 - atxbta@gmail.com - Brandon Aghamalian		info@kmisportsconstruction. com		
Payment Terms: [Deposit required to secure a spot on our schedule, remaining balance due at the	ne time the job	is completed		
Item #	Materials	Quantity	UOM		
	Hatley Infield Dirt - Phase 1 - After Approved Jan 18th, 2023				
1	Clean and remove all of the overgrown grass from the existing dirt infield area and the home plate circle.				
2	Re-shape / clean up the infield/outfield dirt and grass radius				
3	Re-shape / clean up all of the lines on the infield dirt/grass edges				
4	Nail drag all of the dirt surfaces				
5	Add needed baseball field dirt (Elgin Facility), groom, roll and regrade the infield Sandy loam and red clay, mixed at the factory				
6	Remove any lips from the grass to dirt areas				
	Total Phase 1 - After Approved Jan 18th, 2023				\$13,929.44
	Hatley Infield Dirt - Phase 2 After the 2023 Spring Season				
7	Remove all of the infield grass				
8	Add new soil conditioner, regrade and compact				

Customer Signature:		Total Project Price	\$21,779.44
Financing	KMI now offers financing for all commerical projects, ask us today for more details	Due at Completion	\$8,711.78
15 day expiration	This quote expires in 15 days. After which, we will need to reacess costs, supplies, and material available.	Deposit	\$13,067.66
Mobilization	If KMI is scheduled and confirmed to work on a project site and travels to the site and the site is not ready and/or other trades are in the project area preventing work to start, there will be a remobilization charge.	Subtotal	\$21,779.44
	Please Note - Phase 2 work is an estimate based on today's pricing.		
	Total Phase 2 - After the 2023 Spring Season	Approx Range	\$6,850 - \$7,850
10	Add sand to top dress the sod and seams		
9	Add new Bermuda sod to the infield		