

Troy – here's what I got from O'Brien:

9122 Sheringham Drive: Lump Sum: \$14,800.00

Remove and Replace Concrete Curb and HMA Pavement necessary to complete work

Remove block Structure; Assume concrete floor is in good shape and leave in place
Install new poured in place structure and replace existing Lid
Provide Traffic Control
Complete all restoration

SE Corner of Jonecy Drive and Dorothy Lane: Lump Sum: \$12,600.00

Remove and Replace Concrete Curb and HMA Pavement necessary to complete work

Remove block areas of the Structure
Install new poured in place structure wall and replace existing Lid
Provide Traffic Control
Complete all restoration

If elected to complete both locations at the same time a credit of \$2,500.00 can be offered. Total for Both Locations: Lump Sum \$24,900.00

BRANDON BOGGS | Project Designer
Fehr Graham | Engineering & Environmental