

4781 Sandy Hollow Road · Rockford, Illinois 61109 Phone: (815) 874-4422 · www.northernillinoisservice.com

October 30, 2025 **Proposal**No. P25245

Village of Roscoe 10631 Main Street Roscoe, Illinois 61073

Re: Storm Sewer Inlet Repairs – Sheringham Dr. / Joncey Dr. & Dorothy Ln.

We propose the following:

- 1. Provide barricades, traffic control, and protection as required.
- 2. Saw cut as required and remove existing pavement, curb, and failed inlet structures and dispose of off site.
- 3. Reconstruct existing inlets with new precast concrete/masonry materials and provide new precast concrete bullnose tops.
- 4. Patch concrete curb and gutter as required to match existing curb section.
- 5. Patch bituminous pavement as required to match existing roadway pavement section.
- 6. Restore disturbed parkway areas with topsoil, seed, and straw blanket.

Location 1 – Sheringham Dr., S. of Turnbridge Ct. (4' x 4' inlet): \$13,750.00

Location 2 – SEC of Joncey Dr. & Dorothy Lane (4' x 4' inlet): \$14,250.00

Notes / Exclusions:

- Each location is priced as a stand-alone project. If both locations are awarded to NISC for completion at the same time, the price for each location can be reduced by \$750.00. (total deduct of \$1,500.00)
- Inspection, cleaning, and or removal and replacement of existing storm sewer pipes are excluded. If pipe removal and replacement is required, it will be completed on a time & materials basis.
- Watering and maintenance of seeded areas is excluded.

Thank you for the opportunity to provide a proposal for this project. Please contact our office if you have any questions or require additional information.

Sincerely,

Paul Munson

Northern Illinois Service Co.

e-mail: paul@northernillinoisservice.com

Office: (815) 874-4422 Mobile: (815) 378-7880