

Request for Traffic Control Device

Community Development Department
275 West Main Street, Santaquin, Utah
(801) 754-1011
www.santaquin.org



Note: This application, in addition to all required information and exhibits, must be turned into the Community Development Department 14 days prior to a regularly scheduled Development Review Committee meeting for it to be on an agenda. All submitted proposals will be reviewed in accordance with Santaquin City Code 6.20.

Meetings: Development Review Committee meetings are held the 2nd and 4th Tuesdays of each month. The meeting is held in the City Offices, located at 275 West Main. Depending on the date of application, the Community Development Department will inform you of the day and time in which your request will be considered by the Development Review Committee.

Applicant Information				
Applicant Name: Karen Evans				
Telephone:	Alternate Telephone:	Email:		
Requested Traffic Control Device Information				
Address of Proposed Traffic Control Device: 300 E 400 S				
Type of Traffic Control Device Requested: Stop sign.				
Description and Justification for the Request				
<table border="1"><tr><td>Contact Information Name Karen Evans Signs: Missing Traffic Sign Address of Sign Problem: 300 E 400 S</td></tr><tr><td>I have a concern regarding the lack of a stop sign at 300 E 400 S. There has never been one there, but there is thru traffic going both directions. Until the past year, 300 East was a cul de sac and I've only seen cars drive through without stopping a few times, but since it is now a thru street with the new development, it is very concerning that there is no stop sign now for the construction vehicles using the street or for the residents that will soon be moving there. It feels very unsafe.</td></tr></table>			Contact Information Name Karen Evans Signs: Missing Traffic Sign Address of Sign Problem: 300 E 400 S	I have a concern regarding the lack of a stop sign at 300 E 400 S. There has never been one there, but there is thru traffic going both directions. Until the past year, 300 East was a cul de sac and I've only seen cars drive through without stopping a few times, but since it is now a thru street with the new development, it is very concerning that there is no stop sign now for the construction vehicles using the street or for the residents that will soon be moving there. It feels very unsafe.
Contact Information Name Karen Evans Signs: Missing Traffic Sign Address of Sign Problem: 300 E 400 S				
I have a concern regarding the lack of a stop sign at 300 E 400 S. There has never been one there, but there is thru traffic going both directions. Until the past year, 300 East was a cul de sac and I've only seen cars drive through without stopping a few times, but since it is now a thru street with the new development, it is very concerning that there is no stop sign now for the construction vehicles using the street or for the residents that will soon be moving there. It feels very unsafe.				
Applicable Exhibits				
Please attach any drawing, map, or other information that can illustrate your request. None Provided				