

March-23 PUBLIC WORKS MONTHLY REPORT

DEPARTMENT	HOURS	YEARS TOTAL		
	HOUNG	ILANG TOTAL		46.0 Hrs. of Street Repairs, 10.0 Hrs. of Alley Repairs, 0.0 Hrs. of Street Sweeping
				187.0 Hrs. of Repair of Street Equipment, 499.0 Hrs. of Shop Clean-up and Shop
TREET	760	2186.5		Equipment, 18,0 Hrs. of Street Markers & Signs Repairs or Replacement, 363,0 Hrs. of
,,,,,,,,,,				snow removal,
TOTAL OLD TOTAL	320			
STREET SWEEPING	0	7		0.0 Hrs, of Street Sweeping was complete for the Month of March.
				0 Business Miles, 0.0 Residenial Miles, 0 Total Miles, \$0.00 Total Fuel Cost,
				\$0.0 Cost per Mile, 0 Tons of Debris Picked Up.
ICE & SNOW	363	668		363.0 Hrs. of Snow Removal completed for the month of March.
				Time spent removing snow piles, ice in curb/gutters and repairs and maintenance of removal equipment
				Tomoral adaptment
THE STATE OF THE S	00.5	044		All and one violation
PARKS	83.5	311		All park are winterized, 0.0 Hrs, of mowing, 0.0 Hrs, of watering, 62,0 Hrs, of landscaping, 17,0 Hrs, of Park
				equipment maintenance with 1.5 Hrs. of Park Clean-Up, and 4.5 Hrs. of Replacement
				and Repairs of Playground Equipment
GARBAGE	875_5	2284		338.30 Tons of Garbage picked up, 3,420 miles driven, 1,219.90 gallons of
				fuel used, 61 total loads. 726.0 Hrs. of Garbage Hauling, 36.0 Hrs. of Alley Clean-Up
				113.5 Hrs. of Sanitation Equipment Maintenance
				Year to date total tons hauled = 977,41 - Average Dailey Tons = 10,91
VATER	531.5	1266		Total Fuel \$4,500.50 2.0 Hours of meter reading, 0.0 Hours of meter repairs, 37.0 Hours of
W) EIX	001.0	1200		water equipment maintenance, 233.5 Hours of maintenance of hydrants,
				valves and mains, 1.0 Hours of office and records, and 202 0 Hours of
				treatment plant operation and testing, 58.0 hours spent on the lead service line study
SEWER	365	903.5		30.5 hours of sewer main cleaning & TV inspection, 141.0 hours of
				maintenance of Sewer mains, manholes & equipment, 75.5 Hrs. of Maintenance of Lift Stations, 47.5 Hrs. of Maintenance of Storm Sewers, 22.0
				Hrs. of Office & Records, 193.5 of Treatment Plant Operation & Maintenance,
				2 Sewer Call for March- Service line issues
SENERAL CITY	9.5	80.5		247.0 Hours of Vacation Time
Service Off				59.0 Hours of Sick Leave
				55.5 Hours of Overtime,
				3,893.5 Total Working hours
				and the state of t
SHOP, MECHANICAL	187	723 8	STREET	544-P-2 - Repair Fender latch, Changed cutting edge on bucket
SHOP, MECHANICAL	187	723 8	STREET	Unit 117-2 - Replace wheel seals on RR & LR wheels, Replace rear differential vent tube.
SHOP, MECHANICAL	187	723 8	STREET	Unit 117-2 - Replace wheel seals on RR & LR wheels, Replace rear differential vent tube, Unit 095 - IHC Tandom - Replace RR Tail light, Tire repair
SHOP, MECHANICAL	187	723 \$	STREET	Unit 117-2 - Replace wheel seals on RR & LR wheels, Replace rear differential vent tube, Unit 095 - IHC Tandom - Replace RR Tail light, Tire repair 544-P-1 - Regular Service, Repair hydraulic coupler
SHOP, MECHANICAL	187			Unit 117-2 - Replace wheel seals on RR & LR wheels, Replace rear differential vent tube, Unit 095 - IHC Tandom - Replace RR Tail light, Tire repair 544-P-1 - Regular Service, Repair hydraulic coupler 772GP - Regular Service and check-up
SHOP, MECHANICAL	187		STREET	Unit 117-2 - Replace wheel seals on RR & LR wheels, Replace rear differential vent tube, Unit 095 - IHC Tandom - Replace RR Tail light, Tire repair 544-P-1 - Regular Service, Repair hydraulic coupler
HOP, MECHANICAL	187			Unit 117-2 - Replace wheel seals on RR & LR wheels, Replace rear differential vent tube, Unit 095 - IHC Tandom - Replace RR Tail light, Tire repair 544-P-1 - Regular Service, Repair hydraulic coupler 772GP - Regular Service and check-up Unit P-1 - Check-up and clean-up
SHOP, MECHANICAL	187			Unit 117-2 - Replace wheel seals on RR & LR wheels, Replace rear differential vent tube, Unit 095 - IHC Tandom - Replace RR Tail light, Tire repair 544-P-1 - Regular Service, Repair hydraulic coupler 772GP - Regular Service and check-up Unit P-1 - Check-up and clean-up
SHOP, MECHANICAL	187			Unit 117-2 - Replace wheel seals on RR & LR wheels, Replace rear differential vent tube, Unit 095 - IHC Tandom - Replace RR Tail light, Tire repair 544-P-1 - Regular Service, Repair hydraulic coupler 772GP - Regular Service and check-up Unit P-1 - Check-up and clean-up
HOP, MECHANICAL	187		SWEEPING	Unit 117-2 - Replace wheel seals on RR & LR wheels, Replace rear differential vent tube, Unit 095 - IHC Tandom - Replace RR Tail light, Tire repair 544-P-1 - Regular Service, Repair hydraulic coupler 772GP - Regular Service and check-up Unit P-1 - Check-up and clean-up Unit P-2 - Check-up and clean-up
HOP, MECHANICAL	187		SWEEPING	Unit 117-2 - Replace wheel seals on RR & LR wheels, Replace rear differential vent tube, Unit 095 - IHC Tandom - Replace RR Tail light, Tire repair 544-P-1 - Regular Service, Repair hydraulic coupler 772GP - Regular Service and check-up Unit P-1 - Check-up and clean-up Unit P-2 - Check-up and clean-up
SHOP, MECHANICAL	187		SWEEPING	Unit 117-2 - Replace wheel seals on RR & LR wheels, Replace rear differential vent tube, Unit 095 - IHC Tandom - Replace RR Tail light, Tire repair 544-P-1 - Regular Service, Repair hydraulic coupler 772GP - Regular Service and check-up Unit P-1 - Check-up and clean-up Unit P-2 - Check-up and clean-up
SHOP, MECHANICAL	187		SWEEPING	Unit 117-2 - Replace wheel seals on RR & LR wheels, Replace rear differential vent tube, Unit 095 - IHC Tandom - Replace RR Tail light, Tire repair 544-P-1 - Regular Service, Repair hydraulic coupler 772GP - Regular Service and check-up Unit P-1 - Check-up and clean-up Unit P-2 - Check-up and clean-up AMI Directional Blade - Replace cutting edges GH-6 - Service and repair deck hydraulic
SHOP, MECHANICAL	187		SWEEPING ICE&SNOW	Unit 117-2 - Replace wheel seals on RR & LR wheels, Replace rear differential vent tube, Unit 095 - IHC Tandom - Replace RR Tail light, Tire repair 544-P-1 - Regular Service, Repair hydraulic coupler 772GP - Regular Service and check-up Unit P-1 - Check-up and clean-up Unit P-2 - Check-up and clean-up AMI Directional Blade - Replace cutting edges
SHOP, MECHANICAL	187		SWEEPING ICE&SNOW	Unit 117-2 - Replace wheel seals on RR & LR wheels, Replace rear differential vent tube, Unit 095 - IHC Tandom - Replace RR Tail light, Tire repair 544-P-1 - Regular Service, Repair hydraulic coupler 772GP - Regular Service and check-up Unit P-1 - Check-up and clean-up Unit P-2 - Check-up and clean-up AMI Directional Blade - Replace cutting edges GH-6 - Service and repair deck hydraulic
SHOP, MECHANICAL	187		SWEEPING ICE&SNOW	Unit 117-2 - Replace wheel seals on RR & LR wheels, Replace rear differential vent tube, Unit 095 - IHC Tandom - Replace RR Tail light, Tire repair 544-P-1 - Regular Service, Repair hydraulic coupler 772GP - Regular Service and check-up Unit P-1 - Check-up and clean-up Unit P-2 - Check-up and clean-up AMI Directional Blade - Replace cutting edges GH-6 - Service and repair deck hydraulic
HOP, MECHANICAL	187		SWEEPING ICE&SNOW	Unit 117-2 - Replace wheel seals on RR & LR wheels, Replace rear differential vent tube, Unit 095 - IHC Tandom - Replace RR Tail light, Tire repair 544-P-1 - Regular Service, Repair hydraulic coupler 772GP - Regular Service and check-up Unit P-1 - Check-up and clean-up Unit P-2 - Check-up and clean-up AMI Directional Blade - Replace cutting edges GH-6 - Service and repair deck hydraulic
SHOP, MECHANICAL	187		SWEEPING ICE&SNOW PARKS	Unit 117-2 - Replace wheel seals on RR & LR wheels, Replace rear differential vent tube, Unit 095 - IHC Tandom - Replace RR Tail light, Tire repair 544-P-1 - Regular Service, Repair hydraulic coupler 772GP - Regular Service and check-up Unit P-1 - Check-up and clean-up Unit P-2 - Check-up and clean-up AMI Directional Blade - Replace cutting edges GH-6 - Service and repair deck hydraulic GH-7 - Service and miscellaneoud repairs, replace hydrostat housing fan Unit 831: tire repair. Unit 417 - regular service, replace gripper pads, tire repair, Replace slack adjuster
HOP, MECHANICAL	187		SWEEPING ICE&SNOW PARKS	Unit 117-2 - Replace wheel seals on RR & LR wheels, Replace rear differential vent tube, Unit 095 - IHC Tandom - Replace RR Tail light, Tire repair 544-P-1 - Regular Service, Repair hydraulic coupler 772GP - Regular Service and check-up Unit P-1 - Check-up and clean-up Unit P-2 - Check-up and clean-up Unit P-2 - Check-up and clean-up AMI Directional Blade - Replace cutting edges GH-6 - Service and repair deck hydraulic GH-7 - Service and miscellaneoud repairs, replace hydrostat housing fan Unit 831: tire repair. Unit 417 - regular service, replace gripper pads, tire repair, Replace slack adjuster Unit 421 - Replace air dryer cartridge
SHOP, MECHANICAL	187		SWEEPING ICE&SNOW PARKS	Unit 117-2 - Replace wheel seals on RR & LR wheels, Replace rear differential vent tube, Unit 095 - IHC Tandom - Replace RR Tail light, Tire repair 544-P-1 - Regular Service, Repair hydraulic coupler 772GP - Regular Service and check-up Unit P-1 - Check-up and clean-up Unit P-2 - Check-up and clean-up Unit P-2 - Check-up and clean-up AMI Directional Blade - Replace cutting edges GH-6 - Service and repair deck hydraulic GH-7 - Service and miscellaneoud repairs, replace hydrostat housing fan Unit 831: tire repair. Unit 417 - regular service, replace gripper pads, tire repair, Replace slack adjuster Unit 421 - Replace air dryer cartridge Unit 422 - Replace hydraulic hose
SHOP, MECHANICAL	187		SWEEPING ICE&SNOW PARKS SOLID WASTE	Unit 117-2 - Replace wheel seals on RR & LR wheels, Replace rear differential vent tube. Unit 095 - IHC Tandom - Replace RR Tail light, Tire repair 544-P-1 - Regular Service, Repair hydraulic coupler 772GP - Regular Service and check-up Unit P-1 - Check-up and clean-up Unit P-2 - Check-up and clean-up Unit P-2 - Check-up and clean-up AMI Directional Blade - Replace cutting edges GH-6 - Service and repair deck hydraulic GH-7 - Service and miscellaneoud repairs, replace hydrostat housing fan Unit 631: tire repair. Unit 417 - regular service, replace gripper pads, tire repair, Replace slack adjuster Unit 421 - Replace air dryer cartridge Unit 422 - Replace hydraulic hose Unit 635 - replace crankcase breather assembly, repair LH cab step.
SHOP, MECHANICAL	187		SWEEPING ICE&SNOW PARKS	Unit 117-2 - Replace wheel seals on RR & LR wheels, Replace rear differential vent tube. Unit 095 - IHC Tandom - Replace RR Tail light, Tire repair 544-P-1 - Regular Service, Repair hydraulic coupler 772GP - Regular Service and check-up Unit P-1 - Check-up and clean-up Unit P-2 - Check-up and clean-up Unit P-2 - Check-up and clean-up AMI Directional Blade - Replace cutting edges GH-6 - Service and repair deck hydraulic GH-7 - Service and miscellaneoud repairs, replace hydrostat housing fan Unit 831: tire repair. Unit 417 - regular service, replace gripper pads, tire repair, Replace slack adjuster Unit 421 - Replace air dryer cartridge Unit 422 - Replace hydraulic hose Unit 835 - replace crankcase breather assembly, repair LH cab step. Unit #217 - Regular Service, Replaced RL Wheel Seal and differential vent tube
SHOP, MECHANICAL	187		SWEEPING ICE&SNOW PARKS SOLID WASTE	Unit 117-2 - Replace wheel seals on RR & LR wheels, Replace rear differential vent tube. Unit 095 - IHC Tandom - Replace RR Tail light, Tire repair 544-P-1 - Regular Service, Repair hydraulic coupler 772GP - Regular Service and check-up Unit P-1 - Check-up and clean-up Unit P-2 - Check-up and clean-up Unit P-2 - Check-up and clean-up AMI Directional Blade - Replace cutting edges GH-6 - Service and repair deck hydraulic GH-7 - Service and miscellaneoud repairs, replace hydrostat housing fan Unit 631: tire repair. Unit 417 - regular service, replace gripper pads, tire repair, Replace slack adjuster Unit 421 - Replace air dryer cartridge Unit 422 - Replace hydraulic hose Unit 635 - replace crankcase breather assembly, repair LH cab step.
SHOP, MECHANICAL	187		SWEEPING ICE&SNOW PARKS SOLID WASTE	Unit 117-2 - Replace wheel seals on RR & LR wheels, Replace rear differential vent tube. Unit 095 - IHC Tandom - Replace RR Tail light, Tire repair 544-P-1 - Regular Service, Repair hydraulic coupler 772GP - Regular Service and check-up Unit P-1 - Check-up and clean-up Unit P-2 - Check-up and clean-up Unit P-2 - Check-up and clean-up AMI Directional Blade - Replace cutting edges GH-6 - Service and repair deck hydraulic GH-7 - Service and miscellaneoud repairs, replace hydrostat housing fan Unit 831: tire repair. Unit 417 - regular service, replace gripper pads, tire repair, Replace slack adjuster Unit 421 - Replace air dryer cartridge Unit 422 - Replace hydraulic hose Unit 835 - replace crankcase breather assembly, repair LH cab step. Unit #217 - Regular Service, Replaced RL Wheel Seal and differential vent tube
SHOP, MECHANICAL	187		SWEEPING ICE&SNOW PARKS SOLID WASTE	Unit 117-2 - Replace wheel seals on RR & LR wheels, Replace rear differential vent tube, Unit 095 - IHC Tandom - Replace RR Tail light, Tire repair 544-P-1 - Regular Service, Repair hydraulic coupler 772GP - Regular Service and check-up Unit P-1 - Check-up and clean-up Unit P-2 - Check-up and clean-up Unit P-2 - Check-up and clean-up AMI Directional Blade - Replace cutting edges GH-6 - Service and repair deck hydraulic GH-7 - Service and miscellaneoud repairs, replace hydrostat housing fan Unit 831: tire repair. Unit 417 - regular service, replace gripper pads, tire repair, Replace slack adjuster Unit 421 - Replace air dryer cartridge Unit 422 - Replace hydraulic hose Unit 835 - replace crankcase breather assembly, repair LH cab step. Unit #217 - Regular Service, Replaced RL Wheel Seal and differential vent tube Unit 013 - Jeep - Regular Service, Replaced TPMS on RR tire.
SHOP, MECHANICAL	187		SWEEPING ICE&SNOW PARKS SOLID WASTE	Unit 117-2 - Replace wheel seals on RR & LR wheels, Replace rear differential vent tube. Unit 095 - IHC Tandom - Replace RR Tail light, Tire repair 544-P-1 - Regular Service, Repair hydraulic coupler 772GP - Regular Service and check-up Unit P-1 - Check-up and clean-up Unit P-2 - Check-up and clean-up Unit P-2 - Check-up and clean-up AMI Directional Blade - Replace cutting edges GH-6 - Service and repair deck hydraulic GH-7 - Service and miscellaneoud repairs, replace hydrostat housing fan Unit 831: tire repair. Unit 417 - regular service, replace gripper pads, tire repair, Replace slack adjuster Unit 421 - Replace air dryer cartridge Unit 422 - Replace hydraulic hose Unit 835 - replace crankcase breather assembly, repair LH cab step. Unit #217 - Regular Service, Replaced RL Wheel Seal and differential vent tube Unit 013 - Jeep - Regular Service, Replace air line pressure switch. Rebuild water pressure pump.
SHOP, MECHANICAL	187		SWEEPING ICE&SNOW PARKS SOLID WASTE	Unit 117-2 - Replace wheel seals on RR & LR wheels, Replace rear differential vent tube, Unit 095 - IHC Tandom - Replace RR Tail light, Tire repair 544-P-1 - Regular Service, Repair hydraulic coupler 772GP - Regular Service and check-up Unit P-1 - Check-up and clean-up Unit P-2 - Check-up and clean-up Unit P-2 - Check-up and clean-up AMI Directional Blade - Replace cutting edges GH-6 - Service and repair deck hydraulic GH-7 - Service and miscellaneoud repairs, replace hydrostat housing fan Unit 831: tire repair. Unit 417 - regular service, replace gripper pads, tire repair, Replace slack adjuster Unit 421 - Replace air dryer cartridge Unit 422 - Replace hydraulic hose Unit 835 - replace crankcase breather assembly, repair LH cab step. Unit #217 - Regular Service, Replaced RL Wheel Seal and differential vent tube Unit 013 - Jeep - Regular Service, Replaced TPMS on RR tire.