



HAYDEN PAVING, INC.

4710 Windsong Trail, Houston, TX 77084 O: 281-855-7710 F: 281-856-2506

Quotation

Quote Number: 34518
Quote Date: 5/10/2024
Quoted By: ihaun Wilkerson

Quoted to:
 City of Tomball
 501 James St.
 Tomball TX 77375

Job Name: City of Tomball - Asphalt & Concrete Repairs
 Tomball TX 77375
Phone: (281)290-1426

Contact	Good Through	Payment Terms	Job Location
Justin Pruitt	6/9/2024	Net 30 Days	Tomball
Item	Description	Amount	
Supply material, labor and equipment to perform the following:			
1	ASPHALT & BASE REPAIRS: Mill 2" of the existing deteriorated asphalt pavement and 8" of existing base material. Place and compact 8" of Asphalt base material. Apply Tack coat @ 0.05 to 0.15 gal./sq.yd., place and compact 2" of type 'D' HMAC. Area totaling approximately 450/sq.ft.	\$27,416.00	
2	CONCRETE REPAIRS: Saw cut edges to be repaired. Excavate Approximately 8" of the existing deteriorated concrete pavement and haul off-site. Reinforce with #4 Rebar on 12" centers and dowel into existing concrete, place and apply medium broom finish to 8" of 3000 PSI concrete. Area totaling approximately 350 sq.ft.	\$13,581.00	
***	Buy Board Number: 700-23		
		Base	\$40,997
		Bond Cost	\$0
		Subtotal	\$40,997
Exempt - contingent upon receipt of Tax Certificate		8.25%	\$0
		Total	\$40,997

Notes	
1	This quote does not include the cost of permits, which may or may not be required, or the plan work necessary to obtain such permits.
2	Price is subject to change due to any freight increases, liquid asphalt increases, and fuel surcharges incurred.
3	Hayden Paving shall not warranty asphalt failures caused by sub-grade or base failures where asphalt is placed on existing sub-grade, base or asphalt surface which was not installed by Hayden Paving.
4	Asphalt paving industry recommended grade for proper drainage of asphalt surfaces is 2%. Designed grades of less than 1.5% will increase the chances of water ponding. Hayden Paving shall not guarantee zero ponding on surfaces designed with less than 1.5% grade.
5	Engineering layout, offset stakes and string line elevation control costs are not included in this quotation. This quote is based upon the assumption that elevations shall be controlled by existing curbs, gutters, base material, etc.



HAYDEN PAVING, INC.

4710 Windsong Trail, Houston, TX 77084 O: 281-855-7710 F: 281-856-2506

"20 Years Experience"

Acceptance of proposal - The above prices, specifications and conditions are satisfactory and are hereby accepted. Hayden Paving, Inc is authorized to do the work as specified. Payment will be made as described by payment terms listed above. Hayden Paving, Inc. reserves the right to repossess any material that is not paid in full within 90 days of the job completion.

Signature _____

Date _____

Print Name _____