

| ASSET NO. | DESCRIPTION | BARCODE | SERIAL NUMBER | UNIT NUMBER | DEPT | DATE ACQUIRED | ACQ COST | REASON FOR SURPLUS |
|-----------|-----------------------------------|--------------|-------------------|----------------------|------|---------------|--------------|--|
| 3248 | DITCHER, JOHN DEERE ALAMO | 11072 | DTMV-00016 | VEH 115 COMPONENT | 061 | 04/16/10 | \$ 13,962.49 | NO LONGER HAVE THE EQUIPMENT THIS ATTACHES TO |
| 2184 | DUMP BED, 8 1/2 X 96" FLAT (PW91) | 12717 | | VEH 091 | 061 | 04/26/07 | \$ 6,445.55 | BED TO ASSET 2182 |
| 2182 | PICK UP, 08 FORD F350 DRW | 12756 | 1FTWW32YX8EA08084 | VEH 091 | 061 | 03/15/07 | \$ 21,284.50 | BAD VALVES, COSTLY REPAIR AND HARD TO FIND PARTS |
| G05017 | 99 IHC TRUCK | 10624 | 1HTSCAANXYH244108 | VEH 030 | 061 | 04/19/99 | \$ 31,676.62 | NO OIL PRESSURE, BAD MOTOR, COSTLY REPAIR |
| G05137 | 10' X 7' 3" DUMP BODY | 10733 | | VEH 030 | 061 | 05/31/99 | \$ 4,682.00 | BED TO ASSET G05017 |
| 1540 | DOZER, D31-PX21 KOMATSU TRACK | 11671 | 50834 | VEH 065 | 061 | 03/05/06 | \$ 72,650.00 | FINAL DRIVE IS BAD, BROKEN UNDERCARRIAGE, WORN OUT, |
| 2161 | FABRICATED CAB ENCLOSURE-KOMATSU | 12732 | COMPONENT | VEH 065 | 061 | 08/17/07 | \$ 3,000.00 | CAB TO ASSET 1540 |
| G05423 | 2000-AS PAINT MACHINE | 1138 | 1198 | VEH PM2 | 061 | 09/30/99 | \$ 24,451.00 | WORN OUT, CANNOT FIND PARTS TO REPAIR |
| 2209 | CHAIN SAW, MS 260 18' B/C | 12752 | 271100749 | VEH CS8 | 061 | 09/28/07 | \$ 400.00 | MOTOR LOCKED UP |
| G04067 | QUINCY MOD 350 COMPRESSOR | 13438 | 6092747 | PM LOCK UP | 061 | 05/16/97 | \$ 2,300.00 | WORN OUT AND NOT LONGER IN USE |

| | | | | |
|------|--------------------|-------|----------|---------|
| 2153 | RADIO, KENWOOD VHF | 12642 | 80800239 | VEH 091 |
|------|--------------------|-------|----------|---------|

| | | | | |
|------|----------------|-------|----------|---------|
| 4019 | RADIO, TK-7360 | 15285 | B1C01319 | VEH 030 |
|------|----------------|-------|----------|---------|

| | | | | | |
|-----|----------|-----------|--|-----|--|
| 061 | 02/15/07 | \$ 370.00 | | ROW | |
|-----|----------|-----------|--|-----|--|

| | | | | | |
|-----|----------|-----------|--|---------|--|
| 061 | 02/03/12 | \$ 310.50 | | STREETS | |
|-----|----------|-----------|--|---------|--|

1996

| | | | | | | | |
|--------|------|-------|-------------|-------|----------|--------|-------|
| 61-117 | 1996 | RHINO | CY72 BUSH H | 21124 | BUSH HOG | G02569 | 10695 |
|--------|------|-------|-------------|-------|----------|--------|-------|

| | | | | | | | |
|--------|------|-----------|-------|-----------|------------|-----------|-----|
| 61-WE1 | 2022 | STIHL | FS91R | 534746144 | WEED EATER | TW960436 | ROW |
| 61-WE7 | 2016 | HUSQVARNA | 525L | 4400011 | WEED EATER | TW 960326 | ROW |

| | | | | | | | |
|--------|------|--------|------------|-----------|------|-------|----------|
| 61-M07 | 2016 | EXMARK | LXS691KA52 | 314638259 | 4682 | 16061 | TW 16061 |
|--------|------|--------|------------|-----------|------|-------|----------|

| | | |
|----------|-----------|-----|
| COT 1436 | TW 956517 | ROW |
|----------|-----------|-----|

| | | |
|----------------|----------------------|--------------------------|
| BOYD YARBROUGH | DOWNTOWN ASSOCIATION | NOT PURCHASED THROUGH PW |
|----------------|----------------------|--------------------------|