

UNPLANNED EXPENSES IMPACTING 2025 BUDGET

	VENDOR	EXPENSE	AMOUNT	BILLED TO
APR	Martin Systems	Replace defective sensor in ducts	453.66	Building Repairs
MAY	United Systems Associates	Replacement of controllers (Nov 24)	547.35	Building Repairs
	Sure-Fire Inc.	Replace shaft seal and pump gasket	2,365.10	Building Repairs
YTD TOTAL:			3,366.11	