

Bayou Bend Estates
Angleton, TX.

MANHOLE VACUUM TEST

P = Pass F = Fail

M H No.	LOCATION	DATE	RESULTS	START TIME	START VACUUM	STOP TIME	STOP VACUUM
MH1		12/23/21	P	8:38	10" Hg	8:38+20	10" Hg
MH2		12/21/21	P	8:37	10" Hg	8:39	9.7" Hg
MH3		12/21/21	P	10:20	10" Hg	10:21	9.6" Hg
MH4		12/21/21	P	9:33	10" Hg	9:33+20	10" Hg
MH5		12/21/21	P	9:20	10" Hg	9:20+20sec	10" Hg
MH6		12/21/21	P	9:10	10" Hg	9:10+20sec	10" Hg
MH7		12/21/21	P	8:52	10" Hg	8:52+20sec	10" Hg
MH8		12/21/21	P	9:56	10" Hg	9:56+20sec	10" Hg

BAKER & LAWSON, INC.

INSPECTOR

David Carden

JOB No.

13454

Bayou Bend Estates
Angleton, TX

Date: 12/21/21
Job #: 13454

SANITARY SEWER LOW PRESSURE TEST

LOCATION	TIME MEASURED	START TIME	INITIAL PRESSURE	STOP TIME	FINAL PRESSURE	P/F	COMMENTS
MH1 - MH2	3 mins	14:15	3.5 psi 4 psi	14:18	3.8	P	LF=172 ϕ 8"
MH2 - MH3	3 mins	14:28	4 psi	14:31	3.7	P	LF=82 ϕ 8"
MH3 - MH4	3 min	13:51	4 psi	13:54	3.7	P	LF=158 ϕ 8"
MH4 - MH5	3 mins	13:42	4 psi	13:45	3.9 psi	P	LF=176 ϕ 8"
MH5 - MH6	3 mins	11:23	4 psi	11:26	3.8 psi	P	LF=238 ϕ 8"
MH6 - MH7			3.5 psi 4 psi				LF=308 ϕ 8"
MH4 - MH8	3 mins	13:57	4 psi	14:00	4 psi	P	LF=346 ϕ 8"
12/22/21							
MH6 - MH7	3 mins	8:14	4 psi	8:17	3.9	P	LF=308 ϕ 8"