LETTER OF RECOMMENDATION

FOR

City of Angleton

Chenango GST Replacement



CITY OF ANGLETON

JUNE 2022

HDR Project No. 10325096



HDR ENGINEERING, INC. 4828 LOOP CENTRAL DRIVE, SUITE 800 HOUSTON, TEXAS 77081 (713) 622-9264 June 2, 2022

Mayor and City Council Members City of Angleton 121 S. Velasco Angleton, Texas 77515

Re: Letter of Recommendation for Chenango GST Replacement City of Angleton, Texas HDR Job No. 10325096

Dear Mayor and City Council Members:

On May 25, 2022, the City received two (2) bids for the above referenced project. HDR evaluated the bids and our findings are summarized below.

<u>Bid Tabulation Sheet</u> – Two (2) construction firms participated in the bidding process. Each bid was checked for mathematical errors and/or bid irregularities. The project was bid with Base Bid Items, Supplemental Items, Alternate Items, Cash Allowance and Contingency Allowance Items. The bid tabulation is attached in Section 1 of this report. The bids for the project are as follows:

CONTRACTOR	TOTAL (BASE BID ITEMS, SUPPLEMENTAL ITEMS, ALTERNATE ITEMS, CASH ALLOWANCE ITEMS AND CONTINGENCY ALLOWANCE)
DN Tanks, LLC (Apparent Low Bidder)	\$2,418,753.00
Preload, LLC	\$2,513,091.00

Evaluation of Apparent Low Bidder – The apparent low bidder is DN Tanks, LLC.

Evaluation of References – DN Tanks, LLC provided a list of five (5) references. HDR contacted all of these references, and asked them to respond to a questionnaire as part of the evaluation process of the apparent low bidder. DN Tanks, LLC received overall good ratings on their previous projects of similar size and nature. The references indicated that they were satisfied with the work that DN Tanks, LLC. had performed and would use them again in the future. Copies of the questionnaires are attached in Section 2 of this report.

DN Tanks, LLC. appears to be a responsible firm that should be capable of performing the specified work in a satisfactory manner. For these reasons listed above, HDR recommends that the City of Angleton award the Chenango GST Replacement project to DN Tanks, LLC for a total bid amount of Two Million, Four Hundred Eighteen Thousand, Seven Hundred Fifty-Three dollars and Zero cents, (\$2,418,753.00).

hdrinc.com

If you have any questions, please feel free to contact us.

Sincerely,

aletta

Valetta Saldanha, P.E. Project Manager HDR Engineering, Inc.



BID TABULATION CHENANGO GST REPLACEMENT

City	of	Anal	eton

				LC	WEST RESP	ONS	SIVE BIDDER					
					DN Tar			Preload, LLC				
TEM	ITEM DESCRIPTION	UNIT	QUANTITY	UN		-	TAL AMOUNT	U				
NO.) BA:	SE BID ITEMS	-		_								
1	Mobilization and demobilization, complete in place, the sum of: Stormwater pollution prevention and erosion control, including installation,	LS	1	\$	96,900.00	\$	96,900.00	\$	121,000.00	\$	121,000.00	
2	removal and maintenance, and all associated incidentals, complete in place, the sum of:	LS	1	\$	16,500.00	\$	16,500.00	\$	8,000.00	\$	8,000.00	
3	Site work including clear and grub inside the site, removal and proper disposal of excess dit, all terms included in the site grading and chanage plan including but not limited to the site grading, drainage swale, and 12* HDPE culvert, sodding all disturbed areas, site restoration, and related work, and all associated incidentials, complete in place, the sum of:	LS	1	s	93,100.00	\$	93,100.00	\$	50,000.00	\$	50,000.00	
4	Remove tree 12" to 29.99" in diameter and properly dispose, complete in place, the sum of:	EA	3	\$	2,070.00	\$	6,210.00	\$	500.00	\$	1,500.00	
5	Clearance prune tree and properly dispose, complete in place, the sum of:	EA	1	\$	490.00	\$	490.00	\$	1,000.00	\$	1,000.00	
6	Crown cleaning prune and properly dispose, complete in place, the sum of:	EA	2	\$	490.00	\$	980.00	\$	700.00	\$	1,400.00	
7	Install tree protection fence, complete in place, the sum of:	LF	210	\$	8.30	\$	1,743.00	\$	10.00	\$	2,100.00	
8	Install root pruning trench, complete in place, the sum of:	LF	90	\$	21.00	\$	1,890.00	\$	10.00	\$	900.00	
9	Plant 2-inch, 30-gallon container, Eagleston Holly trees as shown on Drawings, complete in place, the sum of: Plant 2-5 callon container. Dwarf Vauron Holly should space and	EA	3	\$	1,210.00	\$	3,630.00	\$	810.00	\$	2,430.00	
10	Plant 2.5-gallon container, Dwarf Yaupon Holly shrubs, spacing and planting per Supplier's recommendations as shown on Drawings, complete in place, the sum of:	LF	50	\$	67.00	\$	3,350.00	\$	20.00	\$	1,000.00	
11	Construct (1) new 1.0 MG (milion gallons) type III prestressed concrete ground storage tank (GST); foundation, understab priping, linkt riser, subgrade preparation, concrete splash pad, and all related appurtenances including painting of GST and logo on GST; install yard piping including water lines and choiren injection line, choiren injection nozzle, potholing of lines, tapping sleeve and valve, valves, fittings and appurtenances, make all connections and lice ins as shown on plans, and all associated incidentals; complete in place, the sum of:	LS	1	\$	1,974,000.00	\$	1,974,000.00	s	2,084,170.00	s	2,084,170.00	
12	Denotition and proper disposal of items called for in Site Denotition Plan including but not limited to (1) existing 1.0 MG GST and (1) water well concrete block; cut, plug and abandon existing 12° (fabesto-cement) water transfer line, plug and remove existing 12° GST drain line; install bill flange and remove existing 10° suction line as shown on plans, complete in place, the sum of:	LS	1	s	52,700.00	\$	52,700.00	\$	71,800.00	\$	71,800.00	
13	Al electrical work, including installation of (1) new flood light and weather- proof light switch for new GST, reinforced concrete encased duct bank, conduit, wing, nervos (1) existing 120/240V (16 space) panel board and replace with (1) new 120/240V (36 space) panel board and circuit breakers, and al related apurtenances for proposed electrical work (excluding grounding ring and bonding conductor, and related appurtenances as shown in separate bid lem), complete in place, the sum of:	LS	1	s	62,300.00	\$	62,300.00	\$	74,500.00	\$	74,500.00	
14	Grounding ring and bonding conductor, and all related appurtenances, complete in place, the sum of:	LS	1	\$	13,900.00	\$	13,900.00	\$	10,900.00	\$	10,900.00	
15	All instrumentation and controls work, including installation of new instrumentation for GST, control wiring for instrumentations and controls, and all related appurtenances for proposed instrumentation and controls	LS	1	\$	19,400.00	\$	19,400.00	\$	14,800.00	\$	14,800.00	
	work, complete in place, the sum of: SUBTOTAL BASE BID ITEMS:					\$	2,347,093.00			\$	2,445,500.00	
3) SU 16	PPLEMENTAL BID ITEMS Cementitious grout for abandoning existing water well casing, complete in	CY	20	s	170.00	\$	3,400.00	\$	140.00	s	2,800.00	
10	place, the sum of: Extra cement stabilized sand, complete in place, the sum of:	CY	12	ې s	50.00	ې s	600.00	ې ۲	140.00	s s	1,320.00	
18	Extra bank sand, complete in place, the sum of:	CY	12	\$ \$	30.00	ş	360.00	\$ \$	50.00	\$	600.00	
19	Repair/install 6-ft tall chainlink fence with barbed wire, including foundation posts, all hardware, materials and tools, complete in place, the sum of:	LF	50	\$	80.00	\$	4,000.00	\$	40.00	\$	2,000.00	
20	Install site gate, including foundation posts, all hardware, materials and tools, complete in place, the sum of:	EA	1	\$	1,900.00	\$	1,900.00	\$	1,380.00	\$	1,380.00	
C) AL	SUBTOTAL SUPPLEMENTAL BID ITEMS: TERNATE ITEMS					\$	10,260.00			\$	8,100.00	
21	Substitution of an FRP ladder (inclusive of braces) for the internal tank ladder, in lieu of the specified Type 316 stainless steel ladder, with installation, complete in place, the sum of:	EA	1	\$	(5,300.00)	\$	(5,300.00)	s	(800.00)	\$	(800.00	
22	Substitution of Type 304/304L stainless steel for all appurtenances and anchors specified to be Type 316/316L stainless steel, with installation, complete in place, the sum of:	LS	1	\$	(1,300.00)	\$	(1,300.00)	\$	(6,109.00)	\$	(6,109.00	
	SUBTOTAL ALTERNATE ITEMS:					\$	(6,600.00)			\$	(6,909.00	
23	SH ALLOWANCE ITEMS Cash Allowance Item 1: Conduct lead and asbestos material testing of equipment identified for demolishino. Contractor shall pothole a representative location on each run of yard piping that will be demolished or representative location on each run of yard piping that will be demolished or presenter of the Project. Contractor shall there aqualified subestos and lead-based paint testing firm to observie/enfly and test as appropriate representative samples of pipe material, and existing coatings to verify the presence or absence of asbestos-containing materials and lead based paint, as related to the project-required construction and demolition. Payment for the absetos and lead-based paint testing up to the amount specified on the Bid Form shall be made from the Owner's cash allowance. Costs for potholing or dherwise providing access for the testing shall be included as subsidiary in the Contractor's lump sum pricing for other items a defined. In the event absetos and lead-based paint above threshold limits are determined to be present, the Owner will negotate with the Contractor for remediation and disposal requirements and pay for mutually- agreed additional costs out of the Owner's cash allowance.	LS	1	s	4,000.00	\$	4,000.00	\$	4,500.00	\$	4,500.00	
24	Cash Allowance Item 2: PLC and SCADA programming to be performed by BL Technology, Inc. (BLTI). Contact Robert E Lee II at BLTI at Phone No: 832-698-8035 and Email: ble@blit.com	LS	1	\$	14,000.00	\$	14,000.00	\$	11,900.00	\$	11,900.00	
E) CO	SUBTOTAL CASH ALLOWANCE ITEMS: NTINGENCY ALLOWANCE ITEMS		I			\$	18,000.00			\$	16,400.00	
25	Owner's Contingency Allowance	LS	1	\$	50,000.00	\$	50,000.00	\$	50,000.00	\$	50,000.00	
	SUBTOTAL CONTINGENCY ALLOWANCE ITEMS:			-		\$	50,000.00	-		\$	50,000.0	
			BID ITEMS:			\$	2,347,093.00			\$	2,445,500.0	
	SUBTOTAL SUPPLEM					\$	10,260.00			\$	8,100.0	
	SUBTOTAL					\$	(6,600.00) \$18,000.00			\$	(6,909.0	
										s	16 400 00	
	SUBTOTAL CASH A					¢				•		
	SUBI UTAL CASH A SUBTOTAL CONTINGENCY A TOTAL BASE, SUPPLEMENTAL, ALTERNATE, CASH ALLOWANCE	LLOWA	NCE ITEMS:			\$	50,000.00			\$	50,000.0	



BUILT FOR THE FUTURE
TOR THE TOTORE

Project Information:

Project Name: Lyon Street Booster Pump Station North Ground Storage Tank Demolition & Replacement Laredo, TX, USA Ground Storage 1 - 4.00 MG (146:00 FT ID x 32:00 FT SWD) Year Bull: 2022 Total Project Contract: \$8,111,377 Contract Date: 9/21/2020 Scope of Work: Demolition of existing 6.0 MG GST, and construction of new 4.0 MG D110 Type III GST, wall, fencing, and associated sitework, yardpiping, and electrical.

Project Information: Project Name: West Travis Public Utility Agency Southwest Parkway **Ground Storage Tank** Austin, TX, USA Ground Storage 1 - 1.00 MG (65.00 FT ID x 40.00 FT SWD) Year Built: 2020 Total Project Contract: \$1,666,260 Contract Date: 7/27/2020

Scope of Work: Demolition of two existing GST, and construction of (2) 1.0MG D110 Type III GST and associated sitework, yardpiping, fencing, and electrical.

Project Information: Project Name: Pollok Drive Water Plant (Well No. 20) 1 MG Concrete Type III GST Conroe, TX, USA **Ground Storage** 1 - 1.00 MG (74.33 FT ID x 30.00 FT SWD) Year Built: 2020 Total Project Contract: \$1,476,409 Contract Date: 9/26/2019

Scope of Work: Demolition of existing 1.0 MG GST, construction of new 1.0MG D110 Type III GST and associated sitework, yardpiping, fencing, and electrical.

Project Information: Project Name: Brazosport Water Authority, 2018 Plant Improvements, Contract 1 (Clearwell) Lake Jackson, TX, USA Clearwell 1 - 10.00 MG (194.50 FT ID x 45.00 FT SWD) Year Built: 2020 Total Project Contract \$7,402,449 Contract Date: 11/27/2018 Scope of Work: Construction of new 10.0 MG GST, utilities, and sitework,

Project Information: Project Name: Daniels Mountain Storage Tank, No. 201616, Contract No. 2018-505-C Georgetown, TX, USA **Ground Storage** 1 - 4.00 MG (121.67 FT ID x 46.00 FT SWD) Year Built: 2016 Total Project Contract: \$1,725,680 Contract Date: 1/26/2016 Scope of Work: Construction of new 4.0MG D110 Type III GST, and associated sitework,

yardpiping, and electrical.

Japon Calin Sin 2/2022

Principality and cardidately information. Information uriz al Dill Tasim così er

Owner: City of Georgetown 609 Main St Georgetown, TX, USA 78627-0409 Contact: Pousson, Chris **CIP Manager** (512) 930-2571

Email: chris pousson@georgetown org

1101 Capital of Texas Hwy S., Bldg D. Ste 110 Austin, TX, USA 78746 Contact: Muriee, George President (512) 927-9204 Email: ddelavins@murfee.com

Murfee Engineering Company, Inc.

Engineer: **Bleyl Engineering** 100 Nugent Street Conroe, TX, USA 77301 Contact: Green, Jonny **Project Manager** (936) 441-7833 Email: jgreen@blevlengineering.com

Engineer: **CDM Smith** 12357-A Rista Trace Pkwy, Ste 210 Austin, TX, USA 78727 Contact: Woelke, Allen Vice President (512) 346-1100 Email: woelkead@cdmamith.com

Engineer: **CDM Smith** 12357-A Riata Trace Pkwy, Ste 210 Austin, TX, USA 78727 Contact: Woelke, Allen Vice President (512) 346-1100 Email: woelkead@cdmamith.com

Statement of Experience

References, and Statement of Qualifications

Engineer: Ardurra (LNV) Engineering 6010 McPherson, Ste. 110 Laredo, TX LISA 78041 Contact: Valdez, Enrique Civil Engineer (956) 462-5511 Email: evaldez@invinc.com

Engineer:

retaining

West Travis County Public Utility Agency 12117 Bee Cave Road Austin, TX, USA 78738 Contact: c/o George Murgee at Murfee Engineering

Owner:

City of Laredo City Manager

Laredo, TX, USA 78042-0579

Water Plant Superintendent

Email: tmoreno@ci.laredo.tx.us

1110 Houston St (78040)

Contact: Moreno, Tony

(956) 791-7345

Owner:

Owner:

Owner:

1251 FM 2004

General Manager

(979) 297-2715

BM.

City of Conroe

401 Sgl. Ed Holcomb Blvd. S.

Conroe, TX, USA 77305-3066

Email: Nmcguire@cityofconroe.org

Contact: McGuire, Norman

Brazosport Water Authority

Contact: Woodruff, Ronnie

Email: rewoodruff@att.net

Lake Jackson, TX, USA 77566

Public Works Director

(936) 522-3885



Reference Responses

FJS

CONTRACTOR REFERENCE FORM

Date: June 1, 2022

Project: City of Angleton Chenango GST Replacement

Contractor: DN Tanks LLC

Reference Name:Ronald MillerCompany: Ardurra (LNV) EngineeringContact: (956) 326-9847Reference Project:City of Laredo Lyon Street Booster Pump Station North Ground Storage Tank Demolition & Replacement

Dear Mr. Miller (by phone):

DN Tanks, LLC is the apparent low bidder for the above referenced project and has submitted your name as a reference. Reference responses will be included in the evaluation of lowest responsible bid proposals received for this project.

HDR would appreciate your time in rating your experience with this Contractor. Please circle the number corresponding to the response which best indicates your opinion of the Contractor or provide a short answer on the lines as it relates to each item.

	Excellent		ve rage	Averag		Below Averaç		Poor	
Rate the Contractor's performance as a "team player".	10 9	8	76	5	4	3	2	1	No Opinion
How would you rate their ability to coordinate the work with neighboring property owners?	10 9	8	76	5	4	3	2	1	No Opinion
Rate the quality of construction, the Contractor's supervision and project management.	10 (9)	8	76	5	4	3	2	1	No Opinion
Rate the Contractor's ability to achieve completion of the project on time. Supply chain issues, not theirs		8	76	-	4	-	2	1	No Opinion
Were there many change orders on the project? If so, what were the reasons? Were the reasonable?	unforesee	n circum							vanted or le and took
	care of the	m_							
Rate the Contractor's responsiveness to warranty work requests and the quality of the work. <i>Always pretty responsive</i>	, 10 9	$\binom{8}{7}$	76	5	4	3	2	1	No Opinion
Rate the Contractor's ability to expeditiously closeout projects. <i>N/A Project is ongoing – not closed out yet</i>	10 9	8 7	76	5	4	3	2	1	No Opinion
Did they have any problems with the job? If so, what was the nature of the problem?	10 9	8	76	5	4	3	2	1	No Opinion
N/A Just the change orders, unforeseen, they got through it Rate the Contractor's restoration and clean-up work. N/A Project is ongoing – not closed out yet	10 9	8 7	76	5	4	3	2	1	No Opinion
Would you want to work with this Contractor again?	Definitely,	yes. Th	ey are	always	s re	sponsiv	e. Ha	ave a	site

Definitely, yes. They are always responsive. Have a site superintendent. Always on top of things.

Thank you for your time in participating in the proposal evaluation process for this project.

Sincerely,

Detto

Valetta Saldanha, P.E. Project Manager hdrinc.com

HDR

CONTRACTOR REFERENCE FORM

Date:	June 1, 2022								
Project:	City of Angleton Chen	City of Angleton Chenango GST Replacement							
Contractor:	DN Tanks LLC								
Reference Name:	Jonny Green	Company: Bleyl Engineering	Contact: (936) 441-7833						
Reference Project: City of Conroe - Pollok Drive Water Plant (Well No. 20) 1 MG Concrete Type III GST									
Dear Mr. Green (by phone):									

DN Tanks, LLC is the apparent low bidder for the above referenced project and has submitted your name as a reference. Reference responses will be included in the evaluation of lowest responsible bid proposals received for this project.

HDR would appreciate your time in rating your experience with this Contractor. Please circle the number corresponding to the response which best indicates your opinion of the Contractor or provide a short answer on the lines as it relates to each item.

	Excelle		Above Averaç		verag		Below Averag	-	oor	
Rate the Contractor's performance as a "team player".	10 9	8	7	6	5	4	3	2	1	No Opinion
How would you rate their ability to coordinate the work with neighboring property owners? City of Conroe performed most of the Contract Administration	10 9	68	7	6	5	4	3	2	1	No Opinion
Rate the quality of construction, the Contractor's supervision	10 9) 8	7	6	5	4	3	2	1	No Opinion
and project management. Rate the Contractor's ability to achieve completion of the project on time.	10 9)	7	6	5	4	-	2	1	No Opinion
Were there many change orders on the project? If so, what were the reasons? Were the reasonable?	None o	n reco	ord, City	' wou	ld hav	/e h	nandled			
Rate the Contractor's responsiveness to warranty work requests, and the guality of the work. <i>He was not involved, City handled</i>	10 9	8	7	6	5	4	3	2	1	No Opinion
Rate the Contractor's ability to expeditiously closeout projects.	10 (9) 8	7	6	5	4	3	2	1	No Opinion
Did they have any problems with the job? If so, what was the nature of the problem? Not that he is aware of	10 9	8	7	6	5	4	3	2	1	No Opinion
Rate the Contractor's restoration and clean-up work. Not sure	10 9	8	7	6	5	4	3	2	1	No Opinion
Would you want to work with this Contractor again?	He woul							0		would know

Note that the City of Conroe was very hands on and would know more about the handling of the project.

Thank you for your time in participating in the proposal evaluation process for this project.

Sincerely,

aletta

Valetta Saldanha, P.E. Project Manager

F

CONTRACTOR REFERENCE FORM

Date:	June 1, 2022									
Project:	City of Angleton Chenango GST Replacement									
Contractor:	DN Tanks LLC									
Reference	Name: Ana Karamalegos	Company: CDM Smith	Contact: (512) 346-1100							
Reference Project: City of Georgetown - Daniels Mountain Storage Tank, No. 201616, Contract No. 2016-505-C										
Dear Ms. K	aramalegos (by phone):									
DN Tanks, LLC is the apparent low bidder for the above referenced project and has submitted your name as a reference. Reference responses will be included in the evaluation of lowest responsible bid proposals received for this project.										
HDR would appreciate your time in rating your experience with this Contractor. Please circle the number corresponding to the response which best indicates your opinion of the Contractor or provide a short answer on the lines as it relates to each item.										

	Excellent	Above Averag	Avera e	ige	Below Average		Poor	
Rate the Contractor's performance as a "team player".	10 9	8 7	6 5	4	3	2	1	No Opinion
How would you rate their ability to coordinate the work with neighboring property owners?	10 9	8 7	65	4	3	2	1	No Opinion
Rate the quality of construction, the Contractor's supervision and project management.	10 9	8 7	65	4	3	2	1	No Opinion
Rate the Contractor's ability to achieve completion of the project on time.	10 9	8 7	65	4	3	2	1	No Opinion
Were there many change orders on the project? If so, what were the reasons? Were they reasonable?	Does not r	recall anyth	ing spec	cific d	or unexpe	ecte	ed occu	irring.
Rate the Contractor's responsiveness to warranty work requests, and the quality of the warranty work.	10 🤇	9 8	76	5	4	3	2	1 No Opinion
Rate the Contractor's ability to expeditiously closeout projects.	10	9 8	76	5	6 4	3	2	1 No Opinion
Did they have any problems with the job? If so, what was the nature of the problem?	<u>Nothing jur</u>	mps out to	<u>ner reco</u>	llecti	on. They	are	e very c	consistent.
Rate the Contractor's restoration and clean-up work. Would you want to work with this Contractor again?	10 (9 9 hem require	76 rly You		•	3	2 are gett	1 No Opinion ing with them.
Would you want to work with this Contractor again?	<u>100, USES II</u>	lienniegula	ny. rou	NIIUV	v what ye	Ju a	ne gen	ing with them.

Thank you for your time in participating in the proposal evaluation process for this project.

Sincerelv.

aletto

Valetta Saldanha, P.E. Project Manager

FJS

CONTRACTOR REFERENCE FORM

Date:	June 1, 2022		
Project:	City of Angleton Chenango GST	Replacement	
Contractor:	DN Tanks LLC		
Reference Nan	ne: Ana Karamalegos Com	pany: CDM Smith	Contact: (512) 3

Reference Project: Brazosport Water Authority, 2018 Plant Improvements, Contract 1 (Clearwell)

Dear Ms. Karamalegos (by phone):

DN Tanks, LLC is the apparent low bidder for the above referenced project and has submitted your name as a reference. Reference responses will be included in the evaluation of lowest responsible bid proposals received for this project.

HDR would appreciate your time in rating your experience with this Contractor. Please circle the number corresponding to the response which best indicates your opinion of the Contractor or provide a short answer on the lines as it relates to each item.

346-1100

	Excellent	Above Averaç		erage	Below Averag		Poor	
Rate the Contractor's performance as a "team player".	10 9	8 7	6	54	3	2	1	No Opinion
How would you rate their ability to coordinate the work with neighboring property owners?	10 9	8 7	6	54	3	2	1	No Opinion
Rate the quality of construction, the Contractor's supervision and project management.	10 9	8 7	6	54	3	2	1	No Opinion
Rate the Contractor's ability to achieve completion of the project on time.	: 10 9	8/7	6	54	3	2	1	No Opinion
Were there many change orders on the project? If so, what were the reasons? Were they reasonable?	e <u>Does not r</u>	ecall anyt	hing s	pecific	or unexp	ecte	ed occu	ırring.
Rate the Contractor's responsiveness to warranty work requests, and the quality of the warranty work.	10 🤇	8	7	6 5	54	3	2	1 No Opinion
Rate the Contractor's ability to expeditiously closeout projects.	10	8	7	6 5	54	3	2	1 No Opinion
Did they have any problems with the job? If so, what was the nature of the problem?	<u>Nothing jur</u>	<u>nps out to</u>	<u>her re</u>	collecti	ion. They	/ are	e very o	consistent.
Rate the Contractor's restoration and clean-up work.	10 🤅	8	7	6	54	3	2	1 No Opinion
Would you want to work with this Contractor again?	<u>Yes, uses th</u>	nem regula	arly. Yo	ou knov	w what y	ou a	ire gett	ing with them.
Thank you for your time in participating in the proposal evaluatio	n process for	r this proje	ect.					

Sincerely,

aletto

Valetta Saldanha, P.E. Project Manager

FJS

CONTRACTOR REFERENCE FORM

Date: June 1, 2022

Project: City of Angleton Chenango GST Replacement

Contractor: DN Tanks LLC

Reference Name: Jason Baze Company: Murfee Engineering Company Inc Reference Project: West Travis PUA Southwest Parkway GST

Contact: (512) 739-5057

Dear Mr. Baze (by phone):

DN Tanks, LLC is the apparent low bidder for the above referenced project and has submitted your name as a reference. Reference responses will be included in the evaluation of lowest responsible bid proposals received for this project.

HDR would appreciate your time in rating your experience with this Contractor. Please circle the number corresponding to the response which best indicates your opinion of the Contractor or provide a short answer on the lines as it relates to each item.

	Excellent	Above Averag	Aver e	age	Below Averag		Poor	
Rate the Contractor's performance as a "team player". 7.5	10 9 (8 7	6 5	4	3	2	1	No Opinion
How would you rate their ability to coordinate the work with 8.1 neighboring property owners?	10 9	8 7	65	4	3	2	1	No Opinion
Rate the quality of construction, the Contractor's supervision 7.8 and project management.	10 9 (8 7	65	4	3	2	1	No Opinion
Rate the Contractor's ability to achieve completion of the 9.1 project on time.	10 9	87	65	4	3	2	1	No Opinion
Were there many change orders on the project? If so, what were the reasons? Were they reasonable?	There were	discrepan They	<u>cies no</u>	t the	fault of [<u>T NC</u>	anks.	Reasonable_
Rate the Contractor's responsiveness to warranty work8.5requests, and the quality of the warranty work.	10 (9	8	76	5 5	5 4	3	2	1 No Opinion
Rate the Contractor's ability to expeditiously closeout 8.8 projects.	10 (9	8	76	i t	54	3	2	1 No Opinion
Did they have any problems with the job? If so, what was the nature of the problem?	<u>There was o</u> resulted, how			-	er that wa	as a	n issue	and some delays
Rate the Contractor's restoration and clean-up work.9.9Would you want to work with this Contractor again?	10 9 Yes, he would	8 <u>d,</u>	76	3 5	54	3	2	1 No Opinion

Thank you for your time in participating in the proposal evaluation process for this project.

Sincerely,

Aletta

Valetta Saldahna, P.E. Project Manager