Department Reports

ELECTRIC DISTRIBUTION

Tickets, locates

POWER PLANT

Rounds

STREET

Picked up tree limbs from wind Removed tree at Campsite B lake Hauled debris pile from town to east dump Cut large tree on east Main Street Replace broken signs at LL&G and Garfield

WATER/WASTEWATER

Rounds, tickets, locates Work on well 4 Clean high service Study for sewer and water tests Water samples Clean trucks