WINTON PARK 1200 Block of South "G" Street Fall 2006

LOCATION / DEFICENCY	ADAAG REQUIREMENT(S)	PRIORIT L = Low M = Medium H = High	Barrier Removal Target Date & <u>Notes</u>	RECOMMENDATIONS
PARK FEATURES				
Parking: - No designated parking exists (gravel/grass).	Minimum of 1 "van accessible" space with an access aisle at least 96" wide. Parking spaces and access aisles shall be level with surface slopes not exceeding 1:50 or 2% in all directions. Signage shall be located so they cannot be obscured by a vehicle parked in the space (4.1.2(5)(b), 4.6.3 and 4.6.4).	Н		
Accessible Routes: - Amenities such as shelter, BBQ grill, basketball courts, playground, etc., are surrounded by uneven grass (picture).	At least one accessible route shall connect accessible buildings, facilities, elements, and spaces that are on the same site. Ground and floor surfaces along accessible routes and in accessible rooms and spaces including floors, walks, ramps, stairs, and curb ramps, shall be stable, firm, slipresistant. Changes in level up to ¼" may be vertical and without edge treatment. Changes in level between ¼" and ½" shall be beveled with a slope no greater than 1:2. Changes in level greater than ½" shall be accomplished by means of a ramp (4.3.2 and 4.5.2).	Н-		
Playground: - Equipment and surfaces lack accessible features (pictures).	See "Best Practice" guidance for Parks in the Transition Plan.	L		



Park amenities such as the shelter, playground, BBQ grill are not on an accessible route.