

signs that project over the sidewalk unless they were a characteristic feature of the historic building; or other types of signs that obscure, damage, or destroy remaining character-defining features of the historic building" is not recommended. The sign appears appropriately scaled and is placed on the very narrow sign board which appears to be the appropriate placement. Signs with reverse lit channel letters are considered compatible. In the past, signs have been on awnings or projecting but there is no historical evidence of where signs were placed prior to 1998. The sign would meet the Standards and could be approved per KSA 75-2724.

Project Type & Review Standards			
	YES	NO	N/A
Historic use/reuse and minimal change to distinctive materials, features, etc.			X
Historic character retained; removal or alteration distinctive materials avoided	X		
No changes that create a false sense of historical development	X		
Changes that have acquired historical significance in their own right will be retained	X		
Distinctive materials, features, examples of craftsmanship, etc. will be preserved	X		
Repair deteriorated historic features; new features will match old in design			X
Chemical and physical treatments will be as gentle as possible			X
Protect and preserve archeological resources in place			X
New construction will not destroy historic features that characterize property and will be differentiated from the old; new work is compatible with size, scale, massing, etc	X		X
New construction can be removed without destroying essential form & integrity	X		



111 S. Summit. 1940s Historic View. Images: A Pictorial History of Cowley County Vol. II (2001) scanned by CC Historical Museum. Emphasis added. Downloaded from KHRI on 10/30/2023.

