

Photographs: Project 1 - Bastrop County Courthouse, Tower Repairs



Photo 1: Courthouse tower, existing conditions



Photo 2: Detail of existing sheet metal cladding and clock face.



Photo 3: Detail of existing sheet metal cladding



Photo 4: Existing conditions at tower framing



Photo 5: Existing conditions at tower framing



Photo 6: Detail of existing sheet metal cladding



Photo 7: View of clockworks and interior wood framing



Photo 8: Original clocktower bell



Photo 9: Original clockworks