Emily Wakley DeLozier, 3019 Indian Drive – Variance Request Additional Information/Clarification

Pictures were taken Sunday, 7/16/2023. Reported lake elevation on that day was 84.44 ft (per email from David Woods). Elevation of 79.5 lake bottom would be approximately 5 ft below the water level of the lake (84.44 ft – 79.5 ft = 4.94 ft). Markers on pole are measured as follows on the top of the color:


Black = 5'







The following measurements/pictures are taken from the end of the existing walkway (52 ft walkway ext + 14 ft dock = 66 ft)




~67 ft from end of existing walkway, water level 5' (bottom elevation ~79.44 ft)



End of existing walkway





End of exsiting structure in pictures (to be removed) is $^{\sim}43$ ft from the end of the existing walkway.