

FOUND #5 REBAR, ELEVATION 9997.93' (WGS84)

X

N	LEGEND OTE: NOT ALL ITEMS BELOW ARE REFERENCED IN THIS PLAN
EOA	EDGE OF ASPHALT
EOG	EDGE OF GRAVEL
FG	FINISH GRADE (AT SURFACE)
STA	SOIL TREATMENT AREA (LEACH FIELD)
TOS	TOP OF SLAB
TOT	TOP OF TANK
W	EXISTING WELL
•	PVC PIPE CLEANOUT LOCATED
SS	SEWER LINE
• WF #	WETLAND FLAG LOCATION AND RESPECTIVE #
	EXISTING MAJOR CONTOUR
	EXISTING MINOR CONTOUR
-(100)	EXISTING CONTOUR (ELEV, FT) LABEL
	PROPOSED CONTOUR
	PROPOSED CONTOUR LABEL
\bullet	PROPERTY PIN LOCATED BY SURVEY
	PROPERTY PIN NOT FOUND
	ELEVATION POINT (0.1 FEET ±)
	UTILITY
<	DRAINAGE ROUTE
FT	TREE LOCATION/CANOPY & HEIGHT
	WETLANDS (IF DELINEATED)
	GRAVEL OR DIRT ROADWAY
	ASPHALT ROADWAY
<i>₩</i>	FIRE HYDRANT
)- 	GUY ANCHOR
	MANHOLE
4	POLE-FLAG
<u> </u>	POLE - LIGHT
	POLE-TRAFFIC LIGHT
-0-	POLE-UTILITY
0	BOLLARD
OE	OVERHEAD UTILITY LINE
	-

- GOLD KING NO. 1 PLACER


FOUND #5 REBAR, ELEVATION 9996.72' (WGS84) BENCHMARK

(10290)

(100)



PROPERTY PIN NOT VISIBLE (NOT LOCATED WHEN THIS SURVEY WAS PERFORMED). THIS POINT WAS LOCATED BY HOLDING THE SOUTH PROPERTY LINE PER SUBDIVISION PLAT MAP BY HOWARD P. BUNGER, JR., DATED MAY 14, 1966. BOUNDARY SURVEY RECOMMENDED PRIOR TO DEVELOPMENT.



Ŵ

EXISTING WELL

10010

- LOT 554~

EDGE OF GRAVEL, LODESTONE TRAIL

EXISTING NEIGHBORING STRUCTURE

> EXISTING NEIGHBORING STRUCTURE


EXISTING NEIGHBORING

STRUCTURE

PROPERTY INFORMATION THE CROWN SUBDIVISION GOOSE PASTURE TARN LOT 532 39 LODESTONE TRAIL BLUE RIVER, CO 80424

SURVEY NOTES

DRAWING PREPARED FOR: HELEN SCHNEIDER LEMAY 266 CROWN DRIVE BLUE RIVER, CO 80424 <u>PROPERTY OWNER:</u> SAME AS ABOVE



Y 285, SUITE #201 COLORADO 80440 FICE 719.836.7120 ONE 719.783.3757

Ζ

Ш

U

Ζ

0

T

Ш'

 \frown

PROJECT NO.

2023-100072

CLIENT

HELEN

LEMAY

DATE

07.13.2023

REVISION:

Z () PF

 2. BASIS OF BEARING IS THE WEST LINE OF THE CROWN SUBDIVISON, WHICH BEARS SOUTH 19°59'00" WEST, 120 FEET. MONUMENTS FOUND, AS SHOWN.
3. BASIS OF ELEVATION IS THE SOUTHWEST CORNER OF LOT 532. ELEVATION IS 9996.72 FEET, BASED ON WGS84 MAPPING.

1. SURVEY WAS COLLECTED USING AERIAL IMAGERY. AERIAL SURVEY IS A

METHOD OF COLLECTING GEOMATICS OR OTHER IMAGERY BY USING UAV'S,

LIDAR SENSING IN THE NON-VISIBLE PART OF THE ELECTROMAGNETIC

AND OTHER AERIAL METHODS. TECHNIQUES OF AERIAL PHOTOGRAPHY AND

SPECTRUM AND EARTH OBSERVATION WERE USED TO CREATE THIS SURVEY.

4. THE PURPOSE OF THIS SURVEY IS FOR THE CREATION OF A TOPOGRAPHIC MAP. ENGINEER DID NOT REVIEW A TITLE COMMITMENT; THIS SURVEY DOES NOT REPRESENT A TITLE SEARCH BY THIS ENGINEER.

5. ENGINEER DID NOT REVIEW EASEMENTS, BUILDING SETBACKS, CONSTRUCTION SETBACK REQUIREMENTS, RIGHT OF WAYS, AND/OR NEIGHBORING LOT INFORMATION.

6. ENGINEER DID NOT REVIEW SPECIFIC BUILDING COMPONENTS INCLUDING BUT NOT LIMITED TO STRUCTURES, SEPTIC SYSTEMS, ACCESS REQUIREMENTS

7. CERTIFICATION NOT VALID WITHOUT ORIGINAL SEAL AND SIGNATURE. THIS SURVEY AND ALL RELATED DOCUMENTS ARE FOR THE SOLE USE OF THE CLIENT AT THE DATE OF CERTIFICATION AND DOES NOT EXTEND TO ANY UNNAMED PERSON OR ENTITY WITHOUT AND EXPRESSED RESTATEMENT BY THE ENGINEER NAMING SAID PERSON OR ENTITY.

8. UNITS OF MEASURE: SURVEY FEET

9. ONE FOOT CONTOUR INTERVAL SHOWN HEREIN.

10. AREA: 0.54 ACRES, 23,695 SQUARE FEET.

11. REFERENCE DOCUMENT: SUBDIVISION PLAT "THE CROWN, GOOSE PASTURE TARN, BLUE RIVER ESTATES, INC." ACCEPTED MAY 14, 1966.

12. ONLY VISIBLE UTILITIES LOCATED AND SHOWN. UNDERGROUND LOCATE NOT DONE.

13. ANY PERSON WHO KNOWINGLY REMOVES, ALTERS, OR DEFACES ANY PUBLIC LAND SURVEY MONUMENT OR BOUNDARY MONUMENT OR ACCESSORY, COMMITS A CLASS TWO (2) MISDEMEANOR PURSUANT TO STATE STATUTE 18-4-508, C.R.S.

14. THE SOUTHEAST PROPERTY CORNER WAS UNABLE TO BE LOCATED IN THE FIELD. IT IS SHOWN BASED ON THE BEARING AND DISTANCE OF THE SOUTH PROPERTY LINE ILLUSTRATED ON THE SUBDIVISION PLAT (SEE NOTE 11). THE EAST PROPERTY LINE IS DRAWN AS MEASURED BETWEEN NORTHEAST KNOWN PIN AND CALCULATED SOUTHEAST PIN LOCATION.

NOTICE: ACCORDING TO COLORADO LAW YOU MUST COMMENCE ANY LEGAL ACTION BASED UPON ANY DEFECT IN THIS SURVEY WITHIN THREE YEARS AFTER YOU FIRST DISCOVER SUCH DEFECT. IN NO EVENT MAY ANY ACTION BASED UPON ANY DEFECT IN THIS SURVEY BE COMMENCED MORE THAN TEN YEARS FROM THE DATE OF THE CERTIFICATION SHOWN HEREON.

THIS DRAWING IS SIGNED AND/OR SEALED BY A PROFESSIONAL ENGINEER REPRESENTING THAT THE ENGINEERING SERVICES ADDRESSED HEREIN HAVE BEEN PERFORMED BY THE PROFESSIONAL ENGINEER OR UNDER THE PROFESSIONAL ENGINEER IN RESPONSIBLE CHARGE.

THIS SURVEY IS BASED UPON THE PROFESSIONAL ENGINEER'S KNOWLEDGE, INFORMATION, AND BELIEF AND IS IN ACCORDANCE WITH APPLICABLE STANDARDS OF TOPOGRAPHIC SURVEY PRACTICE KNOWN TO THE ENGINEER. THIS SURVEY IS NOT A GUARANTY OR WARRANTY, EITHER EXPRESSED OR IMPLIED, OF CONFIRMATION OF THE PROPERTY BOUNDARY LINES AND PROPERTY MONUMENTS. IF THERE ARE ANY QUESTIONS ABOUT PROPERTY BOUNDARY MONUMENTS, PROPERTY BOUNDARY LINES, AND/OR EASEMENTS, A REGISTERED COLORADO SURVEYOR SHOULD BE CONTACTED FOR VERIFICATION OF SUCH.



0'		20'		40'		,	6	0
	$\sim \pm \pm c$				<i>،</i> ،	,	~~'	

PLOTTED SCALE 1" = 20'