

Public Works Department Report

Operations & Maintenance

- Collector 3 maintenance remove sand from caisson.
 - Turbidity meter working correctly on SCADA.
 - Painting of Hydrant lanes.
 - Walkway paved from Main St. to dog park location on First Street at Oregon Trail.
 - Storm Drain sump cleaning throughout City.
 - Preparing for new tap at Tatone and Oregon Trail for service to SW First street loop area.
 - Sweeping at Riverside High School for new school year.
-

City Parks and landscaping

- Pulling and spraying weeds citywide.
 - Replaced several valves and sprinklers throughout the city parks.
 - Continuing irrigation for Circle 52.
 - Plans for moving the dog park as soon as the BPA green way is grubbed all equipment has been removed from old park and waiting for installation at new site as soon as it is ready.
 - With help from Church groups we painted the wayside gazebo, poured concrete pads and replaced garbage cans, and did some clean up.
-

Sampling & Compliance

- Collected water and wastewater samples for OSU, DEQ, and OHA.
 - Collector Well 3 testing and flushing completed.
 - Backflow testing throughout City.
 - Continue to work towards completion of valve exercising.
 - Scheduling for courses to complete cross connection training.
-

Bids

- Biosolid removal lagoon 1
- Crack seal