DEVELOPER'S PACKET

Produced By:

Clark County Geographic Information System (GIS)



For:

Olson Engineering Inc.

Subject Property Account Number(s):

127357000


PDF # 278036

Printed: January 10, 2022 Expires: January 10, 2023

Table of Contents

General Location	1
Property Information Fact Sheet	2
Elevation Contours	3
2020 Aerial Photography	4
2020 Aerial Photography with Elevation Contours	5
Zoning Designations	6
Comprehensive Plan Designations	7
Arterials, C-Tran Bus Routes, Parks & Trails	8
Water, Sewer, and Storm Systems	9
Water Systems	10
Hydrant Fire Flow Details	11
Soil Types	12
Environmental Constraints I	13
Environmental Constraints II	14
Adjacent Development	15
Quarter Section Parcels	16

Developer's Packet: Page 1 of 16



Property Information Fact Sheet

Mailing Information:

Account No.: 127357000

Owner: DEWITT LEONA

Address: PO BOX 674

C/S/Z: CAMAS, WA 98607

Assessed Parcel Size: 2.16 Ac

Property Type: UNUSED OR VACANT LAND - NO IMPROVEMENTS

PARCEL LOCATION FINDINGS:

Quarter Section(s): NW 1/4,S09,T1N,R3E

Municipal Jurisdiction: Camas Urban Growth Area: Camas

Zoning: CC

Zoning Overlay: No Mapping Indicators **Comprehensive Plan Designation:** COM

Columbia River Gorge NSA: No Mapping Indicators

Late-Comer Area: No Mapping Indicators

Trans. Impact Fee Area: Camas

Park Impact Fee District: No Mapping Indicators

Neighborhood Association: No Mapping Indicators

School District: Camas

Elementary School: Grass Valley **Junior High School:** Skyridge Middle

Senior High School: Camas

Fire District: City of Camas Sewer District: Camas Water District: Camas

Printed: January 10, 2022

Wildfire Danger Area: Over 500ft need further review

ENVIRONMENTAL CONSTRAINTS:

Soil Type(s): PoB, 97.8% of parcel

PoD, 2.2%

Hydric Soils: Non-Hydric, 100.0% of parcel **Flood Zone Designation:** Outside Flood Area

CARA: Category 2 Recharge Areas

Forest Moratorium Area: No Mapping Indicators

Liquefaction Susceptibility: Bedrock

NEHRP: B

Slope: 0 - 5 percent, 30.3% of parcel

5 - 10 percent, 69.7%

Landslide Hazards: No Mapping Indicators **Slope Stability:** No Mapping Indicators


Cultural Resources:

Archeological Predictive: Moderate, 43.2% of parcel

Moderate-High, 56.8%

Archeological Site Buffers: No Mapping Indicators

Historic Sites: No Mapping Indicators








Feet

2020 Aerial Photography

Account: 127357000
Owner: DEWITT LEONA
Address: PO BOX 674
C/S/Z: CAMAS, WA 98607

Subject Property(s)

Printed on: January 10, 2022



Developer's Packet: Page 4 of 16







2020 Aerial Photography with Elevation Contours


Account: 127357000 Owner: DEWITT LEONA Address: PO BOX 674 C/S/Z: CAMAS, WA 98607


2' Elevation Contours
Subject Property(s)





Developer's Packet: Page 5 of 16











Hydrant Fire Flow Details

Account No.: 127357000
Owner: DEWITT LEONA
Address: PO BOX 674
C/S/Z: CAMAS, WA 98607

Water District(s) Hydrant Data Update Project Site Provider	ter District(s) Hydrant Data Update Pr	Hydrant Data Update Project Site Provid	s) Hydrant Data Update Project Site Provider
Camas March 17, 2021 Service Provider	nas March 17, 2021 Se	March 17 2021 Service Provider	March 17, 2021 Service Provider

HYDRANT INFORMATION:

Hydrant ID	Hydrant Owner	Main Diameter	Flow at 20 PSI	Test Date	Distance to site
Unknown	Unknown	0.0"	No Data		96 ft
Unknown	Unknown	0.0"	No Data		158 ft
Unknown	Unknown	0.0"	No Data		272 ft
Unknown	Unknown	0.0"	No Data		351 ft
2021-161	Private	0.0"	No Data		413 ft
Unknown	Unknown	0.0"	No Data		432 ft

Printed: January 10, 2022

