

March 2026

Construction Photo Exhibit – Jade Street Site



Community Center Exterior Work
Front entry concrete installation completed.



Community Center Exterior Work
Exterior siding installation in progress.




Community Center Exterior Work

Installation of bike racks near the Community Center entrance.




Community Center Interior Improvements

Installation of decorative entry wall feature.



Community Center Interior Improvements
Installation of acoustic ceiling panels in the entry area.



Community Center Interior Improvements
Installation of marmoleum flooring throughout interior spaces.



Community Center Interior Improvements
Kitchen area prior to appliance installation.



Community Center Interior Improvements
Men's restroom nearing completion.

March 2026
Construction Photo Exhibit – Jade Street Site



Treasure Cove Playground Infrastructure
Drainage system installation.



Treasure Cove Playground Infrastructure
Concrete forming for walkway installation.

March 2026
Construction Photo Exhibit – Jade Street Site




Treasure Cove Playground Infrastructure
Subsurface work and base preparation.



Treasure Cove Playground Infrastructure
Final grading and concrete formwork.



Jade Street Park Restroom Renovation
Restroom facility prior to demolition.



Jade Street Park Restroom Renovation
Demolition of existing restroom interior completed.