

Exhibit 1: Kitchen Interior Demolition & Ceiling Work



Exposed framing, insulation, and partial drywall installation with ceiling electrical rough-ins.

Exhibit 2: Roof Demolition and Temporary Covering



Crew working on roof structure, black sheathing in place for weather protection.

Exhibit 3: Structural Beam and Column Reinforcement



Close-up of new beams and steel brackets installed on concrete support columns.

Exhibit 4: Roof Sheathing Installation



Multiple workers fastening new roof sheathing in place.

Exhibit 5: Plumbing Rough-In



Exposed plumbing pipes at restroom wall during rough-in stage.

Exhibit 6: Covered Outdoor Area Progress



Painted roof soffit and posts; site grading visible in foreground.

Exhibit 7: Sidewalk Trenching



Crews trenching along sidewalk for underground utilities.

Exhibit 8: Interior Framing



Interior stud framing walls in progress with open ceiling.

Exhibit 9: Interior Concrete Patch



New concrete patch inside building covering utility trench.

Exhibit 10: Entrance Concrete Work



Heavy equipment and crews performing grading and concrete work at building entrance.

Exhibit 11: Exterior Waterproofing



View of new waterproofing along the exterior wall, with wood ceiling soffit above.

Exhibit 12: EV Charger Trenching



Long trench cut through asphalt for conduit installation, extending approximately 300 feet.

Exhibit 13: Main Room Drywall Installation



Interior drywall installed in large main room; steel beams and electrical rough-in visible.

Exhibit 14: Concrete Work – Excavation and Foundation



Excavation and demolition at the building entry; equipment breaking up existing concrete.