

December 11, 2025
Construction Photo Exhibit – Jade Street Site



Front entry approach graded and compacted, with concrete seat walls and large boulders installed along the pedestrian pathway

December 11, 2025
Construction Photo Exhibit – Jade Street Site



Front office window units installed, surrounded by exterior sheathing and waterproofing

December 11, 2025
Construction Photo Exhibit – Jade Street Site



Installation of new storefront system with weatherproofing membrane and flashing

December 11, 2025
Construction Photo Exhibit – Jade Street Site



Decorative concrete patio slab placed and stamped with wood-plank pattern

December 11, 2025
Construction Photo Exhibit – Jade Street Site



Concrete patio and sculpted seat walls

December 11, 2025
Construction Photo Exhibit – Jade Street Site



Exposed truss system fully painted

December 11, 2025
Construction Photo Exhibit – Jade Street Site



Interior soffit framing and drywall enclosure to house the operable partition track system

December 11, 2025
Construction Photo Exhibit – Jade Street Site

Exhibit 5



Interior progress with wall paint applied and linear LED lighting

December 11, 2025
Construction Photo Exhibit – Jade Street Site



Upper windows installed

December 11, 2025
Construction Photo Exhibit – Jade Street Site



Demolition of existing playground equipment and surfacing.

December 11, 2025
Construction Photo Exhibit – Jade Street Site



Additional demolition progress, removal of old playground footings

December 11, 2025
Construction Photo Exhibit – Jade Street Site



Additional demolition progress