

# Coburg Parks Table & Bench Inventory

Date: January 15, 2026




**Condition Descriptions**

**Good:** \_\_\_\_\_

**Fair:** \_\_\_\_\_

**Poor:** \_\_\_\_\_

**Norma Pfeiffer Picnic Table 1**



**Location:** Norma Pfeiffer Park Picnic Shelter

**Material:** Wood with metal frame

**Condition (Good/Fair/Poor):** Fair

**Asset ID:** Picnic table 1


**Install Date:** Unknown

**Notes:** \_\_\_\_\_

**Covered/Exposed:** \_\_\_\_\_

**Inspection/Review Date:** \_\_\_\_\_

**Norma Pfeiffer Picnic Table 2**



**Location:** Norma Pfeiffer Park Picnic Shelter

**Material:** Wood with metal frame

**Condition (Good/Fair/Poor):** Good

**Asset ID:** Picnic table 2


**Install Date:** Unknown

**Notes:** \_\_\_\_\_

**Covered/Exposed:** \_\_\_\_\_

**Inspection/Review Date:** \_\_\_\_\_

**Norma Pfeiffer Picnic Table 3**



**Location:** Norma Pfeiffer Park Picnic Shelter

**Material:** Wood with metal frame

**Condition (Good/Fair/Poor):** Good

**Asset ID:** Picnic table 3

**Install Date:** Unknown

**Notes:** \_\_\_\_\_


\_\_\_\_\_

\_\_\_\_\_

**Covered/Exposed:** \_\_\_\_\_

**Inspection/Review Date:** \_\_\_\_\_

**Norma Pfeiffer Picnic Table 4**



**Location:** Norma Pfeiffer Park Picnic Shelter

**Material:** Wood with metal frame

**Condition (Good/Fair/Poor):** Good

**Asset ID:** Picnic table 4

**Install Date:** Unknown

**Notes:** \_\_\_\_\_


\_\_\_\_\_

\_\_\_\_\_

**Covered/Exposed:** \_\_\_\_\_

**Inspection/Review Date:** \_\_\_\_\_

**Norma Pfeiffer Picnic Table 5**



**Location:** Norma Pfeiffer Park Picnic Shelter

**Material:** Wood with metal frame

**Condition (Good/Fair/Poor):** Good

**Asset ID:** Picnic table 5

**Install Date:** Unknown

**Notes:** \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

**Covered/Exposed:** \_\_\_\_\_

**Inspection/Review Date:** \_\_\_\_\_

**Norma Pfeiffer Picnic Table 6**



**Location:** Norma Pfeiffer Park Picnic Shelter

**Material:** Metal

**Condition (Good/Fair/Poor):** Good

**Asset ID:** Picnic table 6

**Install Date:** 2020

**Notes:** \_\_\_\_\_


\_\_\_\_\_

\_\_\_\_\_

**Covered/Exposed:** \_\_\_\_\_

**Inspection/Review Date:** \_\_\_\_\_

**Pavilion Park Picnic Table 7**



**Location:** Pavilion Park near Bike Hub

**Material:** Wood with metal frame

**Condition (Good/Fair/Poor):** Poor

**Asset ID:** Picnic table 7


**Install Date:** Unknown

**Notes:** \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

**Covered/Exposed:** \_\_\_\_\_

**Inspection/Review Date:** \_\_\_\_\_

**Pavilion Park Picnic Table 8**



**Location:** Pavilion Park west side

**Material:** Wood with metal frame

**Condition (Good/Fair/Poor):** Fair

**Asset ID:** Picnic table 8


**Install Date:** Unknown

**Notes:** \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

**Covered/Exposed:** \_\_\_\_\_

**Inspection/Review Date:** \_\_\_\_\_

**Pavilion Park Picnic Table 9**




**Location:** Pavilion Park west side  
**Material:** Wood with metal frame  
**Condition (Good/Fair/Poor):** Fair  
**Asset ID:** Picnic table 9  
**Install Date:** Unknown  
**Notes:** \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
**Covered/Exposed:** \_\_\_\_\_  
**Inspection/Review Date:** \_\_\_\_\_

**Pavilion Park Picnic Table 10**




**Location:** Pavilion Park ADA Picnic area  
**Material:** Wood with metal frame  
**Condition (Good/Fair/Poor):** Good  
**Asset ID:** Picnic table 10  
**Install Date:** Unknown  
**Notes:** \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
**Covered/Exposed:** \_\_\_\_\_  
**Inspection/Review Date:** \_\_\_\_\_

**Johnny Diamond Park Table 11**



**Location:** Johnny Diamond Park  
**Material:** Wood with metal frame  
**Condition (Good/Fair/Poor):** Good  
**Asset ID:** Picnic table 11  
**Install Date:** 2018  
**Notes:** \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
**Covered/Exposed:** \_\_\_\_\_  
**Inspection/Review Date:** \_\_\_\_\_

**Johnny Diamond Park Table 12**



**Location:** Johnny Diamond Park ADA  
**Material:** Wood with metal frame  
**Condition (Good/Fair/Poor):** Good  
**Asset ID:** Picnic table 12  
**Install Date:** 2018  
**Notes:** \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
**Covered/Exposed:** \_\_\_\_\_  
**Inspection/Review Date:** \_\_\_\_\_

**Johnny Diamond Park Table 13**



**Location:** Johnny Diamond Park Play Area

**Material:** Metal

**Condition (Good/Fair/Poor):** Good

**Asset ID:** Picnic table 13


**Install Date:** \_\_\_\_\_

**Notes:** \_\_\_\_\_

**Covered/Exposed:** \_\_\_\_\_

**Inspection/Review Date:** \_\_\_\_\_

**Jacob Spores Park Table 14**



**Location:** Jacob Spores Picnic Shelter

**Material:** Wood with metal frame

**Condition (Good/Fair/Poor):** Fair

**Asset ID:** Picnic table 14


**Install Date:** Unknown

**Notes:** \_\_\_\_\_

**Covered/Exposed:** \_\_\_\_\_

**Inspection/Review Date:** \_\_\_\_\_

**Jacob Spores Park Table 15**



**Location:** Jacob Spores Park Picnic Shelter

**Material:** Wood with metal frame

**Condition (Good/Fair/Poor):** Fair

**Asset ID:** Picnic table 15


**Install Date:** Unknown

**Notes:** \_\_\_\_\_

**Covered/Exposed:** \_\_\_\_\_

**Inspection/Review Date:** \_\_\_\_\_

**Trails End Park Table 16**



**Location:** Trails End Park Picnic Pad

**Material:** Metal

**Condition (Good/Fair/Poor):** Good

**Asset ID:** Picnic table 16

**Install Date:** 2019

**Notes:** \_\_\_\_\_

**Covered/Exposed:** \_\_\_\_\_

**Inspection/Review Date:** \_\_\_\_\_

**Norma Pfeiffer Park Bench 1**




**Location:** Norma Pfeiffer Park  
**Material:** Wood and metal  
**Condition (Good/Fair/Poor):** Poor  
**Asset ID:** Bench 1  
**Install Date:** Unknown  
**Notes:** \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
**Covered/Exposed:** \_\_\_\_\_  
**Inspection/Review Date:** \_\_\_\_\_

**Norma Pfeiffer Park Bench 2**




**Location:** Norma Pfeiffer Park  
**Material:** Wood and metal  
**Condition (Good/Fair/Poor):** Poor  
**Asset ID:** Bench 2  
**Install Date:** Unknown  
**Notes:** \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
**Covered/Exposed:** \_\_\_\_\_  
**Inspection/Review Date:** \_\_\_\_\_

**Norma Pfeiffer Park Bench 3**



**Location:** Norma Pfeiffer Park  
**Material:** Wood and metal  
**Condition (Good/Fair/Poor):** Fair  
**Asset ID:** Bench 3  
**Install Date:** Unknown  
**Notes:** \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
**Covered/Exposed:** \_\_\_\_\_  
**Inspection/Review Date:** \_\_\_\_\_

**Norma Pfeiffer Park Bench 4**



**Location:** Norma Pfeiffer Park  
**Material:** Wood and metal  
**Condition (Good/Fair/Poor):** Fair  
**Asset ID:** Bench 4  
**Install Date:** Unknown  
**Notes:** \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
**Covered/Exposed:** \_\_\_\_\_  
**Inspection/Review Date:** \_\_\_\_\_

**Norma Pfeiffer Park Bench 5**



**Location:** Norma Pfeiffer Park Veterans Rose Garden

**Material:** Wood and metal

**Condition (Good/Fair/Poor):** Good

**Asset ID:** Bench 5

**Install Date:** Unknown

**Notes:** \_\_\_\_\_  
\_\_\_\_\_

**Covered/Exposed:** \_\_\_\_\_

**Inspection/Review Date:** \_\_\_\_\_

**Pavilion Park Bench 6**



**Location:** Pavilion Park near Restrooms

**Material:** Wood and metal

**Condition (Good/Fair/Poor):** Good

**Asset ID:** Bench 6


**Install Date:** Unknown

**Notes:** \_\_\_\_\_  
\_\_\_\_\_

**Covered/Exposed:** \_\_\_\_\_

**Inspection/Review Date:** \_\_\_\_\_

**Pavilion Park Bench 7**



**Location:** Pavilion Park near Restrooms  
**Material:** Wood and metal  
**Condition (Good/Fair/Poor):** Good  
**Asset ID:** Bench 7  
**Install Date:** Unknown  
**Notes:** \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
**Covered/Exposed:** \_\_\_\_\_  
**Inspection/Review Date:** \_\_\_\_\_

**Pavilion Park Bench 8**



**Location:** Pavilion Park west side  
**Material:** Wood and metal  
**Condition (Good/Fair/Poor):** Fair  
**Asset ID:** Bench 8  
**Install Date:** Unknown  
**Notes:** \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
**Covered/Exposed:** \_\_\_\_\_  
**Inspection/Review Date:** \_\_\_\_\_

**Pavilion Park Bench 9**



**Location:** Pavilion Park west side

**Material:** Wood and metal

**Condition (Good/Fair/Poor):** Fair

**Asset ID:** Bench 9

**Install Date:** Unknown

**Notes:** \_\_\_\_\_

**Covered/Exposed:** \_\_\_\_\_

**Inspection/Review Date:** \_\_\_\_\_

**Johnny Diamond Park Bench 10**



**Location:** Johnny Diamond Park

**Material:** Wood and metal

**Condition (Good/Fair/Poor):** Good

**Asset ID:** Bench 10

**Install Date:** Unknown

**Notes:** \_\_\_\_\_

**Covered/Exposed:** \_\_\_\_\_

**Inspection/Review Date:** \_\_\_\_\_

**Johnny Diamond Park Bench 11**



**Location:** Johnny Diamond Park  
**Material:** Wood and metal  
**Condition (Good/Fair/Poor):** Good  
**Asset ID:** Bench 11  
**Install Date:** Unknown  
**Notes:** \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
**Covered/Exposed:** \_\_\_\_\_  
**Inspection/Review Date:** \_\_\_\_\_

**Johnny Diamond Park Bench 12**



**Location:** Johnny Diamond Park South Side  
**Material:** Wood and metal  
**Condition (Good/Fair/Poor):** Good  
**Asset ID:** Bench 12  
**Install Date:** Unknown  
**Notes:** \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
**Covered/Exposed:** \_\_\_\_\_  
**Inspection/Review Date:** \_\_\_\_\_

**Johnny Diamond Park Bench 13**



**Location:** Johnny Diamond Park west side

**Material:** Wood and metal

**Condition (Good/Fair/Poor):** Good

**Asset ID:** Bench 13

**Install Date:** Unknown

**Notes:** \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

**Covered/Exposed:** \_\_\_\_\_

**Inspection/Review Date:** \_\_\_\_\_

**Johnny Diamond Park Bench 14**



**Location:** Johnny Diamond Park north side

**Material:** Wood and metal

**Condition (Good/Fair/Poor):** Good

**Asset ID:** Bench 14

**Install Date:** Unknown

**Notes:** \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

**Covered/Exposed:** \_\_\_\_\_

**Inspection/Review Date:** \_\_\_\_\_

**Austin St Swale Bench 15**



**Location:** Austin St near Loop Path  
**Material:** Wood and metal  
**Condition (Good/Fair/Poor):** Good  
**Asset ID:** Bench 15  
**Install Date:** Unknown  
**Notes:** \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
**Covered/Exposed:** \_\_\_\_\_  
**Inspection/Review Date:** \_\_\_\_\_

**Booth Kelly Path North End Bench 16**



**Location:** Booth Kelly Path north end of path  
**Material:** Wood and metal  
**Condition (Good/Fair/Poor):** Poor  
**Asset ID:** Bench 16  
**Install Date:** Unknown  
**Notes:** \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
**Covered/Exposed:** \_\_\_\_\_  
**Inspection/Review Date:** \_\_\_\_\_

**Booth Kelly Path Middle Bench 17**



**Location:** Booth Kelly Path middle

**Material:** Wood and metal

**Condition (Good/Fair/Poor):** Poor

**Asset ID:** Bench 17

**Install Date:** Unknown

**Notes:** \_\_\_\_\_

**Covered/Exposed:** \_\_\_\_\_

**Inspection/Review Date:** \_\_\_\_\_

**Booth Kelly Path South End Bench 18**



**Location:** Booth Kelly Path South end

**Material:** Wood and metal

**Condition (Good/Fair/Poor):** Poor

**Asset ID:** Bench 18

**Install Date:** Unknown

**Notes:** \_\_\_\_\_

**Covered/Exposed:** \_\_\_\_\_

**Inspection/Review Date:** \_\_\_\_\_

**Coburg Commons Bench 19**



**Location:** Van Duyn and Willamette near Coburg Commons

**Material:** Metal

**Condition (Good/Fair/Poor):** Good

**Asset ID:** Bench 19

**Install Date:** Unknown

**Notes:** \_\_\_\_\_


\_\_\_\_\_

\_\_\_\_\_

**Covered/Exposed:** \_\_\_\_\_

**Inspection/Review Date:** \_\_\_\_\_

**Locust and Willamette Bench 20**



**Location:** Locust and Willamette near Dari Mart

**Material:** Wood and metal

**Condition (Good/Fair/Poor):** Fair

**Asset ID:** Bench 20

**Install Date:** Unknown

**Notes:** \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

**Covered/Exposed:** \_\_\_\_\_

**Inspection/Review Date:** \_\_\_\_\_

**N Industrial Loop Path Bench 21**



**Location:** N Industrial Loop Path

**Material:** Wood and Metal

**Condition (Good/Fair/Poor):** Fair

**Asset ID:** Bench 21

**Install Date:** Unknown

**Notes:** \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

**Covered/Exposed:** \_\_\_\_\_

**Inspection/Review Date:** \_\_\_\_\_

**Trails End Park Bench 22**



**Location:** Trails End Park

**Material:** Wood and Metal

**Condition (Good/Fair/Poor):** Fair

**Asset ID:** Bench 22

**Install Date:** Unknown

**Notes:** \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

**Covered/Exposed:** \_\_\_\_\_

**Inspection/Review Date:** \_\_\_\_\_

**Trails End Park Bench 23**




**Location:** Trails End Park  
**Material:** Wood and Metal  
**Condition (Good/Fair/Poor):** Fair  
**Asset ID:** Bench 23  
**Install Date:** Unknown  
**Notes:** \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
**Covered/Exposed:** \_\_\_\_\_  
**Inspection/Review Date:** \_\_\_\_\_

**Item 24: [Enter Title Here]**



**Location:**  
**Material:**  
**Condition (Good/Fair/Poor):**  
**Asset ID:** Bench  
**Install Date:**  
**Notes:** \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
**Covered/Exposed:** \_\_\_\_\_  
**Inspection/Review Date:** \_\_\_\_\_

**Item 25: [Enter Title Here]**



**Location:**

**Material:**

**Condition (Good/Fair/Poor):**

**Asset ID:** Bench


**Install Date:**

**Notes:** \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

**Covered/Exposed:** \_\_\_\_\_

**Inspection/Review Date:** \_\_\_\_\_

**Item 26: [Enter Title Here]**



**Location:**

**Material:**

**Condition (Good/Fair/Poor):**

**Asset ID:** Bench

**Install Date:**

**Notes:** \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

**Covered/Exposed:** \_\_\_\_\_

**Inspection/Review Date:** \_\_\_\_\_