



Appraiser Report

Administrative

1/26/2024

Please click on all that apply(mandatory):

Owner Name: CITY OF CRESTWILL

Total Loss ☐

Repairable ☒

Border ☐

UPD ☐

Claim# 24300K996844

Excellent ☐

Average ☒

Good ☐

Fair ☐

Appraiser: M PERRY

Drivable ☐

Inoperable ☐

Tow ☒

Storage ☐

Est/Suppl \$ \$ 16,522.26

Field ☒

Deskwrite ☐

DOI ☐

Quality ☐

Damage Description L SIDE

Vehicle Description POLICE CAR

Estimates

Body Shop

Shop Address:

Shop Telephone:

Supplement N/A

Days for Repair

Unrelated Prior Dmg.

Reserve/Open Items

Shop Est. Amount

Prevailing Shop Rates

Estimate Threshold 0.0

Shop Agreed price No

Quality Re-inspection

Please click on all that apply

Fire Loss

Total Burn ☐

Evidence of Flame ☐

Extinguish Attempt ☐

Recent Work on vehicle ☐

Hot Spot Area

Suspected Cause

Please click on all that apply

Flood Loss Water

Type Veh. Salt ☐

Brackish ☐

Fresh ☐

Sewage ☐

Other ☐

Structure Alum. ☐

Steel ☐

Fiberglass ☐

Composite ☐

Wood ☐

Water Level Roof ☐

Over Dash ☐

Under Dash ☐

Floor ☐

Rocker ☐

Mitigation Fans ☐

R/I Seats ☐

R/I Carpets ☐

Oil Change ☐

Trans ☐

Mold Intrusion E_W ☐

H_dTW ☐

Heavy ☐

Moderate ☐

Light ☐

Water Mark <1' ☐

1' - 2' ☐

2' - 3' ☐

3' - 4' ☐

>5' ☐

Days In Water <1 day ☐

1-2 Days ☐

3-4 Days ☐

4-5 Days ☐

>5 Days ☐

Oxidation Mild ☐

Moderate ☐

Heavy ☐

Severe ☐

None Seen ☐

Narrative *(required)*

Seen at lot. Damage to right rear. Approx 10-12 days to repair. Wrap open per invoice.