

Julius Hansen

From: Chad Johnson <chad.johnson@usgwater.com>
Sent: Thursday, March 6, 2025 12:48 PM
To: Julius Hansen
Subject: Filter 12

External Sender: Use caution with links and attachments. Use caution when replying. If you are unsure please contact IT.

Julius,

While working on well, 12, we have discovered that more repairs are needed than we initially thought this could be attributed to the age of the filter and lack of maintenance previously. We are experiencing some metal thickness issues and the tank is leaking more than expected when we go to test it. Basically as we try to weld the leaks closed more leaks appear. So, we are chasing a little at the moment. We will need to request some change orders because this extra work goes beyond scope of work in the contact and we are finding more issues with the tank as we go along.

We can make a site visit tomorrow to go over this in more detail and decide on the option for the plan forward.

Thank you

Chad

Chad Johnson

Water System Consultant
USG Water Solutions

Cell
(630) 280-5620



USG WATER
— SOLUTIONS —