Demolition Properties

Presented by: Code Enforcement Officer II Tiffany Stewart

Request to set Hearing Date




219 5th Street East





219 5th Street East

- Unfit for Human Occupancy & Dangerous Building 3/24/24
- Demolition request 7/25/24
- Documentation going back to 2001
- No potable water since 2018
- Interior inspection completed 10/11/24
- Outstanding code violations
 - Junk, abandoned vehicles
- Building & Codes recommends the structures be demolished





22 S 10th Avenue West





22 S 10th Avenue West

- Dangerous building 8/24/21
- Demolition request 6/13/22
- Interior inspection completed 8/28/24
- Interior & exterior dilapidation
- No potable water
- Abandoned for period far exceeding 6 months
- Building & Codes recommends structures be demolished

