





Kitchen Window before



Kitchen Window after




Front door sto before



Front door stop after




W. Parlor Window before




W. Parlor Window after

Siding being prepped for
epoxy

Siding finished





Sample of products used



Contractor at work on
the West side of the
building

Detailed picture of work
done

Contractor at work on
the West side of the
building

