



**NOTES**

1. 2016 THROUGH 2022 SHORELINE AND TOP OF BANKS ARE BASED ON FIELD SURVEYS PERFORMED BY EDGE SURVEY AND DESIGN, LLC.
2. 2012 TOP OF BANKS ARE BASED ON AN ORTHOPHOTO PROVIDED BY THE CITY OF DILLINGHAM.
3. 2010 TOP OF BANKS ARE BASED ON AN ORTHOPHOTO PROVIDED BY MICROSOFT BING.
4. 2000, 1996, AND 1962 TOP OF BANKS ARE BASED ON AERIAL PHOTOS PROVIDED BY THE CITY OF DILLINGHAM. THESE PHOTOS WERE NOT CORRECTED FOR CAMERA AND TERRAIN DISTORTIONS AND ARE APPROXIMATE.
5. 1942 SHORELINE BASED ON USGS QUADRANGLE SHEET "DILLINGHAM A-7" DATED 1952. THIS MAP NOTES THAT AERIAL PHOTOGRAPHS WERE TAKEN IN 1942.
6. INLAND BANKS ARE BASED ON 2012 AERIAL PHOTO AND ARE APPROXIMATE.
7. BASED ON THE DATA FROM 1942 THROUGH 2022 THE SHORELINE HAS ERODED 930 FEET OR 11.6 FEET PER YEAR.

**LEGEND**

- 2020 TOP BANK - SURVEY / PHOTO
- 2019 TOP BANK - SURVEY / PHOTO
- 2018 TOP BANK - SURVEY / PHOTO
- 2017 TOP BANK - SURVEY
- 2016 TOP BANK - SURVEY
- - - 2012 TOP BANK - PHOTO
- - - 2010 TOP BANK - PHOTO
- - - 2000 TOP BANK - PHOTO
- - - 1996 TOP BANK - PHOTO
- - - 1962 TOP BANK - PHOTO
- - - 1942 SHORELINE - QUAD MAP
- - - INLAND BANK - 2012
- 2022 TOP BANK - SURVEY / PHOTO
- 2021 TOP BANK - SURVEY / PHOTO





8000 KING STREET ANCHORAGE, AK 99518  
Phone (907) 344-5990 Fax (907) 344-7794

**DILLINGHAM SHORELINE  
EROSION ANALYSIS**

DRAWN BY: SM	DATE: 11/18/2022	JOB NUMBER: 16-134
CHECKED BY: MA	SCALE: 1" = 200'	SHEET: 1 OF 1