Meter Reads Driftwood Golf & Ranch Completed	Work Order #	Title	WO Status
00664 FMP Pool weedeating Completed 00665 Spray Weeds and Weed Whack at Adult Softball Field Completed 00666 Clean WWTP and weirs Completed 00667 Remove Tree Limbs Completed 00668 Mow Caliterra Lift Station Completed 00669 Clean Trucks Completed 00670 Weeds. Swrf Completed 00671 Mercer weeds Completed 00672 City hall bulbs Completed 00673 Electrical panel city hall Completed 00674 Landscaping - VMP Completed 00675 SRP. Mulch piles Completed 00676 Clean Office and Restroom Completed 00677 SRP trash Completed 00678 Trang Writterooard on wall benind door Completed 00679 Landscaping - Stephenson Building Completed 00680 Landscaping - City Hall Completed 00681 Mount Server Rack with plywood backing to East off Completed 00682 Pressure washer		Meter Reads Driftwood Golf & Ranch	Completed
00666 Clean WWTP and weirs Completed 00667 Remove Tree Limbs Completed 00668 Mow Caliterra Lift Station Completed 00669 Clean Trucks Completed 00670 Weeds. Swrf Completed 00671 Mercer weeds Completed 00672 City hall bulbs Completed 00673 Electrical panel city hall Completed 00674 Landscaping - VMP Completed 00675 SRP. Mulch piles Completed 00676 Clean Office and Restroom Completed 00677 SRP trash Completed 00678 Transprantenoration wair perimination Completed 00679 Landscaping - Stephenson Building Completed 00680 Landscaping - City Hall Completed 00681 Mount Server Rack with plywood backing to East off Completed 00682 Pressure washer at the Regional Treatment Facility Completed 00683 Pool lifeguard umbrella Completed 00684 Founders, wa	0664	FMP Pool weedeating	·
D0667 Remove Tree Limbs Completed	0665	Spray Weeds and Weed Whack at Adult Softball Field	Completed
00668 Mow Caliterra Lift Station Completed 00669 Clean Trucks Completed 00670 Weeds. Swrf Completed 00671 Mercer weeds Completed 00672 City hall bulbs Completed 00673 Electrical panel city hall Completed 00674 Landscaping - VMP Completed 00675 SRP. Mulch piles Completed 00676 Clean Office and Restroom Completed 00677 SRP trash Completed 00678 Trang vyrinepoard on wair perintal door Completed 00679 Landscaping - Stephenson Building Completed 00680 Landscaping - City Hall Completed 00681 Mount Server Rack with plywood backing to East off Completed 00682 Pressure washer at the Regional Treatment Facility Completed 00683 Pool lifeguard umbrella Completed 00684 Founders, water leak repair cover Completed 00685 Founders, water leak repair cover Completed 00686 Ex mark lawnmower Completed 00687<	0666	Clean WWTP and weirs	Completed
00669 Clean Trucks Completed 00670 Weeds. Swrf Completed 00671 Mercer weeds Completed 00672 City hall bulbs Completed 00673 Electrical panel city hall Completed 00674 Landscaping - VMP Completed 00675 SRP. Mulch piles Completed 00676 Clean Office and Restroom Completed 00677 SRP trash Completed 00678 Pandy vyrineboard on wair bening door Completed 00679 Landscaping - Stephenson Building Completed 00680 Landscaping - City Hall Completed 00681 Mount Server Rack with plywood backing to East off Completed 00682 Pressure washer at the Regional Treatment Facility Completed 00683 Pool lifeguard umbrella Completed 00684 Founders, water leak repair cover Completed 00685 Founders, water leak repair cover Completed 00686 Ex mark lawnmower Completed 00687 Spray Boxes at Arrowhead Completed 00688	0667	Remove Tree Limbs	Completed
00670 Weeds. Swrf Completed 00671 Mercer weeds Completed 00672 City hall bulbs Completed 00673 Electrical panel city hall Completed 00674 Landscaping - VMP Completed 00675 SRP. Mulch piles Completed 00676 Clean Office and Restroom Completed 00677 SRP trash Completed 00678 Diang venice Dealer on wair Denino door Completed 00679 Landscaping - Stephenson Building Completed 00680 Landscaping - City Hall Completed 00681 Mount Server Rack with plywood backing to East off Completed 00682 Pressure washer at the Regional Treatment Facility Completed 00683 Pool lifeguard umbrella Completed 00684 Founders, water leak repair cover Completed 00685 Founders pool Completed 00686 Ex mark lawnmower Completed 00687 Spray Boxes at Arrowhead Completed 00688 Set Meter 850 Thurman Roberts Void 00689 Landscaping - Rob Shelton medians Completed 00691 Broken Door Handle - Front Office @ Pool Completed 00692 DSRP has a severe pest issue. In Progress 00694 AD001 Registration	0668	Mow Caliterra Lift Station	Completed
00671Mercer weedsCompleted00672City hall bulbsCompleted00673Electrical panel city hallCompleted00674Landscaping - VMPCompleted00675SRP. Mulch pilesCompleted00676Clean Office and RestroomCompleted00677SRP trashCompleted00678Frang vyrinterboard on wall berlind doorCompleted00679Landscaping - Stephenson BuildingCompleted00680Landscaping - City HallCompleted00681Mount Server Rack with plywood backing to East offCompleted00682Pressure washer at the Regional Treatment FacilityCompleted00683Pool lifeguard umbrellaCompleted00684Founders, water leak repair coverCompleted00685Founders poolCompleted00686Ex mark lawnmowerCompleted00687Spray Boxes at ArrowheadCompleted00688Set Meter 850 Thurman RobertsVoid00690Exercise Transfer SwitchesCompleted00691Broken Door Handle - Front Office @ PoolCompleted00692DSRP has a severe pest issue.In Progress00694AD001 RegistrationCompleted	0669	Clean Trucks	Completed
City hall bulbs Completed 00673 Electrical panel city hall Completed 00674 Landscaping - VMP Completed 00675 SRP. Mulch piles Completed 00676 Clean Office and Restroom Completed 00677 SRP trash Completed 00678 Clean Office and Restroom Completed 00679 Landscaping - Stephenson Building Completed 00680 Landscaping - City Hall Completed 00681 Mount Server Rack with plywood backing to East off Completed 00682 Pressure washer at the Regional Treatment Facility Completed 00683 Pool lifeguard umbrella Completed 00684 Founders, water leak repair cover Completed 00685 Founders pool Completed 00686 Ex mark lawnmower Completed 00687 Spray Boxes at Arrowhead Completed 00688 Set Meter 850 Thurman Roberts Void 00690 Landscaping - Rob Shelton medians Completed 00691 Broken Door Handle - Front Office @ Pool Completed 00692 DSRP has a severe pest issue. In Progress 00694 AD001 Registration Completed	0670	Weeds. Swrf	Completed
D0673 Electrical panel city hall Completed	0671	Mercer weeds	Completed
00674Landscaping - VMPCompleted00675SRP. Mulch pilesCompleted00676Clean Office and RestroomCompleted00677SRP trashCompleted00678Pang vyniteboard on wair benind doorCompleted00679Landscaping - Stephenson BuildingCompleted00680Landscaping - City HallCompleted00681Mount Server Rack with plywood backing to East offCompleted00682Pressure washer at the Regional Treatment FacilityCompleted00683Pool lifeguard umbrellaCompleted00684Founders, water leak repair coverCompleted00685Founders poolCompleted00686Ex mark lawnmowerCompleted00687Spray Boxes at ArrowheadCompleted00688Set Meter 850 Thurman RobertsVoid00689Landscaping - Rob Shelton mediansCompleted00690Exercise Transfer SwitchesCompleted00691Broken Door Handle - Front Office @ PoolCompleted00692DSRP has a severe pest issue.In Progress00694AD001 RegistrationCompleted	0672	City hall bulbs	Completed
O0675 SRP. Mulch piles Completed O0676 Clean Office and Restroom Completed O0677 SRP trash Completed O0678 Parity Writterboard on wall benind door Completed O0679 Landscaping - Stephenson Building Completed O0680 Landscaping - City Hall Completed O0681 Mount Server Rack with plywood backing to East off Completed O0682 Pressure washer at the Regional Treatment Facility Completed O0683 Pool lifeguard umbrella Completed O0684 Founders, water leak repair cover Completed O0685 Founders pool Completed O0686 Ex mark lawnmower Completed O0687 Spray Boxes at Arrowhead Completed O0688 Set Meter 850 Thurman Roberts Void O0689 Landscaping - Rob Shelton medians Completed O0690 Exercise Transfer Switches Completed O0691 Broken Door Handle - Front Office @ Pool Completed O0692 DSRP has a severe pest issue. In Progress	0673	Electrical panel city hall	Completed
00676Clean Office and RestroomCompleted00677SRP trashCompleted00678Completed00679Landscaping - Stephenson BuildingCompleted00680Landscaping - City HallCompleted00681Mount Server Rack with plywood backing to East offCompleted00682Pressure washer at the Regional Treatment FacilityCompleted00683Pool lifeguard umbrellaCompleted00684Founders, water leak repair coverCompleted00685Founders poolCompleted00686Ex mark lawnmowerCompleted00687Spray Boxes at ArrowheadCompleted00688Set Meter 850 Thurman RobertsVoid00699Landscaping - Rob Shelton mediansCompleted00690Exercise Transfer SwitchesCompleted00691Broken Door Handle - Front Office @ PoolCompleted00692DSRP has a severe pest issue.In Progress00694AD001 RegistrationCompleted	0674	Landscaping - VMP	Completed
00677SRP trashCompleted00678Planty Virille Doard on Wall Denim GoodCompleted00679Landscaping - Stephenson BuildingCompleted00680Landscaping - City HallCompleted00681Mount Server Rack with plywood backing to East offCompleted00682Pressure washer at the Regional Treatment FacilityCompleted00683Pool lifeguard umbrellaCompleted00684Founders, water leak repair coverCompleted00685Founders poolCompleted00686Ex mark lawnmowerCompleted00687Spray Boxes at ArrowheadCompleted00688Set Meter 850 Thurman RobertsVoid00689Landscaping - Rob Shelton mediansCompleted00690Exercise Transfer SwitchesCompleted00691Broken Door Handle - Front Office @ PoolCompleted00692DSRP has a severe pest issue.In Progress00694AD001 RegistrationCompleted	0675	SRP. Mulch piles	Completed
00678 Completed 00679 Landscaping - Stephenson Building Completed 00680 Landscaping - City Hall Completed 00681 Mount Server Rack with plywood backing to East off Completed 00682 Pressure washer at the Regional Treatment Facility Completed 00683 Pool lifeguard umbrella Completed 00684 Founders, water leak repair cover Completed 00685 Founders pool Completed 00686 Ex mark lawnmower Completed 00687 Spray Boxes at Arrowhead Completed 00688 Set Meter 850 Thurman Roberts Void 00689 Landscaping - Rob Shelton medians Completed 00690 Exercise Transfer Switches Completed 00691 Broken Door Handle - Front Office @ Pool Completed 00692 DSRP has a severe pest issue. In Progress 00694 AD001 Registration Completed	0676	Clean Office and Restroom	Completed
00679 Landscaping - Stephenson Building Completed 00680 Landscaping - City Hall Completed 00681 Mount Server Rack with plywood backing to East off Completed 00682 Pressure washer at the Regional Treatment Facility Completed 00683 Pool lifeguard umbrella Completed 00684 Founders, water leak repair cover Completed 00685 Founders pool Completed 00686 Ex mark lawnmower Completed 00687 Spray Boxes at Arrowhead Completed 00688 Set Meter 850 Thurman Roberts Void 00689 Landscaping - Rob Shelton medians Completed 00690 Exercise Transfer Switches Completed 00691 Broken Door Handle - Front Office @ Pool Completed 00692 DSRP has a severe pest issue. In Progress 00694 AD001 Registration Completed	0677		Completed
00680Landscaping - City HallCompleted00681Mount Server Rack with plywood backing to East offCompleted00682Pressure washer at the Regional Treatment FacilityCompleted00683Pool lifeguard umbrellaCompleted00684Founders, water leak repair coverCompleted00685Founders poolCompleted00686Ex mark lawnmowerCompleted00687Spray Boxes at ArrowheadCompleted00688Set Meter 850 Thurman RobertsVoid00689Landscaping - Rob Shelton mediansCompleted00690Exercise Transfer SwitchesCompleted00691Broken Door Handle - Front Office @ PoolCompleted00692DSRP has a severe pest issue.In Progress00694AD001 RegistrationCompleted	0678	mang whiteboard on wall benind door	Completed
00680Landscaping - City HallCompleted00681Mount Server Rack with plywood backing to East offCompleted00682Pressure washer at the Regional Treatment FacilityCompleted00683Pool lifeguard umbrellaCompleted00684Founders, water leak repair coverCompleted00685Founders poolCompleted00686Ex mark lawnmowerCompleted00687Spray Boxes at ArrowheadCompleted00688Set Meter 850 Thurman RobertsVoid00689Landscaping - Rob Shelton mediansCompleted00690Exercise Transfer SwitchesCompleted00691Broken Door Handle - Front Office @ PoolCompleted00692DSRP has a severe pest issue.In Progress00694AD001 RegistrationCompleted	0679	Landscaping - Stephenson Building	Completed
00682Pressure washer at the Regional Treatment FacilityCompleted00683Pool lifeguard umbrellaCompleted00684Founders, water leak repair coverCompleted00685Founders poolCompleted00686Ex mark lawnmowerCompleted00687Spray Boxes at ArrowheadCompleted00688Set Meter 850 Thurman RobertsVoid00689Landscaping - Rob Shelton mediansCompleted00690Exercise Transfer SwitchesCompleted00691Broken Door Handle - Front Office @ PoolCompleted00692DSRP has a severe pest issue.In Progress00694AD001 RegistrationCompleted	0680		Completed
00683Pool lifeguard umbrellaCompleted00684Founders, water leak repair coverCompleted00685Founders poolCompleted00686Ex mark lawnmowerCompleted00687Spray Boxes at ArrowheadCompleted00688Set Meter 850 Thurman RobertsVoid00689Landscaping - Rob Shelton mediansCompleted00690Exercise Transfer SwitchesCompleted00691Broken Door Handle - Front Office @ PoolCompleted00692DSRP has a severe pest issue.In Progress00694AD001 RegistrationCompleted	0681	Mount Server Rack with plywood backing to East off	Completed
00684Founders, water leak repair coverCompleted00685Founders poolCompleted00686Ex mark lawnmowerCompleted00687Spray Boxes at ArrowheadCompleted00688Set Meter 850 Thurman RobertsVoid00689Landscaping - Rob Shelton mediansCompleted00690Exercise Transfer SwitchesCompleted00691Broken Door Handle - Front Office @ PoolCompleted00692DSRP has a severe pest issue.In Progress00694AD001 RegistrationCompleted	0682	Pressure washer at the Regional Treatment Facility	Completed
00685Founders poolCompleted00686Ex mark lawnmowerCompleted00687Spray Boxes at ArrowheadCompleted00688Set Meter 850 Thurman RobertsVoid00689Landscaping - Rob Shelton mediansCompleted00690Exercise Transfer SwitchesCompleted00691Broken Door Handle - Front Office @ PoolCompleted00692DSRP has a severe pest issue.In Progress00694AD001 RegistrationCompleted	0683	Pool lifeguard umbrella	Completed
00686Ex mark lawnmowerCompleted00687Spray Boxes at ArrowheadCompleted00688Set Meter 850 Thurman RobertsVoid00689Landscaping - Rob Shelton mediansCompleted00690Exercise Transfer SwitchesCompleted00691Broken Door Handle - Front Office @ PoolCompleted00692DSRP has a severe pest issue.In Progress00694AD001 RegistrationCompleted	0684	Founders, water leak repair cover	Completed
00687Spray Boxes at ArrowheadCompleted00688Set Meter 850 Thurman RobertsVoid00689Landscaping - Rob Shelton mediansCompleted00690Exercise Transfer SwitchesCompleted00691Broken Door Handle - Front Office @ PoolCompleted00692DSRP has a severe pest issue.In Progress00694AD001 RegistrationCompleted	0685	Founders pool	Completed
00688Set Meter 850 Thurman RobertsVoid00689Landscaping - Rob Shelton mediansCompleted00690Exercise Transfer SwitchesCompleted00691Broken Door Handle - Front Office @ PoolCompleted00692DSRP has a severe pest issue.In Progress00694AD001 RegistrationCompleted	0686	Ex mark lawnmower	Completed
00689Landscaping - Rob Shelton mediansCompleted00690Exercise Transfer SwitchesCompleted00691Broken Door Handle - Front Office @ PoolCompleted00692DSRP has a severe pest issue.In Progress00694AD001 RegistrationCompleted	0687	Spray Boxes at Arrowhead	Completed
00690Exercise Transfer SwitchesCompleted00691Broken Door Handle - Front Office @ PoolCompleted00692DSRP has a severe pest issue.In Progress00694AD001 RegistrationCompleted	0688	Set Meter 850 Thurman Roberts	Void
00691Broken Door Handle - Front Office @ PoolCompleted00692DSRP has a severe pest issue.In Progress00694AD001 RegistrationCompleted	0689	Landscaping - Rob Shelton medians	Completed
00692DSRP has a severe pest issue.In Progress00694AD001 RegistrationCompleted	0690	Exercise Transfer Switches	Completed
00694 AD001 Registration Completed	0691	Broken Door Handle - Front Office @ Pool	Completed
	0692	DSRP has a severe pest issue.	In Progress
	0694	AD001 Registration	Completed
00695 FMP Trail landscaping Maint. Completed	0695	FMP Trail landscaping Maint.	Completed
00696 Kubota mower cods Completed	0696	Kubota mower cods	Completed
00697 Landscaping - Roger Hanks Completed	0697	Landscaping - Roger Hanks	Completed
00698 Pool , breaker trips Completed	0698	Pool , breaker trips	Completed
00699 The spigot at the outdoor arena is leaking, looks Completed	0699	The spigot at the outdoor arena is leaking, looks	Completed
00700 Sportsplex Message board set up In Progress	0700	Sportsplex Message board set up	In Progress
00701 Message board set up - Burn ban Completed	0701	Message board set up - Burn ban	Completed
00702 Please relocate Server Rack to adjacent closet and Completed	0702	•	Completed
00703 A/C in the lifeguard office is not blowing cool ai Completed			
00704 Wasp SRP Completed	0704		
00705 Zone 5 Arrowhead Drip Field Repair Completed		·	
00706 Supervise LS Cleaning 6,7,AH,SRWTF Completed	0706	· · ·	·

00707	Grease Pumps, Filter and Mini Skid Steer at SRWTF	Completed
00708	City hall	Completed
00709	City hall light bulbs	Completed
00710	Headlight md 003	Completed
00711	Move and Anchor Pole by Field	Completed
00712	WW-Kubota-Mower-72_1 PM's	New Work Order
00713	PW-Bobcat-MT85 100hr PM's	Completed
00714	MD006 brakes squealing	Completed
00715	Drip Field Weeds, Trash and Branches	Void
00716	Drip Field House Keeping	Completed
00717	Replace Bulbs in Barn @WWTP	Completed
00718	Ranch House Chlorine Tablets	Completed
00719	Weeds waste water	Completed
00720	Speedy bleachers	Completed
00721	Weedeat around Pool Fence	Completed
00722	Install Emergency Shut Off sign. Sign needs to be	Completed
00723	AD001 - Rotate Tires	Completed
00724	TEST PM SCHEDULE	Void
00725	MD002-7500-Oil Change and Filter	On Hold
00726	PW004 - Oil Change	Completed
00727	Please fix the volleyball net at the sand court.	Completed
00728	Spray and remove weeds and stickers around the san	Completed
00729	Weed eat yellow bell st.	Completed
00730	Drip Field Weeds, Trash and Branches	Void
00731	Sanding and repainting the display units	In Progress
00732	Can you replace the filters here? Not sure of size	Completed
00733	PW004-20000-Replace Cabin Air Filter	Completed
00734	AC drain leaking again in hallway; different locat	Completed
00735	Grease Blowers and Non Pot Pumps at AH Ranch	Completed
00736	Carcass	Completed
00737	Center the shut off switch sign that was installed	Completed
00738	There is a sprinkler box with a big hole in the to	Completed
00739	SRP glass in parking lot	Completed
00740	Install Reflective Tape on structure at SRWTF	Completed
00741	Clean Drip Skid filters at Arrowhead Ranch	Completed
00742	Broken branch VMP	Completed
00743	Repair 3" return line in field 32 at SRWTF	Completed
00744	WW Ferris 3200Z-50hr PM	New Work Order
00745	WW Ferris 3200Z-100hr PM	New Work Order
00746	WW Kubota Mower 72_1-F100hr PM	New Work Order
00747	WW Kubota Mower 72_1-50hr PM	New Work Order
00748	WW Kubota Mower 72 1-100hr PM	New Work Order
00749	WW Kubota Mower 72_1-150hr PM	New Work Order
00750	WW Kubota Mower 72_1-200hr PM	New Work Order
00751	PW Bobcat S450-10hr PM	Completed
00751	PW Bobcat S450-50hr PM	Completed
50, <u>52</u>	. Tr Dobout O 100 Joill 1 W	Completed

00754	Clean VFD panel s and filters at SRWTF	Completed
00755	Sheetrock	Completed
00756	City hall Sheetrock	Completed
00757	TEST PM MD004	Void
00758	Pump Room door handle broken - It appears to be lo	Completed
00759	Auto Dialer Inputs	New Work Order
00760	Landscaping - Rob Shelton Medians	Completed
00761	MD 002. DEF	Completed
00762	VMP electric box	Completed
00763	PW004-Oil Change	New Work Order
00764	Vac Lift Stations and Plant	Completed
00765	VMP - Farmers Market Banner	Completed

Maintenance and Facilities Work Order Report

July-23

	July-23)	
Priority	Origin	Source Asset	Source User
Critical - ASAP	Non-PM		Anthony Pennell
Medium - 3-7 days	Non-PM		John Hill
Medium - 3-7 days	Non-PM		Robert Hutson
High - 1-3 days	Non-PM		Cameron Queen
High - 1-3 days	Non-PM		Cameron Queen
High - 1-3 days	Non-PM		Cameron Queen
Medium - 3-7 days	Non-PM	PW001 - 2019 Ford F-150 - 9837	Anthony Pennell
Medium - 3-7 days	Non-PM		Manny Espinosa
Medium - 3-7 days	Non-PM		Manny Espinosa
Medium - 3-7 days	Non-PM		Sonny Garza
Medium - 3-7 days	Non-PM		Robert Hutson
Medium - 3-7 days	Non-PM		John Hill
Medium - 3-7 days	Non-PM		Andrew Thompson
High - 1-3 days	Non-PM		Cameron Queen
Medium - 3-7 days	Non-PM		Manny Espinosa
Low - 7-15 days	Non-PM		John Hill
Medium - 3-7 days	Non-PM		John Hill
Medium - 3-7 days	Non-PM		John Hill
Medium - 3-7 days	Non-PM		Andrew Thompson
Medium - 3-7 days	Non-PM	WW-Kohler Prsr Wshr-9564	Sonny Garza
Medium - 3-7 days	Non-PM		Robert Hutson
Medium - 3-7 days	Non-PM		John Hill
Medium - 3-7 days	Non-PM		Andrew Thompson
Medium - 3-7 days	Non-PM	PW-Exmark LzrZ-2840	Sonny Garza
Medium - 3-7 days	Non-PM		Cameron Queen
High - 1-3 days	Non-PM		Cameron Queen
Medium - 3-7 days	Non-PM		John Hill
High - 1-3 days	Non-PM		Cameron Queen
High - 1-3 days	Non-PM		Andrew Thompson
Medium - 3-7 days	Non-PM		Manny Espinosa
Spare Time	Non-PM	AD001 - 2014 Chevy Spark - 4197	Craig Rice
Medium - 3-7 days	Non-PM		John Hill
Medium - 3-7 days	Non-PM	PW-Kubota Mower 60-4766	Sonny Garza
Medium - 3-7 days	Non-PM		John Hill
Medium - 3-7 days	Non-PM		Sonny Garza
Medium - 3-7 days	Non-PM		Robert Hutson
High - 1-3 days	Non-PM		Sonny Garza
Medium - 3-7 days	Non-PM		Sonny Garza
Medium - 3-7 days	Non-PM		Robert Hutson
Critical - ASAP	Non-PM		Sonny Garza
Medium - 3-7 days	Non-PM		Andrew Thompson
Medium - 3-7 days	Non-PM		Anthony Pennell
Medium - 3-7 days	Non-PM		Wacey Henager

Medium - 3-7 days	Non-PM		Cameron Queen
Medium - 3-7 days	Non-PM		Andrew Thompson
Medium - 3-7 days	Non-PM		Andrew Thompson
Critical - ASAP	Non-PM	MD003 - 2019 Ford F-150 - 0865	Andrew Thompson
Medium - 3-7 days	Non-PM	MD003 - 2019 F010 F-130 - 0803	Andrew Thompson
Medium - 3-7 days	Non-PM	WW-Kubota Mower 72-3411	Robert Hutson
	Non-PM	PW-Bobcat MT85-9347	
Medium - 3-7 days	Non-PM	MD006 - 2022 GMC 2500 - 4413	Sonny Garza Robert Hutson
Medium - 3-7 days	114111111	MD006 - 2022 GMC 2500 - 4413	
Medium - 3-7 days	Non-PM		Cameron Queen
Medium - 3-7 days	Non-PM		Cameron Queen
Medium - 3-7 days	Non-PM		Cameron Queen
Low - 7-15 days	Non-PM		Andrew Thompson
Medium - 3-7 days	Non-PM		Andrew Thompson
Medium - 3-7 days	Non-PM	PCS-Speedy Bleacher-0440	Sonny Garza
Medium - 3-7 days	Non-PM		Andrew Thompson
Medium - 3-7 days	Non-PM		Robert Hutson
	PM	AD001 - 2014 Chevy Spark - 4197	Craig Rice
	PM	AD001 - 2014 Chevy Spark - 4197	John Hill
	PM	MD002 - 2018 Ford F-350 - 4183	Craig Rice
	PM	PW004 - 2019 Ford F-150 - XXXX	Sonny Garza
Medium - 3-7 days	Non-PM		Sonny Garza
Medium - 3-7 days	Non-PM		Andrew Thompson
Medium - 3-7 days	Non-PM		Sonny Garza
Medium - 3-7 days	Non-PM		Cameron Queen
Spare Time	Non-PM		Manny Espinosa
Low - 7-15 days	Non-PM		Robert Hutson
Medium - 3-7 days	PM	PW004 - 2019 Ford F-150 - XXXX	Sonny Garza
High - 1-3 days	Non-PM		Sonny Garza
Medium - 3-7 days	Non-PM		Cameron Queen
Critical - ASAP	Non-PM		Sonny Garza
Low - 7-15 days	Non-PM		Robert Hutson
Medium - 3-7 days	Non-PM		John Hill
High - 1-3 days	Non-PM		Andrew Thompson
Medium - 3-7 days	Non-PM		Anthony Pennell
Medium - 3-7 days	Non-PM		Cameron Queen
Medium - 3-7 days	Non-PM		John Hill
Medium - 3-7 days	Non-PM		Gray Lahrman
Medium - 3-7 days	PM	WW-Ferris 3200Z-2634	Robert Hutson
Medium - 3-7 days	PM	WW-Ferris 3200Z-2634	Robert Hutson
Medium - 3-7 days	PM	WW-Kubota Mower 72-3411	Robert Hutson
Medium - 3-7 days	PM	WW-Kubota Mower 72-3411	Robert Hutson
Medium - 3-7 days	PM	WW-Kubota Mower 72-3411	Robert Hutson
Medium - 3-7 days	PM	WW-Kubota Mower 72-3411	Robert Hutson
Medium - 3-7 days	PM	WW-Kubota Mower 72-3411	Robert Hutson
Medium - 3-7 days	PM	PW-Bobcat S450-1796	Sonny Garza
Medium - 3-7 days	PM	PW-Bobcat S450-1796	Sonny Garza
Medium - 3-7 days	PM PM	PW-Bobcat S450-1796	
ivieuiuiii - 3-7 days	LIVI	F vv-DUDCat 343U-1790	Sonny Garza

Medium - 3-7 days	Non-PM		Anthony Pennell
Medium - 3-7 days	Non-PM		Robert Hutson
Medium - 3-7 days	Non-PM		Andrew Thompson
Medium - 3-7 days	PM	MD004 - 2018 Ford F-250 - 9849	John Hill
Critical - ASAP	Non-PM		Sonny Garza
Spare Time	Non-PM		Gray Lahrman
Medium - 3-7 days	Non-PM		John Hill
Medium - 3-7 days	Non-PM	MD002 - 2018 Ford F-350 - 4183	Sonny Garza
Medium - 3-7 days	Non-PM		Sonny Garza
Medium - 3-7 days	PM	PW004 - 2019 Ford F-150 - XXXX	Craig Rice
Medium - 3-7 days	Non-PM		Cameron Queen
Medium - 3-7 days	Non-PM		John Hill

Assigned	Expected
07/03/2023 07:28:00 AM	
07/03/2023 09:24:00 AM	
07/03/2023 09:25:00 AM	
07/03/2023 10:25:00 AM	07/07/2023 04:00:00 PM
07/03/2023 10:28:00 AM	07/05/2023 04:00:00 PM
07/03/2023 10:34:00 AM	07/05/2023 04:00:00 PM
07/03/2023 10:38:00 AM	07/07/2023 04:00:00 PM
07/05/2023 07:49:00 AM	
07/05/2023 10:44:00 AM	
07/05/2023 10:46:00 AM	
07/05/2023 10:57:00 AM	
07/05/2023 11:25:00 AM	
07/05/2023 11:36:00 AM	
07/05/2023 11:36:00 AM	07/07/2023 04:00:00 PM
07/05/2023 11:40:00 AM	
07/06/2023 09:07:00 AM	
07/06/2023 08:59:00 AM	
07/06/2023 03:04:00 PM	
07/07/2023 08:06:00 AM	
07/07/2023 08:07:00 AM	
07/07/2023 11:29:00 AM	
07/07/2023 11:32:00 AM	
07/07/2023 11:39:00 AM	
07/07/2023 11:48:00 AM	
07/07/2023 02:10:00 PM	
07/07/2023 02:12:00 PM	07/10/2023 12:00:00 PM
07/07/2023 02:54:00 PM	
07/10/2023 09:32:00 AM	
07/10/2023 01:58:00 PM	
07/10/2023 03:44:00 PM	
07/10/2023 03:52:00 PM	
07/10/2023 04:07:00 PM	
07/11/2023 01:46:00 PM	
07/11/2023 02:58:00 PM	
07/12/2023 08:11:00 AM	
07/13/2023 08:03:00 AM	
07/12/2023 10:11:00 AM	
07/12/2023 10:16:00 AM	
07/13/2023 08:03:00 AM	
07/13/2023 08:04:00 AM	
07/12/2023 03:14:00 PM	
07/13/2023 07:21:00 AM	
07/13/2023 07:36:00 AM	

07/13/2023 07:40:00 AM	
07/14/2023 07:21:00 AM	
07/14/2023 07:23:00 AM	
07/14/2023 09:36:00 AM	
07/17/2023 10:27:00 AM	07/17/2023 05:00:00 AM
07/17/2023 11:14:00 AM	
07/17/2023 11:22:00 AM	
07/17/2023 02:52:00 PM	
07/18/2023 06:33:00 AM	
07/18/2023 07:32:00 AM	
07/18/2023 07:33:00 AM	
07/18/2023 09:16:00 AM	07/18/2023 05:00:00 AM
07/18/2023 09:19:00 AM	
07/18/2023 09:23:00 AM	
07/18/2023 10:42:00 AM	
07/18/2023 01:10:00 PM	
07/18/2023 01:38:00 PM	07/19/2023 11:59:00 PM
07/18/2023 01:38:00 PM	07/25/2023 11:59:00 PM
07/18/2023 01:41:00 PM	07/25/2023 11:59:00 PM
07/18/2023 01:46:00 PM	07/19/2023 11:59:00 PM
07/18/2023 01:51:00 PM	
07/18/2023 01:52:00 PM	
07/18/2023 03:13:00 PM	
07/18/2023 06:33:00 AM	
07/19/2023 04:00:00 PM	
07/19/2023 03:56:00 PM	
07/19/2023 03:12:00 PM	07/26/2023 11:59:00 PM
07/24/2023 08:44:00 AM	
07/21/2023 07:12:00 AM	
07/24/2023 09:53:00 AM	
07/25/2023 01:53:00 PM	
07/25/2023 02:06:00 PM	
07/24/2023 11:27:00 AM	
07/25/2023 06:44:00 AM	
07/25/2023 06:49:00 AM	
07/25/2023 07:04:00 AM	
07/25/2023 12:41:00 PM	
07/25/2023 02:54:00 PM	08/01/2023 11:59:00 PM
07/25/2023 02:54:00 PM	08/01/2023 11:59:00 PM
07/25/2023 02:55:00 PM	08/01/2023 11:59:00 PM
07/25/2023 02:55:00 PM	08/01/2023 11:59:00 PM
07/25/2023 02:55:00 PM	08/01/2023 11:59:00 PM
07/25/2023 02:55:00 PM	08/01/2023 11:59:00 PM
07/25/2023 02:55:00 PM	08/01/2023 11:59:00 PM
07/25/2023 02:58:00 PM	08/01/2023 11:59:00 PM
07/25/2023 02:58:00 PM	08/01/2023 11:59:00 PM
07/25/2023 02:58:00 PM	08/01/2023 11:59:00 PM
	·

07/26/2023 07:15:00 AM	
07/26/2023 10:55:00 AM	
07/27/2023 07:10:00 AM	
07/27/2023 11:11:00 AM	08/03/2023 11:59:00 PM
07/28/2023 08:36:00 AM	
07/28/2023 07:52:00 AM	
07/28/2023 10:05:00 AM	
07/28/2023 02:12:00 PM	
07/28/2023 02:23:00 PM	
07/31/2023 07:44:00 AM	08/07/2023 11:59:00 PM
07/31/2023 12:20:00 PM	
07/31/2023 03:04:00 PM	
07/31/2023 12:20:00 PM	08/07/2023 11:59:00 PM