

Site Photo Analysis



Daniel  
Scott  
Turner  
Design

Existing Homestead









Daniel  
Scott  
Turner  
Design

Existing Homestead - Contributing Structures





Original House - Tree Canopy





Mid-property grasslands and open space









Lower Third - Preserve Draw





Homestead  
Foundation Analysis




Severe damage to cedar  
piles - full replacement  
and leveling required





# CENTEX FOUNDATION REPAIR SCOPE OF WORK

Work Order No	a124651d	Foundation Type	P&B
Property Address	519 Old Fitzhugh Rd	Inspection Date	09-15-2021
City	Dripping Springs	State Tx	Zip 78620
Cust Name	Miller	Inspector Name	Clint Newman



⊙	Existing Drain Line Clean-Out	↘	Foundation Crack	⊕	Gas Meter	⚡	Electrical Supply Service
---	-------------------------------	---	------------------	---	-----------	---	---------------------------