



All American Pump Solutions,
Inc.
185 CR 350
Dublin TX 76446
United States

Estimate

#1367

2/26/2025

Bill To

EDEN, CITY OF
P O BOX 915
EDEN TX 76837
United States

TOTAL

\$8,446.81

Expires: 3/28/2025

WTP, 3RD PUMP

Expires	Exp. Close	Sales Rep	Partner	Shipping Method
3/28/2025	2/26/2025	Cort Hale		

Quantity	Item	Options	Rate	Amount
20	Labor REGARDING 3RD PUMP FROM THE WATER TREATMENT PLANT. THIS ONE WAS LOCKED UP AND CUSTOMER SAID WOULDN'T RUN. IMPELLER STUCK IN VOLUTE. HAD TROUBLE GETTING VOLUTE & IMPELLER OFF - IMPELLER ALSO STUCK IN BACK PLATE. FOUND CRACKS ON BORE OF IMPELLER AND VERY RUSTY - NEEDS TO BE REPLACED. SEAL PLATE GOOD TO GO AGAIN. CHECKED MOTOR - MEG OK, SCOPE OK. FAN HAS CRACKS ON IT - NEEDS REPLACED. SUGGEST TO CLEAN UP MOTOR, REPLACE BEARINGS & FAN, REASSEMBLE & PAINT. GET PUMP KIT, TRIM IMPELLER TO SIZE AND COAT IMPELLER AND VOLUTE TO TRY TO KEEP RUST TO A MINIMUM. REASSEMBLE TO MOTOR AND PRESSURE TEST & PAINT		\$90.00	\$1,800.00
1	REPAIR PARTS, W/O# 31981 MECHANICAL SEAL, VOLUTE ORING, PUMP IMPELLER KIT, 2 MOTOR BEARINGS, BELZONA EPOXY KIT TO COAT IMPELLER & VOLUTE, ALUMINUM FAN FOR MOTOR AND BORE TO SIZE & CUT KEY & SET SCREWS			\$4,989.81
1	FREIGHT *ESTIMATED* FREIGHT IN FOR MATERIALS NOT IN STOCK		\$150.00	\$150.00
14	Labor *ESTIMATED* TRIP TO INSTALL AND WIRE PUMP, TEST RUN		\$90.00	\$1,260.00
86	MILEAGE - SAN ANGELO MILEAGE CHARGED FROM SAN ANGELO LOCATION		\$2.00	\$172.00
1	MISC *ESTIMATED* 2X VOLUTE GASKETS 2X BOLT KITS IF NEEDED		\$75.00	\$75.00



1367



All American Pump Solutions,
Inc.
185 CR 350
Dublin TX 76446
United States

Estimate

#1367

2/26/2025

Subtotal \$8,446.81

Tax Total (%) \$0.00

Total \$8,446.81



1367