



1802 NORTH 21ST STREET  
 ESCANABA, MI 49829  
 Phone: (906) 233-9100 Fax:  
 www.pcitrucks.com

**SERVICE INVOICE: R111009670:01**

BILL TO:  
 CITY OF GLADSTONE - 20395  
 1100 DELTA AVENUE  
 GLADSTONE MI 49837  
 P: (906) 428-3737  
 F: (906) 428-2599

DELIVER TO  
 CITY OF GLADSTONE - 20395  
 1100 DELTA AVE  
 GLADSTONE MI 49837  
 P: (906) 428-3737  
 F: (906) 428-2599

**This invoice was emailed**

No returns without this invoice. Parts returned after thirty (30) days will be subject to a 15%-20% handling charge. Any special order part which is returned will be subject to a 15%-20% handling charge. Cores must be returned within thirty (30) days for full credit. Core subject to chargeback pending final inspection at core center. Special order "open" kits are not returnable.

DATE PROMISED	DATE INVOICE	SALES TYPE	CUSTOMER REFERENCE	TERMS	ADVISOR			
9/17/2025 1:49:13PM	9/24/2025	SRET		NFT10N	L.Avin			
YEAR	MAKE	MODEL	VIN	CUSTOMER UNIT #	UNIT ID	IN SERVICE	ODOMETER IN	ODOMETER OUT
2021	INTERNATIONAL	HV607	3HAEKTAT4ML488884	30	112467	1/19/2021	0	56022

**Sold Repairs**

**JOB #1 45-000 SRET ENGINE**

**540-560-751.000**

COMPLAINT ENGINE FAULTS

**Trash Truck**

CAUSE BAD DPF AND DPS

CORRECTION The technician conducted a comprehensive health report and collected an image from the engine control module (ECM) to review any faults. After performing after-treatment system tests, it was determined that the diesel particulate filter (DPF) ash load was at 80.3 percent. The ECM calibration was confirmed to be up to date.

Following the installation of a new DPF, additional after-treatment system tests were performed. During a road test, engine faults were detected, prompting further diagnostics. A regeneration process was carried out using a loaner DPF pressure sensor, which resulted in lower pressure readings and no faults during the road test.

Subsequently, a new DPF pressure sensor was installed, and another road test was conducted. The vehicle performed well, with no warnings or faults reported. Overall, the corrective actions taken have ensured the proper functioning of the vehicle's after-treatment system.

QTY	ITEM	VMRS	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	111C:5492073		SENSOR,DPF PRESSURE	185.60	185.60
1	111C:5579370		KIT,PARTICULATE FILTER	3,469.07	3,469.07
	LABOR 43-006-02		REPLACE DPF		450.00
	276 - Hansen, Dennis - M222600				
	LABOR 45-000-10		ENGINE		975.00
	276 - Hansen, Dennis - M222600				

Prepay: 0.00 Parts: 3,654.67 Labor: 1,425.00 Misc: 0 Sublet: 0 **TOTAL JOB #1 45-000 5,079.67**

**JOB #2 43-006 SRET REPLACE DPF**

COMPLAINT REPLACE DPF

CAUSE

CORRECTION

QTY	ITEM	VMRS	DESCRIPTION	UNIT PRICE	EXTD PRICE

Prepay: Parts: Labor: Misc: Sublet: **TOTAL JOB #2 43-006**

**See Final Page for Invoice Total**



1802 NORTH 21ST STREET  
 ESCANABA, MI 49829  
 Phone: (906) 233-9100 Fax:  
 www.pcitrucks.com

**SERVICE INVOICE: R111009670:01**

BILL TO  
 CITY OF GLADSTONE - 20395  
 1100 DELTA AVENUE  
 GLADSTONE MI 49837  
 P: (906) 428-3737  
 F: (906) 428-2599

DELIVER TO  
 CITY OF GLADSTONE - 20395  
 1100 DELTA AVE  
 GLADSTONE MI 49837  
 P: (906) 428-3737  
 F: (906) 428-2599

**This invoice was emailed**

I hereby authorize the repair work hereinafter set forth to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in part shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto. Customer is also liable for all costs of collections, including reasonable attorney's fees.

Customer Signature: \_\_\_\_\_

**PLEASE NOTE**

Invoice terms: Due by the 10th of the month following billing. All past due amounts are subject to a finance charge of 1.5% per month (18% per annum) on all balances thirty (30) or more days past due. Disclaimer of Warranties: The dealer is not a party to any manufacturer's warranty on any parts or service contained within. The dealer hereby expressly disclaims all warranties, express or implied, including any implied warranty of merchantability or fitness for a particular purpose with respect to any parts, labor or diagnostic services furnished under this order.

	ESTIMATED	REMOVED
LABOR		1,425.00
PARTS		3,654.67
MISC		0.00
SUBLET		0.00
<b>SUBTOTAL</b>		<b>\$5,079.67</b>

**CUSTOMER COPY**

\_\_\_\_\_  
 DATE \_\_\_\_\_

\_\_\_\_\_  
 DATE \_\_\_\_\_

\_\_\_\_\_  
 DATE/TIME \_\_\_\_\_

SHOP SUPPLIES	142.50
COUNTY TAX	0.00
STATE TAX	0.00
<b>TOTAL</b>	<b>5,222.17</b>

Please Remit Payment to:  
 UP INTERNATIONAL TRUCKS INC  
 PO BOX 1536  
 GREEN BAY, WI 54305-1536  
 www.pcitrucks.com

CERTIFICATION - Michigan Facility Reg. No F166423. All repairs and parts listed were furnished in compliance with Michigan Auto Repair ACT (P.A. 300)

Per Michigan MCL 257.1334 All repairs have been completed properly. Any unrepaired items have been noted and explained in detail on this invoice. U  
 P International Inc. \_\_\_\_\_

\*\*\*\*\*  
**Remodeling of our Green Bay facility begins in July 2024. Please excuse our dust while we upgrade to serve you better!**

**We will be OPEN during construction!**

Effective January 1, 2025, we will be imposing a 3% credit card processing fee on all credit card purchases. Customers may avoid this fee by paying with check, cash or debit cards. There will not be a processing fee on debit card purchases.