Somervell County Fire Department

Fire Marshal Office 111 Shepard St. Glen Rose, TX 76043



Fire Marshal Office

March 2024 Summary - City of Glen Rose Report

Plan review – 4 hours
Certificate of Occupancy – 6 hours
Annual Inspections – 16 hours
Complaints – 1 hour
Total Hours – 27 hours

Certificate of Occupancy Fire Inspections for the City of Glen Rose

- 1420 NE Big Bend Trail Dollar Tree (Interior Finish Final) In Progress
- 706 Hereford Heights Townhomes In Progress New Owner
- 202 SW Big Bend Trail Heights Apartments In Progress New Owner
- 901 Rio Grande Glen Rose Self Storage In Progress
- 305 NE Barnard St Nivens In Progress
- 1408 NE Big Bend Trail County Garden Café In Progress
- 200 E. Elm St Suite G The Shop In Progress
- 106 Cedar Old Jail In Progress
- 505 SW Big Bend Trail Rivera Chinese Food In Progress
- 700 NE Big Bend Trail Sheppard Cowboy Church In Progress
- 1613 NE Big Bend Trail Suite C Dr. Office Construction In Progress
- 808 NE Big Bend TGR Healthcare Construction In Progress
- 202 SW Barnard St Longhorn Innovation Construction In Progress
- 1701 Big Bend Trail Dino Carwash- Construction In Progress
- Access Control Gates VRC -In Progress
- Annual Inspection Quality Inn In Progress Knox Box Installed
- Annual Inspection La Quinta In Progress Knox Box Ordered
- Annual Inspection Best Western In Progress Knox Box Installed
- Annual Inspection Texaco Lucky Travel #11 Gas Station In Progress
- Annual Inspection Lucky Travel #12 Gas Station In Progress
- Annual Inspection EZ Mart Gas Station Passed
- Annual Inspection Exxon Travel Plaza Gas Station In Progress
- Annual Inspection Sunoco Gas Station In Progress
- Annual Fire Inspection Paluxy River Apartments In Progress
- Annual GRISD School Inspections 2023 Inspections Completed In Progress

Somervell County Fire Department

Fire Marshal Office 111 Shepard St. Glen Rose, TX 76043



- General Inspection Pie Peddlers In Progress
- General Inspection Shoo-Fly Soda Shop In Progress
- General Inspection Los Primos In Progress
- General Inspection Diversified Energy In Progress Knox Box Installed
- General Inspection Green Pickle In Progress