

HISTORIC RESOURCES SURVEY FORM

1. IdentificationCounty Somervell City Glen Rose (survey site 10)Current name The Botique Historic name Palace Theater/Gresham's Dry Goods StoreAddress 114 Northeast Barnard Street, Glen Rose, Texas 76043Owner/address Tim J. Cecil, PO Box 2430, Glen Rose, Texas 76043Photo data: Roll 1 Frame 27 to Roll 1 Frame 28Current Designations: NR NR District (Is property contributing? Yes No) ☒ RTHL HTC SAL Local OtherRecorded by: Tarleton State University History 509 Class Date recorded: 5 April 2010**General architectural description** Two-story commercial block of modest height adapted in 1940s motion picture studio and faced with artificial stone veneer; facade has three arched fixed windows and a recessed entry.**Outbuildings** (Specify number and type):

Garage _____ Barn _____ Shed _____ Other _____

Archeological evidence of outbuildings, specify Rectangular stone and concrete foundation adjacent to rear of building.**Landscape/site features:**Sidewalks ☒ Terracing _____ Drives _____ Well/cistern _____ Gardens _____ Other _____**2. Architectural Description****Stylistic Influence(s):**

Log Traditional	Shingle	Gothic Revival	Pueblo Revival	International
Greek Revival	Romanesque Revival	Tudor Revival	Spanish Colonial	Post-war Modern
Italianate	Folk Victorian	Neo-Classical	Prairie	Ranch Style
Second Empire	Colonial Revival	Beaux Arts	Craftsman	Com. Style ☒
Eastlake	Renaissance Revival	Mission	Art Deco	No Style
Queen Anne	Exotic Revival	Monterey	Moderne	Other _____

Structural Details:

Roof Type:	Wall Facade:	Windows:	Plan:
Gable Hipped Gambrel Shed Flat w/parapet ☒ Dormers: gable hipped shed Other _____	<u>3</u> Number of bays Stucco Stone Brick Wood shingle Log Terra Cotta Metal Siding, type <u>artificial stone</u> Fieldstone veneer Awning(s) Other _____	Fixed ☒ Wood sash Double hung Casement Aluminum sash Decorative screenwork Other _____	L-plan T-plan Modified L-plan Center passage Bungalow Shotgun Irregular Four Square Rectangular ☒ Other _____
Roof Materials: Wood shingles Tile Composition shingles Metal _____ Other <u>tar</u>	Chimneys: <u>0</u> Specify number(s) Interior Exterior Brick Stone With corbelled caps Stuccoed Other _____	Doors: Single-door primary entrance Double-door primary ent. ☒ With transom ☒ With sidelights Other _____	Foundation: Slab Pier and beam ☒ Perimeter wall ☒ Other _____
Construction: Frame Adobe Solid brick Stone ☒ Other _____		Porches: Shed roof Hipped roof Gable roof Inset Wood posts Brick piers Box columns	Classical columns Tapered box supports Fabricated metal Spindlework Jig-sawn trim Other <u>fabric canopy at entry</u>

Stories: 2 Basement: None ☒ Partial _____ Full _____ Dimensions: L 90 x W 29 = Square feet 2,574 tax records**3. Integrity**Location ☒ Design ☒ Materials ☒ Workmanship ☒ Setting ☒ Feeling ☒ Association ☒

4. Function

Historic Use: Agriculture Commerce/trade ☒ Defense Domestic Educational Government Healthcare
Industry/processing Recreation/culture Religious Social Other _____

Current Use: Agriculture Commerce/trade ☒ Defense Domestic Educational Government Healthcare
Industry/processing Recreation/culture Religious Social Vacant Other _____

5. Architectural History

Architect: _____ Builder: _____

Construction date: ca. 1905 Actual Estimated ☒ Source: Images of America Glen Rose Texas (2002), pp. 19, 21.

Additions/modifications, specify dates: _____

Relocated, specify former location and reason: _____

Other associated contexts and information of interest: _____

6. Archeology Ground

Original state Disturbed ☒ Explain Disturbed from sidewalk construction and placement of underground utilities

Is a State Archeological Survey Form available for this site? Yes No Not known ☒

Details: _____

7. Other Information

Is prior documentation available for this resource? Yes No Not known ☒ **Type:** HABS Survey Other _____

Details: _____

Accessible to the public: Yes ☒ No Not known **Possible threat(s):** None ☒ Damage (i.e. natural disaster) Neglect
Development Major alteration Relocation Other _____ * **Note:** Also see Endangered Historic Property Identification Form

8. Geographic Information

USGS quad #: 96599 Year: 1979 Map scale: 1:24,000

UTM zone: 14 Easting: 617304 Northing: 3567163

Legal description (Lot/Block): Glen Rose Townsite, block 5, lot SW 2' of lot 1, all of lot 2

Addition: Glen Rose Townsite Year of addition: 1878

9. Significance

Applicable National Register (NR) criteria:

- A. Associated with events that have made a significant contribution to the broad pattern of our history;
- B. Associated with the lives of persons significant in our past;
- ☒ C. Embodies the distinctive characteristics of a type, period or method of construction or represents the work of a master, or possesses high artistic value, or represents a significant and distinguishable entity whose components lack individual distinction;
- D. Has yielded, or is likely to yield, information important in prehistory or history;

Areas of significance: Architecture: Commerce

Period(s) of significance: Ca. 1905

Level of significance: National State Local ☒

Possible NR district: Yes ☒ No **Is property contributing?** Yes ☒ No

10. Priority (See manual for definitions.) ☐ High ☐ Medium ☒ Low

Explain _____

Questions?
Contact survey coordinator
History Programs Division, Texas Historical Commission
at 512/463-5853 or history@thc.state.tx.us.



TEXAS
HISTORICAL
COMMISSION

The State Agency for Historic Preservation

www.thc.state.tx.us



Glen Rose Historic Resources Survey, Site 10(roll 1, exp. 27), Palace Theater/Gresham's Dry Goods Store, 114 Northeast Barnard Street, southeast to front.



Glen Rose Historic Resources Survey, Site 10 (roll 1, exp. 28), Palace Theater/Gresham's Dry Goods Store, 114 Northeast Barnard Street, northwest to rear.

