

HARTFORD PUBLIC WORKS DEPARTMENT

200 Beachwood St.

621-3022

Dan Staunton Supt.



6/28/2021

MAINTENANCE DEPARTMENT

Serviced all the equipment that required servicing
Repaired all the equipment that required repairing
Empty trash cans every week.
Clean restrooms every day.
Mow grass as needed.
Mow Waste Water Treatment Plants grass.
Mow all city propertys as needed.
Working with contractors with both constrution projects.

WATER DEPARTMENT

Water turn off	2
Water turn on	1
Water meter repairs	3
Water leaks repaired	4
Water meters read by request	5
Water services replaced to water main	2
Collected monthly water samples and delivered to Paw Paw Lab	
Sent monthly reports to the Michigan Department of Health	
Ran auxiliary well generator once a week	
Water meters read for the month.	

MAJOR AND LOCAL STREETS

Cold patching
Sweeping Main St. and Center St. curbs.

SEWER SYSTEM

Sewer mains rodded	4
Sewer services dug up and repaired	1

LIFT STATIONS

Lift stations are running very well at this time
Generators are run once a week for testing
Bar screens are cleaned twice a week

Iron Removal Plant

HARTFORD PUBLIC WORKS DEPARTMENT

200 Beachwood St.
621-3022
Dan Staunton Supt.



6/28/2021

MAINTENANCE DEPARTMENT

Serviced all the equipment that required servicing
Repaired all the equipment that required repairing
Empty trash cans every week.
Clean restrooms every day.
Mow grass as needed.
Mow Waste Water Treatment Plants grass.
Mow all city propertys as needed.
Working with contractors with both construction projects.

WATER DEPARTMENT

Water turn off	2
Water turn on	1
Water meter repairs	3
Water leaks repaired	4
Water meters read by request	5
Water services replaced to water main	2
Collected monthly water samples and delivered to Paw Paw Lab	
Sent monthly reports to the Michigan Department of Health	
Ran auxiliary well generator once a week	
Water meters read for the month.	

MAJOR AND LOCAL STREETS

Cold patching
Sweeping Main St. and Center St. curbs.

SEWER SYSTEM

Sewer mains rodded	4
Sewer services dug up and repaired	1

LIFT STATIONS

Lift stations are running very well at this time
Generators are run once a week for testing
Bar screens are cleaned twice a week

Iron Removal Plant