

Plan Review Permit Log

	Date	Permit Number	Address	Issued To	Amount Received	Description / Scope
1	Fri 1/6/23	HV-22-114P	12 Hilshire Grove	Abacus Plumbing	\$ 180.00	Water-Heater Replacement
2	Mon 1/9/23	HV-22-115M	4 Hilshire Grove	Central City Air	\$ 160.00	HVAC Repair
3	Mon 1/9/23	HV-22-102P	8002 Bromley	Belford Enterprises	\$ 380.00	Plumbing-Remodel
	Tues 1/10/23	HV-21-061I	1123 Guinea	RL Builders	\$ -	Plan Review - Irrigation
4	Wed 1/11/23	HV-23-001	1220 Archley Drive	Icon Power	\$ 160.00	Electrical - Solar Panel
5	Thu 1/12/23	HV-22-093B	1126 Guinea Drive	Enterprise Builders	\$ 10,193.20	New SFR
6	Thu 1/12/23	HV-22-113E	7915 Hilshire Green	Definite Electric	\$ 205.00	Generator-Electrical
7	Thu 1/12/23	HV-22-113P	7915 Hilshire Green	LesCon Plumbing	\$ 280.00	Plumbing - Plumbing
8	Thu 1/12/23	HV-22-102M	8002 Bromley Rd	Riojas AC	\$ 330.00	Mechanical - Remodel
9	Tue 1/17/23	HV-22-093E2	1126 Guinea	Electrical Works of Ho	\$ 405.00	Electric-SFR
10	Tue 1/17/23	HV-22-093P	1126 Guinea	Strutton Plumbing	\$ 530.00	Plumbing -SFR
11	Mon 1/23/23	HV-23-004	1127 Glourie	John Moore Services	\$ 180.00	Water-Heater Replacement
12	Mon 1/30/23	HV-23-006	8201 Burkhart	Drains Plus Plumbing	\$ 160.00	GTO

Permits:	
Electrical	3
HVAC	2
Generator	1
Plumbing	6
Total	12

Inspection Log

Log #	Address	Permit #	Inspection Type	Result	Date	Inspector
22-364	7906 N Villa Court	HV-22-087GP	Plumbing Final	PASS	1/3/23	BBG
22-365	7906 N Villa Court	HV-22-087GE	Electrical Final	PASS	1/3/23	BBG
22-370	1327 Pine Chase Dr	HV-21-1119E	Electrical Final-Solar	PASS	1/4/23	BBG
23-001	7922 Hilshire Green	HV-22-108F	Fence Final	PASS	1/4/23	BBG
23-002	8002 Bromley Rd	HV-22-102R	Interior Demo	PASS	1/6/23	BBG
23-003	8002 Bromley Rd	HV-22-102R	Framing	FAIL	1/6/23	BBG
23-004	1311 Friarcreek Ln	HV-22-078P	Plumbing Ground	PASS	1/6/23	BBG
23-005	8001 Bromley	HV-21-111AD	Partial Underground	PASS	1/8/23	HDR
23-006	8002 Bromley Rd	HV-22-102P	plumbing top-out	PASS	1/10/23	BBG
23-007	8002 Bromley Rd	HV-22-102P	gas test	PASS	1/10/23	BBG
23-008	1123 Guinea	HV-21-061P	Plumbing Final	FAIL	1/10/23	BBG
23-009	8001 Bromley	HV-21-111F	Fence Final	PASS	1/11/23	BBG
23-010	12 Hilshire Grove	HV-22-114P	Water Heater Final	PASS	1/12/23	BBG
23-011	1123 Guinea Drive	HV-21-041E2	Electrical Final	PASS	1/12/23	BBG
23-012	1123 Guinea Drive	HV-21-041M	Vent Hood & Mechanical Final	PASS	1/12/23	BBG
23-013	1126 Guinea Drive	HV-22-093B	Pre-construction jobsite inspection GATE 1357	PASS	1/13/23	BBG
23-014	1126 Guinea Drive	HV-22-093B	Pre-construction Arborist GATE 1357	PASS	1/13/23	Cary Moran
23-015	1126 Guinea Drive	HV-22-093B	Pre-Construction Engineer GATE 1357	PASS	1/13/23	HDR
23-016	1123 Guinea Drive	HV-21-061I	Irrigation Final	PASS	1/13/23	BBG
23-017	7915 Hilshire Green	HV-22-113P	Electrical Ditch Cover	PASS	1/13/23	BBG
23-018	1210 Ridgeley Dr	HV-22-048	Hurricane Clips & Straps	PASS	1/17/23	BBG
23-019	7915 Hilshire Green	HV-22-113P	undergournd (generator)	PASS	1/17/23	BBG
23-020	7915 Hilshire Green	HV-22-113P	gas test (generator)	FAIL	1/17/23	BBG
23-021	7915 Hilshire Green	HV-22-113P	plumbing final (generator)	FAIL	1/17/23	BBG
23-022	1126 Guinea	HV-22-098B	Piers	FAIL	1/18/23	BBG

Inspection Log

23-023	1315 Friarcreek Ln	HV-22-071	Pre-Construction	FAIL	1/18/23	BBG
23-024	1315 Friarcreek Ln	HV-22-071	Pre-Construction	PASS	1/18/23	Cary Moran
23-025	1315 Friarcreek Ln	HV-22-071	Pre-Construction	FAIL	1/18/23	HDR
23-026	7915 Hilshire Green	HV-22-113P	gas test (generator)	FAIL	1/18/23	BBG
23-027	7915 Hilshire Green	HV-22-113P	plumbing final (generator)	FAIL	1/18/23	BBG
23-028	1123 Guinea	HV-21-061f	Fence Final	PASS	1/18/23	BBG
23-029	1123 Guinea	HV-21-061b	Building Final	FAIL	1/18/23	BBG
23-029	1123 Guinea	HV-21-061b	Tree Final	PASS	1/18/23	Cary Moran
23-031	1311 Friarcreek Ln	HV-22-078	Foundation	PASS	1/19/23	BBG
23-032	8002 Bromley	HV-22-102M	hvac cover	PASS	1/19/23	BBG
23-033	8002 Bromley	HV-22-102M	vent hood	PASS	1/19/23	BBG
23-034	7915 Hilshire Green	HV-22-113P	Gas test	PASS	1/19/23	BBG
23-035	7915 Hilshire Green	HV-22-113P	Final Plumbing	PASS	1/19/23	BBG
23-036	1126 Guinea	HV-22-098B	Piers	PASS	1/19/23	BBG
23-039	1210 Ridgeley	HV-22-048B	nail pattern	PASS	1/20/23	BBG
23-040	1123 Guinea	HV-21-061B	Building final	PASS	1/20/23	BBG
23-040	8002 Bromley	HV-22-102M	HVAC Final	CANCELLED	1/20/23	BBG
23-041	8001 Bromley	HV-21-111P	Gas Test	PASS	1/20/23	BBG
23-042	8002 Bromley	HV-22-102M	Frame	PASS	1/23/22	BBG

Inspection Log

23-043	1315 Friarcreek Ln	HV-22-071B	Pre-Con	PASS	1/23/22	BBG
23-044	1311 Friarcreek Ln	HV-22-078E	T-Pole	PASS	1/24/23	BBG
23-045	8001 Bromley	HV-21-111AD	Underground	FAIL	1/24/23	HDR
23-046	8001 Bromley	HV-21-111B	Flatwork	PASS	1/24/23	BBG
23-047	1315 Friarcreek	HV-22-071E	T-Pole	FAIL	1/26/23	BBG
23-048	1126 Guinea	HV-22-093P	Ground	PASS	1/26/23	BBG
23-049	1126 Guinea	HV-22-093P	sewer	PASS	1/26/23	BBG
23-050	1126 Guinea	HV-22-093P	water	PASS	1/26/23	BBG
23-051	1315 Friarcreek	HV-22-071E	T-Pole (lock should have been removed)	FAIL	1/27/23	BBG
23-052	1315 Friarcreek	HV-22-071E	T-Pole (lock should have been removed)	PASS	1/31/23	BBG

Inspections:	
Pass	40
Fail	13
Consult	0
Canceled	1
Total	54