## February 2021 MONTHLY BUILDING REPORT SUMMARY

Plan Review: None

**Permits:** Four (4):

Demolition:		
Remodel / Add-On:		
New Construction:		
Accessory Building:		
Electrical:		
HVAC:	1	
Plumbing:		
Fire Sprinklers:	1	
30-Day Dumpster:		

Sign:	
Roof:	
Fence:	1
Tree Removal:	
Irrigation:	
Drainage:	
Swimming Pool:	
Swimming Pool Demo:	
Other: Storage Container	1

**Inspections:** Twenty (20)

Red Tag Stop Work Orders Issued: None

## **Building Finals / Certificates of Occupancy:**

• Conditional Certificate of Occupancy – 1306 Bridle Spur Ln

**Change of Occupancy Use:** None

**Extended Permit Request:** None

CITY OF HILSHIRE VILLAGE PLAN REVIEW AND PERMIT LOG - February 2021							
Date	Permit Number	Address	Issued To	Amount Received		Description / Scope	No of insp
Thu 2/4/21	HV-19-062F	1306 Bridle Spur Ln	Greengos Irrigation	\$	175.00	Fence Replacement	1
Wed 2/3/21	HV-20-059FS	1330 Glourie Dr	1st Texas Fire Protection, Inc	\$	280.00	Fire Sprinkler System	2
Wed 2/24/21	HV-21-009M	1233 Pine Chase	Central City Air	\$	160.00	Furnace replacement	1
Fri 2/26/21	HV-21-010ACC	8311 Creekstone Cir	PODS Storage Buildings	\$	25.00	Storage container for plumbing repairs due to storm	1

	INSPECTION LOG - February 2021						
LOG NO.	ADDRESS	PERMIT NO.	TYPE OF REQUEST	P OR F	DATE	INSPECTOR	
21-012	8006 Anadell	HV-21-005P	Re-Pipe & Water Service Line Cover	Pass	2/3/2021	BBG	
21-013	1327 Friarcreek	HV-21-006P	Water Heater Final	Pass	2/4/2021	BBG	
21-014	1220 Archley	HV-20-007SPE	SP Electrical Underground, Bonding	Pass	2/4/2021	BBG	
21-015	1301 Glourie Dr	HV-21-002D	Drainage Final	Pass	2/5/2021	Javier Vasquez	
21-016	1306 Bridle Spur Ln	HV-19-062F	Fence	Height - Pass, Pending Engineer Review	2/8/2021	BBG	
21-017	1306 Bridle Spur Ln	HV-19-062M	HVAC Final	Fail	2/8/2021	BBG	
21-018	1306 Bridle Spur Ln	HV-19-077E	Electrical Final	Pass	2/8/2021	BBG	
21-019	1306 Bridle Spur Ln	HV-19-062D	Drainage Final	Pending Final Items	Under Review	Javier Vasquez	
21-020	1306 Bridle Spur Ln	HV-19-062B	Building Final - Occupancy	Fail	2/8/2021	BBG	
21-021	1306 Bridle Spur Ln	HV-19-062M	HVAC Final Reinspection	Pass	2/10/2021	BBG	
21-022	1306 Bridle Spur Ln	HV-19-062B	Building Final - Occupancy	Fail	2/10/2021	BBG	
21-023	1306 Bridle Spur Ln	HV-19-062P	Plumbing Final	Fail	2/10/2021	BBG	
21-024	1330 Glourie Dr	HV-20-059E	Electrical Rough-In	Pass	2/10/2021	BBG	
21-023	1306 Bridle Spur Ln	HV-19-062P	Plumbing Final & Building Occupancy	Pass	2/11/2021	BBG	
21-026	1330 Glourie Dr	HV-20-059B	Framing	Fail	2/12/2021	BBG	
21-027	1306 Bridle Spur Ln	HV-19-062FS	Fire Sprinkler Final	Pass	2/8/2021	Fire Marshal	
21-028	1330 Glourie Dr	HV-20-059B	Framing Reinspection	Cancelled	2/19/2021	N/A	
21-029	1330 Glourie Dr	HV-20-059B	Framing Reinspection	Contractor Cancelled	2/24/2021	N/A	
21-030	1306 Bridle Spur Ln	HV-19-077T	Tree Final	Pass Pending Corrections	2/24/2021	Cary Moran	
21-031	1233 Pine Chase	HV-21-009M	HVAC Final	Pass	2/26/2021	BBG	

February 2021 Construction Site Inspections				
2/2/2021				
2/2/2021	No violations noted			
1306 Bridle Spur	Fully sodded exterior; home complete			
1111 Guinea Dr	No violations noted			
1023 Ridgeley Dr	No violations noted			
1023 Magercy Dr	No change - no construction started			
1210 Ridgeley	String lines have been ran; no other changes			
1326 Glourie Dr	No work at this time			
1220 Archley Dr	No violations noted			
1330 Glourie Dr	No violations noted			
7906 N Villa	No violations noted			
1306 Glourie Dr	No violations noted			
1226 Glourie Dr	No changes			
	No violations noted			
14 Hilshire Grove Ln	Possible construction complete			
2/8/2021				
1111 Guinea Dr	No violations noted			
1023 Ridgeley Dr	No violations noted			
1210 Ridgeley	Work has not started yet			
1326 Glourie Dr	Work has not started yet			
1220 Archley Dr	No violations noted			
1220 Clauria Dr	Porta potty has been rotated and can be seen from street; left a warning sticker to			
1330 Glourie Dr	resolve			
7906 N Villa	No violations noted			
1306 Glourie Dr	No violations noted			
1226 Glourie Dr	No changes			
14 Hilshire Grove Ln	No violations noted			
	storm week			
2/22/2021				
1111 Guinea Dr	No violations noted			
1023 Ridgeley Dr	No violations noted;			
1023 Mageley Di	Large amount of trash bags left at curb			
1210 Ridgeley	Work has not started yet			
1326 Glourie Dr	Work has not started yet			
1220 Archley Dr	No violations noted			
1330 Glourie Dr	Violation given: Porta potty must be screened from view by a solid structure and not			
	visible from the street			
7906 N Villa	No violations noted			
1306 Glourie Dr	No violations noted			
1226 Glourie Dr	No changes			
14 Hilshire Grove Ln	No violations noted			