

Pending Items Report

Customer: Hinckley Fire Department
Equipment/Component: Engine 19
Work Order: 135441


Printed: 4/24/2025

Hinckley Fire Department - Completed Items for Work Order: 135441

WO#	Equipment/Component	Item Description
135441	Engine 19	Heavy Duty Emergency Vehicle Safety Inspection.

Hinckley Fire Department - Pending Items for Work Order: 135441

WO#	Equipment/Component	Item Description
135441	Engine 19	Left side batteries dead - type 31 stud, 2 batteries.
135441	Engine 19	One upper clearance light out.
135441	Engine 19	Left rear compartment light out, right rear compartment light out.
135441	Engine 19	Right side mirror heat not working.
135441	Engine 19	Four ground lights not working.
135441	Engine 19	Auto eject cover cracked.
135441	Engine 19	Right cab cylinder pin coming out, is bent.
135441	Engine 19	Left cab lift cylinder leaks.
135441	Engine 19	Left side of engine, class 3 leak.
135441	Engine 19	Right side of engine class 1 leak.
135441	Engine 19	One pump panel light out, both sides.



Pending Items Report

Customer: Hinckley Fire Department
Equipment/Component: Grass Rig 17
Work Order: 135442


Printed: 4/10/2025

Hinckley Fire Department • Completed Items for Work Order: 135442

WO#	Equipment/Component	Item Description
135442	Grass Rig 17	Light Duty Emergency Vehicle Safety Inspection.

Hinckley Fire Department • Pending Items for Work Order: 135442

WO#	Equipment/Component	Item Description
135442	Grass Rig 17	Left front bumper red light inoperative.
135442	Grass Rig 17	Windshield has rock chips.
135442	Grass Rig 17	Rear floor lights inoperative.
135442	Grass Rig 17	Left side front compartment light inoperative.
135442	Grass Rig 17	Right side compartment both front middle lower and rear lights inoperative.
135442	Grass Rig 17	Power steering hoses class 1 leak.
135442	Grass Rig 17	Batt 10.5
135442	Grass Rig 17	10.5 80 amps alt weak.
135442	Grass Rig 17	No draw 14 volts, lights on drops to 12 volt or less.
135442	Grass Rig 17	Front axle cover leaking.
135442	Grass Rig 17	Oil pan leaking.
135442	Grass Rig 17	Transmission pan leaking.
135442	Grass Rig 17	Transfer case slip yoke has play.
135442	Grass Rig 17	Rear axle seals and cover leaking. —
135442	Grass Rig 17	Rear brakes need replacing and brake wheel cylinder.
135442	Grass Rig 17	U-joints are stiff, all should be replaced. —
135442	Grass Rig 17	Front and rear shafts.
135442	Grass Rig 17	Rear fuel tank strap rusted out.



Pending Items Report

Customer: Hinckley Fire Department
Equipment/Component: Engine 11
Work Order: 135439

Printed: 4/10/2025


Hinckley Fire Department • Completed Items for Work Order: 135439

WO#	Equipment/Component	Item Description
135439	Engine 11	Heavy Duty Emergency Vehicle Safety Inspection.

Hinckley Fire Department • Pending Items for Work Order: 135439

WO#	Equipment/Component	Item Description
135439	Engine 11	Rear axle, all bolts very rusty.
135439	Engine 11	Foam tank leaking.
135439	Engine 11	Need alternator.

check Pump Primer oil



Pending Items Report

Customer: Hinckley Fire Department
Equipment/Component: Tanker 20
Work Order: 135444

Printed: 4/10/2025

Hinckley Fire Department • Completed Items for Work Order: 135444

WO#	Equipment/Component	Item Description
135444	Tanker 20	Heavy Duty Emergency Vehicle Safety Inspection.

Hinckley Fire Department • Pending Items for Work Order: 135444

WO#	Equipment/Component	Item Description
135444	Tanker 20	Engine front cover oil leaks, class 2.
135444	Tanker 20	Coolant leak right side motor would not leak under pressure.
135444	Tanker 20	Low rad hose leaking, re-tighten or recheck, maybe rac has hole in outlet
135444	Tanker 20	Fuel lines to tank class 2 leak, cleaned off, recheck.
135444	Tanker 20	All tires 20 to 30 psi low.
135444	Tanker 20	May need radiator.



Pending Items Report

Customer: Hinckley Fire Department
Equipment/Component: Engine 19
Work Order: 135441


Printed: 4/10/2025

Hinckley Fire Department • Completed Items for Work Order: 135441

WO#	Equipment/Component	Item Description
135441	Engine 19	Heavy Duty Emergency Vehicle Safety Inspection.

Hinckley Fire Department • Pending Items for Work Order: 135441

WO#	Equipment/Component	Item Description
135441	Engine 19	One clearance light out.
135441	Engine 19	One pump panel light out, both sides.
135441	Engine 19	Left rear compartment light out.
135441	Engine 19	Right rear compartment light out.
135441	Engine 19	Right side mirror heat inoperative.
135441	Engine 19	Four ground lights out - 4" round.
135441	Engine 19	Auto eject cover cracked, cover spring broken.
135441	Engine 19	Right cab lift cylinder pin coming out, is bent.
135441	Engine 19	Pin won't go back safely, stop won't work.
135441	Engine 19	Rear drive shaft slip yoke has play.
135441	Engine 19	Right front oil hub leaking.
135441	Engine 19	Tires all 10 to 30 psi low.
135441	Engine 19	Cab lift cylinders lift, left leaking class 3, right class 1.



Pending Items Report

Customer: Hinckley Fire Department
Equipment/Component: Tanker 23
Work Order: 135445


Printed: 4/10/2025

Hinckley Fire Department • Completed Items for Work Order: 135445

WO#	Equipment/Component	Item Description
135445	Tanker 23	Heavy Duty Emergency Vehicle Safety Inspection.

Hinckley Fire Department • Pending Items for Work Order: 135445

WO#	Equipment/Component	Item Description
135445	Tanker 23	Check engine light on, shut down light, no problem found.
135445	Tanker 23	Oil coming out of blowby.
135445	Tanker 23	Oil fill tube at block class 1 leak, may need new gasket.
135445	Tanker 23	Transmission oil leak on transfer case.



Pending Items Report

Customer: Hinckley Fire Department
Equipment/Component: Engine 18
Work Order: 135440


Printed: 4/10/2025

Hinckley Fire Department • Completed Items for Work Order: 135440

WO#	Equipment/Component	Item Description
135440	Engine 18	Heavy Duty Emergency Vehicle Safety Inspection.

Hinckley Fire Department • Pending Items for Work Order: 135440

WO#	Equipment/Component	Item Description
135440	Engine 18	Power steps inoperative.
135440	Engine 18	Left rear compartment door switch bad, 2 lights inoperative.
135440	Engine 18	Right rear compartment light inoperative.
135440	Engine 18	Rear door switch bad.
135440	Engine 18	CAFS PTO to compressor shaft u-joints need replacing.
135440	Engine 18	CAFS compressor class 2 leak front shaft seal.
135440	Engine 18	Air filter needs replacing.



Pending Items Report

Customer: Hinckley Fire Department
Equipment/Component: Grass Rig 22
Work Order: 135443

Printed: 4/10/2025

Hinckley Fire Department • Completed Items for Work Order: 135443

WO#	Equipment/Component	Item Description
135443	Grass Rig 22	Light Duty Emergency Vehicle Safety Inspection.

Hinckley Fire Department • Pending Items for Work Order: 135443

WO#	Equipment/Component	Item Description
135443	Grass Rig 22	Check engine light on.
135443	Grass Rig 22	AI shocks should be replaced, may have lift kit.
135443	Grass Rig 22	Left front axle seal leaking.