

VEHICLE/EQUIPMENT EVALUATION FORM

Date of Evaluation: 8/28/2024

Vehicle Number: 306
Year: 1999
Make: CRAFCO
Model: 100D
Usage Type: PW STREET

Life-to-date usage miles: NA
Years in service: 25
Year scheduled for replacement: 2023

Drivetrain Condition:

Engine	Average for miles/hours:	<input type="checkbox"/>	Needs work:	<input checked="" type="checkbox"/>
Transmission	Average for miles/hours:	<input type="checkbox"/>	Needs work:	<input type="checkbox"/>
Differential	Average for miles/hours:	<input type="checkbox"/>	Needs work:	<input type="checkbox"/>

Body Condition:

Undercarriage	Average for mileage/year:	<input type="checkbox"/>	Fair:	<input type="checkbox"/>	Poor:	<input checked="" type="checkbox"/>
Sheet Metal	Average for mileage/year:	<input type="checkbox"/>	Fair:	<input type="checkbox"/>	Poor:	<input checked="" type="checkbox"/>
Interior	Average for mileage/year:	<input type="checkbox"/>	Fair:	<input type="checkbox"/>	Poor:	<input type="checkbox"/>

Alternatives:

Retain

- ☐ keep as is/evaluate annually
- ☐ partially rebuild
- ☐ completely rebuild
- ☐ modify w/attachments and options
- ☐ shift to lighter duty application

Dispose

- ☐ Trade-in
- ☒ Sell by Village or auction
 - ☐ As is/no sale prep costs
 - ☐ Incur minimum sale prep. Costs
 - ☐ Disassemble/sell components

Replacement

- ☒ replace w/updated similar vehicle/equipment
- ☐ replace w/rented vehicle equipment as needed
- ☐ replace w/multi-functional vehicle/equipment
- ☐ replace with Fleet recycled vehicle

Notes:

This is a Public Works Street Dept asphalt crack sealer, it has served its purpose however, it is past the useful stage of reliability.

Joe Mancini
Vehicle Maintenance Supervisor