

VEHICLE/EQUIPMENT EVALUATION FORM

Date of Evaluation: 9/20/2024

Vehicle Number: 42-1742
 Year: 2017
 Make: Chevrolet
 Model: Silverado
 Usage Type: Building Maint

Life-to-date usage Hours: 89,000
 Years in service: 7 Years
 Year scheduled for replacement:

Drivetrain Condition:

Engine	Average for miles/hours:	<input checked="" type="checkbox"/>	Needs work:	<input type="checkbox"/>
Transmission	Average for miles/hours:	<input type="checkbox"/>	Needs work:	<input checked="" type="checkbox"/>
Differential	Average for miles/hours:	<input checked="" type="checkbox"/>	Needs work:	<input type="checkbox"/>

Body Condition:

Undercarriage	Average for mileage/year:	<input checked="" type="checkbox"/>	Fair:	<input type="checkbox"/>	Poor:	<input type="checkbox"/>
Sheet Metal	Average for mileage/year:	<input checked="" type="checkbox"/>	Fair:	<input type="checkbox"/>	Poor:	<input type="checkbox"/>
Interior	Average for mileage/year:	<input checked="" type="checkbox"/>	Fair:	<input type="checkbox"/>	Poor:	<input type="checkbox"/>

Alternatives:

Retain

- keep as is/evaluate annually
- partially rebuild
- completely rebuild
- modify w/attachments and options
- shift to lighter duty application

Dispose

- Trade-in
- Sell by Village or auction
 - As is/no sale prep costs
 - Incur minimum sale prep. Costs
 - Disassemble/self components

Replacement

- replace w/updated similar vehicle/equipment
 - replace w/rented vehicle equipment as needed
 - replace w/multi-functional vehicle/equipment
 - replace with Fleet recycled vehicle
-

Notes:

This is a Building maintenance pickup, it has served its purpose, however, it has passed the useful stage of reliability.

Joe Mancini
 Vehicle Maintenance Supervisor