

Street-Side View (Compartments Closed)



Street-Side Front Corner View



Rear View



Street-Side Rear Corner View



Curb-Side Rear Corner View



Front View



Curb-Side View (Compartments Closed)



Manuals



Street-Side Door (Door Open)



Curb-Side Front Corner View



Street-Side Driver's Seat



Job Number



Street-Side Both Seats




Shifter



Custom Switches



White Door Jamb Label



Yellow Door Jamb Label



Odometer (Mileage)



Additional Cab

27 Job Status - Open Issues

Sch # 4-43 27 Job 1021799772

Customer CITY OF IOWA CITY Unit LR8-58RM Location PDI

27 Start 4/4/24 27 Due 5/3/24 Prom 10/1/24 Mfg 4/25/24 24 Job Unit Notes 1022001532 Fleet Chassis VIN

Body L/R Chassis VIN
 Ch L/R WHITE FREDIGHTLINER M2-106 2025 1FVACWF0Z8PVN1774

Age	Author	Challenges	Dept	Champion	Done	Closed
0	Jim Reap	B-Defect#24, Installation, Mechanical, To much lower boom pull down	Plant27	Car Loftis		
0	Warren Cooke	C-Defect#22, Installation, Mechanical, Missing lanyard at cone holder latch	Plant27	Car Loftis		
0	Warren Cooke	C-To-Do#23, Wet Paint, Wet Paint, Scratch on front cabguard	Plant27	Jerry Davis		

Inspector Dept. Cat. Sev. Additional Issues (QA Log) Corrective Action Fixed by


Dept. Codes	Cat. Codes (Submit vendor issues using the red tag / RMR process)	Sev. Codes
F - Fab	M - Mechanical	A - Major issue preventing the trucks operation.
W - Winding / Upper Boom	W - Welding	B - Significant issue but truck will still operate.
PP - Powder Paint	MI - Missing Item	C - Minor issue with no effect on operation.
CA - Component Assembly	E - Electrical	
I - Installation	P - Paint	
WR - Wrap Up / Run In	D - Documentation	
ENG - Engineering	H - Hydraulic	
	T - Trash	

4/16/24 1:28 am Page 1 of 1

Street-Side View (Compartments Open)




PDM



Street-Side Gap Between Cab and Body



Ride-Height Label



Curb-Side View (Compartments Open)



Curb-Side Gap Between Cab and Body



Street-Side Compartments



Curb-Side Compartments



Street-Side Tailshelf



Curb-Side Tailshelf



Rear Tailshelf



Body Serial Number Placard



Additional Body



Unit Serial Number Placard



Pedestal



Inner Body Serial Number Placard



Rear Cab



Reservoir



Lower Controls



Bucket Controls



Bucket Liner



Bucket Cover




Additional Cargo



Additional Cargo



Additional Underside




Hazard Labels



PTO / Pump



Drive Shaft



Emissions Label (take multiple photos)



VIN Plate



Ship Loose Parts



Engine Label



Chassis Battery

