








DORA Intranet Applications -> E&P Permits

-  **Permit Search**
-  **New Permit**
-  **View Permit**
  - Inspections
  - Additional Fees
-  **Report Menu**
-  **Maintenance**

Click the "Cancel" button when you are done viewing this information.

**Permit Number: 724157**  
**Inspection ID: 1007427**

Received Date: 06/28/2012	Inspector: Wyland, Rich
Inspected Date: 06/28/2012	Arrival: 10:35 AM
Number of Days:	Travel Time:
	Inspect Time:

ReInspect Fee Required:

Partial:  Hazard:

Power  
Connected:

Inspection Type: Complete Final      Inspection Status: Accepted

Comments: Kim one of the receptacles here has a ground prong broke off in it, So it renders one of the receptacles unusable

Corrections:

Inspector Notes:

Upload Date: 06/29/2012

Cancel



Colorado Department of Regulatory Agencies

March 19, 2024 08:46 am  
 Session: 1209949  
 User: Luke C Hanson  
 Service Path: /cppprod/  
 Static Full Path: https://borneo.dora.internal/cppprod  
 Calling Procedure: EP\_Inspection\_GUI.View\_Form  
 Version: 1.00