

Photo 1: View of subject property. The home dates to 1854. The property owner wishes to operate the home as a Bed and Breakfast.



Map 1: Aerial view of subject property highlighted in orange. The subject property is bordered by residential properties the northern side. There is a street (Killarney Street) that runs along the southern portion of the property.




Photo 2: View of subject property from Patton Street. The home can be seen just over the tree line in the center of the photo.



Photo

3: Northeastern corner of the subject property. An existing carport and two sheds are located on the property. Very little vegetation is located along this section of the property.



Photo 4: Rear of property. An existing fence and some large trees are located along the property line.



Photo 5: Northwestern corner of property. Some existing plantings are located along this section of the property, however, an adjacent residence can be seen in close proximity to the current property.

