

Date Created	06/14/2022
Inspector	Blake
Salesperson	
Client	
Inspection Type	Final Inspection
Manufacturer	CAT
Model	906M
Serial Number	H6604683
Year	2021
Hours	291
Overall Operating Condition	Good
Branch Location	North Charlotte
Features	Air Conditioner, AM FM Radio, Anti-Theft System, Auxiliary Hydraulics, Bucket, Hand and Foot Control, Product Link, Quick Coupler
GENERAL APPEARANCE	
Start Code	No
Notes	
Radiator Grill & Shroud	Good
Engine Hood & Stack	Good
Bumper	Good
Counterweight	Good
Cab or Canopy	Good
Steps & Ladder	Good
Grab Irons	Good
Fenders	Good
Paint	Good
Interior	Good
Loader Frame	Good
PM Service Complete	Yes
PM Service Levels	Level 1
Machine Greased	Yes
Fuel Level	Yes
Notes	
GENERAL APPEARANCE	No photos available
SAFETY ITEMS	
Horn	Good
Back Up Alarm	Yes
ROPS	Good
Seat Belt	Good
Notes	
SAFETY ITEMS	No photos available
OPERATOR STATION, GAUGES & CONSOLE	
Dash Console	Good
Windshield Wipers	Good
Meter	Good
Gauges	Good

Switches	Good
Joystick Condition	Good
Seat Cushion & Arm Rest	Good
Interior Lights	Good
Floor Boards	Good
EMS Panel & Warnings	Good
Door Latches	Good
Air Conditioner	Good
Heater	Good
Door & Mirrors	Good
Current O&MM	Yes
Notes	
OPERATOR STATION & GAUGES	No photos available
ENGINE	
Oil Leaks	No
Knocking	No
Belts & Pulleys	Good
Engine Supports	Good
Air Cleaners	Good
Exhaust & Muffler	Good
Engine Oil Level	Good
Operating Condition	Good
Notes	
ENGINE	No photos available
COOLING SYSTEM	
Radiator	Good
Hoses	Good
Fan	Good
Leaks	No
Coolant Level	Good
Notes	
COOLING SYSTEM	No photos available
ELECTRICAL, START & CHARGE SYS	
Batteries & Cables	Good
Wiring	Good
Lighting	Good
Charging	Good
Notes	
ELECTRICAL, START & CHARGE SYS	No photos available
TRANSMISSION	
Transmission Forward	Good
Transmission Reverse	Good
Leaks	Good
Operation Condition	Good
Notes	
Transmission	No photos available
HYDRAULICS	
Hoses & Lines	Good
Tilt Cylinders	Good
Lift Cylinders	Good

Leaks	No
Hydraulic Level	Good
Operating Condition	Good
Notes	
HYDRAULICS	No photos available
ATTACHMENTS	
Cutting Edges	Good
Teeth & Adapters	NA
Bucket Bottom	Good
Quick Coupler	Good
Forks	NA
Multipurpose Cylinders	NA
Attachment Tested	Yes
Notes	
ATTACHMENTS	No photos available
TIRES	
Front Tire (R)	Good
Front Tire % Worn (R)	10%
Tread Cuts & Chunks	Good
Front Tire (L)	Good
Front Tire % Worn (L)	10%
Tread Cuts & Chunks	Good
Rear Tire (R)	Good
Rear Tire % Worn (R)	10%
Tread Cuts & Chunks	Good
Rear Tire (L)	Good
Rear Tire % Worn (L)	10%
Tread Cuts & Chunks	Good
Tire Type	Off road
Notes	
Tires	No photos available
COMMENTS, MISC. REPAIRS, REMARKS	



Front Left
1 of 1

06/14/2022
03:48:06 PM



Front Right
1 of 1

06/14/2022
03:48:15 PM




Back Left
1 of 1

06/14/2022
03:48:37 PM




Back Right
1 of 1

06/14/2022
03:48:28 PM



Operator Station
1 of 1

06/14/2022
03:48:57 PM



Engine
1 of 1

06/14/2022
03:49:17 PM



Attachments
1 of 1

06/14/2022
03:49:43 PM



Hour Meter
1 of 1

06/14/2022
03:50:10 PM



Serial Plate
1 of 1

06/14/2022
03:50:29 PM

