



Public Works

20 Year – Road Improvement List

FY2026 – FY2045

Road Rating:

1 – Very Poor, 2 – Poor, 3 – Fair, 4 – Good, 5 – Excellent/New

FY2026		
Road Name:	Road Rating:	Notes:
N. Valencia Avenue – 800 LF	1	Bad Lateral Pavement Cracking, Delaminating of Pavement Layers, Potholes
FY2027		
N. Tangerine Avenue – 1,400 LF	1	Pavement Cracking, Delaminating of Pavement Layers, Base Failure, Intersection Improvements at N. Lakeshore Boulevard
FY2028		
N. Georgia Avenue – 656 LF	1	Bad Lateral and Horizontal Pavement Cracking, Potholes, Base Failure
E. Holly Street – 752 LF	1	Lateral and Horizontal Pavement Cracking, Tree Roots Compromising Road Base and Pavement, Base Failure
FY2029		
W. Dupont Circle – 1,200 LF	2	Lateral Cracking, Potholes
W. Pine Street – 370 LF	2	Some Lateral and Horizontal Pavement Cracking, Base Failure
FY2030		
Mission Lane – 1,335 LF	2	Some cracking, potholes, tree roots
N. Lakeshore Blvd. (Red Road) – 370 LF	2	Some Lateral Cracking, Potholes
FY2031		
W. Cypress Ave – 1,185 LF	2	Lateral Cracking, Bad Narrow radius at SR 19
W. Palmetto Avenue – 347 LF	2	Some Lateral and Horizontal Pavement Cracking, Base Failure
FY2032		

E. Croton Way – 1,636 LF	2	Lateral cracking, narrow Radius at N. Temple, Bad radius at N. Valencia, Bad Radius at N. Lakeshore Blvd
FY2033		
N. Temple Ave – 2,185 LF	2	Lateral Cracking, Narrow Intersection at Orchid, Bad Radius at Camellia Way, Bad Radius at E. Croton, Bad Radius at E. Laurel
FY2034		
E. Camellia Way – 1,682 LF	2	Lateral cracking, Broken edges, Narrow Intersection at N. Temple
FY2035		
E. Laurel Ave – 1,646 LF	2	Lateral cracking, Radius at SR 19
FY2036		
E. Palmetto Ave – 1,275 LF	2	Lateral cracking, small potholes, Radius at N. Lakeshore Blvd, Radius at SR 19
FY2037		
E. Magnolia Ave – 1,527 LF	2	Lateral cracking, Radius at SR 19
FY2038		
E. Cypress Ave – 1,069 LF	2	Lateral cracking, Radius at SR 19
E. Oak Street – 652 LF	2	Lateral cracking, Radius at N. Lakeshore Blvd, Radius at SR 19
FY2039		
E. Cedar Street – 1,066 LF	2	Lateral cracking, Northside Radius at SR 19
E. Pine Street – 967 LF	2	Lateral & Horizontal cracking, Radius at N. Lakeshore Blvd, Radius at SR 19
FY2040		
E. Myrtle Street – 815 LF	2	Cracking, small potholes, Radius at SR 19
W. Oak Street – 750 LF	2	Lateral Cracking, Narrow Radius at SR 19
FY2041		
N. Dixie Drive (W. Pine St – W. Central Ave) – 614 LF	3	Some Cracking
N. Florida Ave (W. Oak St – W. Central Ave) – 320 LF	3	Some Lateral Cracking
N. Florida Ave (W. Cypress Ave - W. Dupont Cir – 833 LF	3	Potholes, Bad Radius at W. Cypress Ave, Bad Radius at W. Dupont
FY2042		
W. Myrtle Street – 706 LF	3	Some cracking, Radius at SR 19, Radius at S. Dixie Drive
W. Holly Street – 704 LF	3	Some cracking, Radius at SR 19, Radius at S. Dixie Drive
FY2043		

W. Lakeview Ave – 709 LF	3	Some cracking, Radius at S. Dixie Drive, Radius at SR 19
E. Lakeview Ave – 783 LF	3	Some cracking, Radius at SR 19
W. Oleander Ave – 685 LF	3	Some cracking, Radius at S. Dixie Drive
FY2044		
E. Orchid Way – 1,544 LF	3	Some cracking, Narrow Intersections at N. Valencia & N. Temple
W. Magnolia Ave – 1,172 LF	3	Some Lateral Cracking, Narrow Radius at SR 19
FY2045		
S. Dixie Drive - 2,603 LF	3	Some cracking, Radius at SR 19, Radius at W. Oleander Ave, Radius at W. Myrtle, Radius at W. Lakeview, Radius at W. Holly St

Additional Notes:

- Roads may be added or removed from the list during any fiscal year due to additional Budgeting and/or Budgetary Restraints.
- Some roads may be improved over multiple fiscal years due to the length of road and/or Budgetary Restraints.