



Public Works

Road Inventory Report

Road Name	Rating	Notes
E. Holly Street	1	Lateral cracking, tree roots, base failure, Radius @ SR 19
E. Gardenia Street	1	Lateral cracking, base failure, drop-offs, tree roots, Radius @ SR 19
N. Citrus Ave	1	Bad Lateral Cracking, Broken edges, Narrow curved intersection @ Camellia Way, Radius @ SR 19
N. Tangerine Ave	1	Bad Lateral & Horizontal cracking, Delamination of asphalt layers, Bad Radius @ Camellia Way
N. Valencia Ave	1	Lateral cracking, Lifting, Bad radius @ E. Magnolia, Bad radius @ E. Croton Way
N. Georgia Ave	1	Bad Lateral Cracking, Bad Intersection/Radius @ W. Cypress Ave
E. Myrtle Street	2	Cracking, small potholes, Radius @ SR 19
E. Oak Street	2	Lateral cracking, Radius @ N. Lakeshore Blvd, Radius @ SR 19
E. Pine Street	2	Lateral & Horizontal cracking, Radius @ N. Lakeshore Blvd, Radius @ SR 19
E. Cedar Street	2	Lateral cracking, Northside Radius @ SR 19
E. Palmetto Ave	2	Lateral cracking, small potholes, Radius @ N. Lakeshore Blvd, Radius @ SR 19
E. Cypress Ave	2	Lateral cracking, Radius @ SR 19
E. Magnolia Ave	2	Lateral cracking, Radius @ SR 19
E. Laurel Ave	2	Lateral cracking, Radius @ SR 19
E. Croton Way	2	Lateral cracking, narrow Radius @ N. Temple, Bad radius @ N. Valencia, Bad Radius @ N. lakeshore Blvd
Mission Lane	2	Some cracking, potholes, tree roots
N. Lakeshore Blvd. (Red Road)	2	Some Lateral Cracking, Potholes
E. Camellia Way	2	Lateral cracking, Broken edges, Narrow Intersection @ N. Temple
N. Temple Ave	2	Lateral Cracking, Narrow Intersection @ Orchid, Bad Radius @ Camellia Way, Bad Radius @ E. Croton, Bad Radius @ E. Laurel
W. Cypress	2	Lateral Cracking, Bad Narrow radius @ SR 19
W. Dupont Circle	2	Lateral Cracking, Potholes
W. Oak Street	2	Lateral Cracking, Narrow Radius @ SR 19
W. Pine Street	2	Lateral Cracking, Narrow Radius @ SR 19
W. Palmetto Street	2	Lateral Cracking, Narrow Radius @ SR 19
W. Myrtle Street	3	Some cracking, Radius @ SR 19, Radius @ S. Dixie Drive
W. Holly Street	3	Some cracking, Radius @ SR 19, Radius @ S. Dixie Drive

W. Lakeview Ave	3	Some cracking, Radius @ S. Dixie Drive, Radius @ SR 19
W. Oleander Ave	3	Some cracking, Radius @ S. Dixie Drive
S. Dixie Drive	3	Some cracking, Radius @ SR 19, Radius @ W. Oleander Ave, Radius @ W. Myrtle, Radius @ W. Lakeview, Radius @ W. Holly St
E. Lakeview Ave	3	Some cracking, Radius @ SR 19
E. Orchid Way	3	Some cracking, Narrow Intersections @ N. Valencia & N. Temple
W. Magnolia	3	Some Lateral Cracking, Narrow Radius @ SR 19
N. Dixie Drive (W. Pine St – W. Central Ave)	3	Some Cracking
N. Florida Ave (W. Cypress Ave - W. Dupont Cir	3	Potholes, Bad Radius @ W. Cypress Ave, Bad Radius @ W. Dupont
N. Florida Ave (W. Oak St – W. Central Ave)	3	Some Lateral Cracking
E. Central Ave	4	Some Lateral Cracking, Some Small Potholes
N. Lakeshore Blvd. (E. Central – N. Tangerine)	4	Some Lateral Cracking
S. Florida Ave	4	Some Lateral Cracking, Broken Edges
Venezia Blvd	4.5	Some Minor Cracking
Messina Place	4.5	Some Minor Cracking
Terracotta Terrace	4.5	Some Minor Cracking
Napoli Way	4.5	Some Minor Cracking
Bellissimo Place	4.5	Some Minor Cracking
Calabria Way	4.5	Some Minor Cracking
Avila Place	4.5	Some Small Patched Areas
Amola Way	5	Excellent Condition
Marilyn Ave	5	Excellent Condition, Reconstructed in 2022
N. Dixie Drive	5	Excellent Condition, Reconstructed and Widened in 2023

Road Ratings:

1. Very Poor Condition
2. Poor Condition
3. Fair Condition
4. Good Condition
5. Excellent Condition/New