



## Public Utilities

### February 2022 – Monthly Report

Activity	Location/ Address	Notes
Plant Maintenance	Well 3	Greased bearings and serviced well pump
Water system maintenance	#2 road	Valve installation on 6-inch water line.
Service Orders	Throughout Town	18 service orders completed for various Utility work
System pressure testing	Main WTP and Well 3	Testing set pressure in preparation for MWTP cleaning/inspection