

Date: September 8, 2022

To: Tammy Hollingsworth, Auditor of State

Victoria Newton, Treasurer of State

Executive Council

From: Mariah Flowers, Fleet Manager

DAS Fleet Services

Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#64/Hail
Event Date	August 19, 2022
Summary	Vehicle #64 sustained hail damage. (243782)
Amount Requested	\$8,998.44 - Estimate
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you.

Mariah Flowers, Fleet Manager

DAS Fleet Services

Mariah.Flowers@iowa.gov

515-414-6582



Risk, DAS <das.risk@iowa.gov>


Storm 8-18-2022

1 message

Adams Jeannie <jadams@dps.state.ia.us>

To: "Risk, DAS (das.risk@iowa.gov)" <das.risk@iowa.gov>

Mon, Aug 22, 2022 at 2:34 PM



Here is what I have so far. The dents on these may come out with the heat.

Jeannie Adams
ISP Fleet & Supply, Fleet Asset Manager
Department of Public Safety
30 N.E. 48th Place
Des Moines, Iowa 50313
Direct #: 515-725-0643
Cell Phone: 515-204-3019

Shop: 515-281-3277 Fax: 515-242-6321

Email: jadams@dps.state.ia.us<mailto:jadams@dps.state.ia.us>



State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: vehicledamage@dps.state.ia.us; das.risk@iowa.gov

- > One Repair Estimate from Approved State Bid Shop
- > DOT MARS Report (if reportable)
- > Memo from the Driver of the State Vehicle
- > 3-4 photos of the vehicle damage

***Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

STATE VEHICLE: (Mark if Act of Nature ⋈) CASE #:

OTATE VEHICLE: (Mark in Act of Mature) OAGE #:								
Date: (Month/Day/Year)	8/19/22	Time: (Time plus a.m./p.m.)	1500 HES.					
Vehicle Plate #:		Vehicle Mileage:						
Vehicle	2020 CHENY TA	HOE						
Description: (Yr/Make/Model/ &	ITM 676							
Vin#)	IGNSKFKC5LR27	23464						
Assigned To:	TRP CARUTHERS	Badge# (아니						
Driven By:	TEP CARRUTHERS	Badge# 64						
Driver's Lic #:		Damage:	\$					
Vehicle Towed: (Yes / No)	No	Towed By:						
Towed To:		Towing Cost:	\$					
Seat Belt:	Yes	Type of Vehicle:	-Marked					
(Yes / No)		(Marked/Semi /Unmarked)	UNMARKED					
Injured/Injuries:	NX							
Occupants: (Other than driver)	ыla							

VEHICLE #2:

DL #:	State:
Vehicle Lic. #	State:
Driver's Name:	
Driver's Address:	
Owner's Name:	
Owner's Address:	

	т			
Owner's Phone:				
Insurance Info:				
(Carrier/Policy #/Phone)				- CAN CONTRACTOR
Veh Description:				
(Yr/Make/Model & Vin#)				
	Α		0 10 16	TXI-
Damage:	\$		Seat Belt:	No
Injured/Injuries:			(Yes / No)	
			A A MANAGEMENT AND A STATE OF THE STATE OF T	
Occupants: (Other than driver)				
Occupant(s) Wear	ng Seat Be	elt: (Yes/N	vo) Yes	
o oodpani(o) vioan		(100)	,	
OTHER INFORMA	TION:			
Witnesses:				
Accident Location:				
(Street/Hwy)				A STATE OF THE STA
County:				
Weather/Road Cor	nditions:			
Narrative:				
Property Damage	other than			
, , ,	oller man			
Vehicles:		Φ.		
Cost:		\$		
Citations Issued To	13/10/			
(List Charge(s) and Statute	e Code(s))			
			T	· · · · · · · · · · · · · · · · · · ·
Investigating Office	er:			The state of the s
VEHICLE #3: (If no	eeded) (F	or more	vehicles, pleas	se make extra copies
this portion)	, (, ,	•
DL#:			State:	
	1		State:	
Vehicle Lic. #			J State.	
Driver's Name:				
Driver's Address:				
Owner's Name:				

Owner's Address:						
Owner's Phone:						
Insurance Info: (Carrier/Policy #/Phone)						
Veh Description: (Yr/Make/Model & Vin#)						
Damage:	\$		Seat (Yes /	Belt: No)	Yes	
Injured/Injuries:						
Occupants: (Other than driver)			**************************************			W 21
Occupant(s) Wearing	ng S	Seat Belt: (Yes	s/No)	Yes		

QUALITY CLAIMS SOLUTIONS

105 N Krohn Place SIOUX FALLS, SD 57103 Phone: (877) 237-3727, FAX:(866) 371-2844 qcs@qcsdirect.com

For:

QUALITY CLAIMS SOLUTIONS

DAS Fleet Services

Estimate of Record

Owner: STATE OF IOWA Job Number:

Written By: David Kelley

STATE OF IOWA Insured:

Collision

UNKNOWN

Date of Loss: 8/31/2022 12:00 PM

Claim #: Days to Repair:

APDSOI0243782-001

Workfile ID:

2db32c11

Point of Impact: 19 All Over

Owner: Inspection Location:

ANKENY, IA 50021

STATE OF IOWA

Type of Loss:

KARL CHEVROLET COLLISION CENTER

Policy #:

1101 SOUTHEAST ORLABOR ROAD

Ankeny, IA 50021

Other

(515) 299-4337 Evening

Repair Facility:

VEHICLE

2020 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Gasoline Direct Injection GREY

VIN:

1GNSKFKC5LR223669

Production Date:

Interior Color:

Front Side Impact Air Bags

BLACK

License:

Dual Mirrors

Odometer:

23,007

Exterior Color:

GREY

Running Boards/Side Steps

State:

Condition:

Backup Camera

TRANSMISSION Console/Storage Communications System **RADIO** Automatic Transmission CONVENIENCE AM Radio Hands Free Device Overdrive Air Conditioning FM Radio Positraction 4 Wheel Drive Intermittent Wipers **SEATS** Stereo **POWER** Tilt Wheel Search/Seek Cloth Seats Power Steering Cruise Control CD Player Reclining/Lounge Seats Power Brakes Rear Defogger Auxiliary Audio Connection 3rd Row Seat **Power Windows** SAFETY WHEELS Keyless Entry Power Locks Alarm Drivers Side Air Bag Styled Steel Wheels Power Mirrors PAINT Message Center Passenger Air Bag Heated Mirrors Steering Wheel Touch Controls Anti-Lock Brakes (4) Clear Coat Paint Power Driver Seat Rear Window Wiper 4 Wheel Disc Brakes TRUCK Climate Control Traction Control Power Passenger Seat Trailer Hitch **DECOR Dual Air Condition** Stability Control Trailering Package

Estimate of Record

Owner: STATE OF IOWA Job Number:

2020 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Gasoline Direct Injection GREY

Privacy Glass

Parking Sensors

Head/Curtain Air Bags

Estimate of Record

Owner: STATE OF IOWA Job Number:

2020 CHEV Tahoe Commercial 4WD (Fleet) 4D UTV 8-5.3L Gasoline Direct Injection GREY

Line		Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	FRONT BUMPE	R				100 mm		
2		R&I	R&I bumper cover				1.3	
3	FRONT LAMPS							
4		R&I	RT Headlamp assy w/o HID lamps w/o RST pkg				0.5	
			Note: Time is after front bumper cove include the Core Charge.	r is removed. This part	is eligible	for a Core Char	ge. Part Price does r	iot
5		R&I	LT Headlamp assy w/o HID lamps w/o RST pkg				0.5	
6	HOOD							
7		Repl	Hood	84348410	1	1,312.50	1.1	3.3
8			Add for Underside(Complete)					1.6
9	FENDER							
10		R&I	LT Fender liner Tahoe w/o Z71 pkg				0.3	
11		R&I	RT Fender liner Tahoe w/o Z71 pkg				0.3	
12	*	Subl	LT Fender Tahoe-PDR REPAIR		1	830.00		
13	*	Subl	RT Fender Tahoe-PDR REPAIR		1	255.00		
14	WINDSHIELD							
15	*	Repl	Windshield GM, w/o heads up display w/o lane keeper	84352101	1	613.48	Incl.	
16	#	Subl	WINDSHIELD INSTALLATION LABOR		1	110.00		
17	ROOF							
18		Repl	Roof panel w/o PPV, SSV w/o roof rack	23267959	1	1,190.22	22.0	4.6
19			Overlap Major Non-Adj. Panel					-0.2
20	PILLARS, ROCK	(ER &	FLOOR					
21	*	Rpr	LT Uniside assy			s	8.0	3.5
22			Overlap Major Adj. Panel					-0.4
23	*	Rpr	RT Uniside assy			s	5.0	3.5
24			Overlap Major Adj. Panel					-0.4
25	FRONT DOOR							
26		R&I	RT Belt molding chrome				0.3	
27		R&I	LT Belt molding chrome				0.3	
28	*	Subl	LT Outer panel Tahoe &		1	490.00		
			Yukon-PDR REPAIR					
29	*	Subl	RT Outer panel Tahoe & Yukon-PDR REPAIR		1	80.00		
30	REAR DOOR							
31		R&I	RT Belt w'strip chrome				0.3	
32		R&I	LT Belt w'strip chrome				0.3	
33	*	Subl	LT Outer panel Tahoe & Yukon-PDR REPAIR		1	570.00		

Estimate of Record

Own	er: STATE OF I	OW.	A				Job N	umber:
2020 C	HEV Tahoe Commerc	cial 4	WD (Fleet) 4D UTV 8-5.3L Gasoline Dire	ct Injection GREY				
34	*	Subl	RT Outer panel Tahoe & Yukon-PDR REPAIR	1		156,25		
35	QUARTER PANE	L						
36	*	Rpr	LT Quarter panel				6.0	3.1
37			Overlap Major Adj. Panel					-0.4
38			Clear Coat					2.5
39	*	Subl	RT Quarter panel-PDR REPAIR	1		255.00		
40	*	Subl	RT Qtr glass GM w/privacy tint	1		80.00		
41	*	Subl	LT Qtr glass GM w/privacy tint	1		80.00		
42	LIFT GATE							
43		R&I	R&I liftgate assy				Incl.	
44	REAR LAMPS							
45	ļ	R&I	RT Combo lamp assy				0.3	
46		R&I	LT Combo lamp assy				0.3	
47	REAR BUMPER							
48		R&I	R&I bumper cover				1.0	
49	#		Hazardous Waste	1		3.00		
50	#		Caulk and Seal	1		49.95	<u>Incl.</u>	
51	#		Tint Color	1				0.5
52	#		Cover Car	1		10.00		
53	#		Corrosion Protection	1		10.00	0.3	
54	#		POST DIAGNOSTIC SCAN	1			0.5	
			SI	JBTOTALS	•	,095.40	48.6	21.2

ESTIMATE TOTALS

Basis	4	Rate	Cost \$
		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	6,095.40
\$ 2,502.72		-28.0 %	-700.76
48.6 hrs	@	\$ 41.00 /hr	1,992.60
21.2 hrs	@	\$ 76.00 /hr	1,611.20
			8,998.44
		1100-00-00-00-00-00-00-00-00-00-00-00-00	8,998.44
			0.00
	***		0.00
			8,998.44
	\$ 2,502.72 48.6 hrs	\$ 2,502.72 48.6 hrs @	\$ 2,502.72 -28.0 % 48.6 hrs @ \$ 41.00 /hr

MyPriceLink Estimate ID / Quote ID:

994235472219742208 / 111001535