



Date: September 7, 2022

To: Tammy Hollingsworth, Auditor of State

Victoria Newton, Treasurer of State

Executive Council

From: Mariah Flowers, Fleet Manager

DAS Fleet Services

Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	# 2204/Deer
Event Date	March 2, 2022
Summary	Vehicle #2204 struck a deer. (234296)
Amount Requested	\$3,903.76 - Estimate
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Mariah Flowers, Fleet Manager

DAS Fleet Services

Mariah.Flowers@iowa.gov

515-414-6582



Risk, DAS <das.risk@iowa.gov>

Fwd: Vehicle 2204 deer collision

1 message

Risk, DAS <das.risk@iowa.gov>

Fri, Mar 4, 2022 at 1:28 PM

To: Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>, TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicle 2204 struck a deer on 3/2/22. I will forward all information as soon as it is received.

All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,



DAS Fleet Services, Risk

Iowa Department of Administrative Services Division of Business and Property Services

Office: 515-725-2243 Das.Risk@iowa.gov https://das.iowa.gov

----- Forwarded message ------

From: Smith, Michele <michele.smith@dnr.iowa.gov>

Date: Thu, Mar 3, 2022 at 7:04 AM Subject: Vehicle 2204 deer collision

To: DAS Risk <das.risk@iowa.gov>, Shane Dodge <shane.dodge@dnr.iowa.gov>, Marissa Sanders

<marissa.sanders@dnr.iowa.gov>

I will be contacting Auto Tech in Dyersville to get the estimate this afternoon but wanted to get the paperwork to you asap to meet the 24 hour deadline. I called Fleet Services yesterday immediately following the incident.



www.iowadnr.gov

MICHELE SMITH · Environmental Specialist

Field Office 1

Iowa Department of Natural Resources Office 563-927-2640 ext. 308 cell 563-920-1580

1101 Commercial Ct. Suite 10, Manchester, IA 52057















March 2 2022 AccidentReportForm.pdf 244K

Vehicle Accident Report

Time and location of accide	ent				
Accident Date (Mo/Day/Year)		Time	No. of Vehicles		
3/2/2	2022	1 pm 1			
County		State			
Cla	yton	Iowa			
Vehicle 1 (State vehicle)					
Driver's Name		Work Street Address			
Michel	e Smith	1101 Comme	rcial Court #10		
Driver's License No./State		City, State, Zip			
969Z	Z4028	Mancheste	r, IA 52057		
Date of Birth	Department	Work Phone	Home Phone		
10/19/1970	Natural Resources	563-927-2640 x 308	563-920-3496		
License Plate No.	VIN	Year, Make, Model			
2204		Ford Focus			
Estimate (\$) of Damage		Description of Damage			
		Deer ran into the car and damaged the driver's side mirror. Dented front quarter panel			
Vehicle 2 (other vehicle) if i	more than two vehicles-use a	dditional forms			
Driver's Name		Street Address			
	-1.				
Driver's License No./State		City, State, Zip			
Date of Birth	Work Phone	Home Phone License Plate No.			
Description of Damage					

Property Damage other than vehicle (fence, utility pole, etc)					
Owner's Name, Address and Phone	Description of Property Damaged				
Injured Persons (attach additional sheets if necessary)					
Vehicle No. 1/ Name and Address	Describe Injuries				
Vehicle No. 2/ Name and Address	Describe Injuries				
Witness					
Name	Address/Phone				
Name	Address/Phone				

Complete diagram below, include a description of what happened. Use the outline below to sketch the scene of your accident, writing in street or highway names or numbers. Use number 1 to indicate the State vehicle. Incident happend within Strawberry Point city limits on the 500 block of Hwy 13 (Commercial Street.) Two deer were running west between two houses as I was driving south. First deer ran in front of the car and the second deer ran into the side of the car. I was already slowing down to avoid the first deer.



AUTO TECH INC

Workfile ID: PartsShare: e3ff1754 6HLk38

Federal ID:

35-2432379

autotechinc@windstream.net 2015 20th Ave SE, Dyersville, IA 52040 Phone: (563) 875-2748

FAX: (563) 875-2889

Final Bill

RO Number: 3083

Customer:

Insurance:

Adjuster:

Estimator:

Jenn Benn

State of Iowa PO Box 9207

SELF PAY

Phone: Claim:

Create Date: APDSOI0234296-00

3/29/2022

Des Moines, IA 50306

Loss Date:

3/8/2022

1

(877) 544-7843 x5925

Deductible:

2017 FORD Focus SE 4D SED 4-2.0L Flex Fuel Gasoline Direct Injection white

VIN:

State:

1FADP3F23HL291228

Interior Color:

33,570

Vehicle Out:

4/18/2022

License:

2204 IA

Exterior Color: Production Date: white 6/2017 Mileage Out: Condition:

Mileage In:

Job #:

Line	Ver	Operation	Description	Qty	Extended Price \$	Part Type	Labor	Туре	Paint
1	E01		FRONT BUMPER	198(2)					
2	E01	Remove/Install	R&I bumper cover				1.3	Body	
3	E01		FRONT LAMPS						
4	E01	Remove/Install	RT R&I headlamp assy				0.3	Body	
5	E01	Remove/Install	LT R&I headlamp assy				0.3	Body	
6	E01	Remove/Replace	Aim headlamps			OEM	0.4	Body	
7	E01		HOOD						
8	E01	Blend	Hood						1.0
9	E01	Remove/Install	Insulator w/o RS				0.3	Body	
10	E01		WINDSHIELD						
11	E01	Remove/Install	RT Washer nozzle w/o RS				0.2	Body	
12	E01	Remove/Install	LT Washer nozzle w/o RS				0.2	Body	
13	S01	Remove/Replace	LT W'shield molding	1	34.81	OEM	0.2	Body	
14	E01		FENDER						
15	E01	Remove/Replace	LT Fender	1	227.00	A/M	2.0	Body	2.0
16	E01		Add for Clear Coat						0.8
17	E01		Add for Edging						0.5
18	E01	Remove/Replace	Deduct for Overlap				(0.4)	Body	
19	E01	Remove/Replace	LT Corner molding w/o chrome molding	1	25.42	OEM	0.0	Body	
20	E01		COWL						
21	E01	Remove/Install	Cowl grille				0.6	Body	
22	E01		PILLARS, ROCKER & FLOOR						
23	E01	Repair	LT Aperture panel				3.0	Body	3.1

4/25/2022 9:31:10 AM Page 1

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

RO Number: 3083

2017 FORD Focus SE 4D SED 4-2.0L Flex Fuel Gasoline Direct Injection white

2017	OILD I O	CUS DE 10 DES 1 210E 11	ex ruer desource breest injection write						
24	E01		Overlap Major Non-Adj. Panel						(0.2)
25	E01		Add for Clear Coat						0.6
26	E01	Remove/Install	LT Rocker molding				0.0	Body	
27	E01		FRONT DOOR						
28	E01	Remove/Install	LT R&I door assy				0.7	Body	
29	E01	Repair	LT Door shell				2.0	Body	2.3
30	E01		Overlap Major Adj. Panel						(0.4)
31	E01		Add for Clear Coat						0.4
			NOTE: MODIFIED REFINISH WITH FULL	CLEAR COAT					
32	E01	Remove/Install	LT R&I mirror				0.0	Body	
33	E01	Remove/Install	LT Belt w'strip w/o chrome				0,3	Body	
34	E01	Remove/Install	LT Applique				0.2	Body	
35	E01	Remove/Replace	LT Mirror assy w/heated mirrors	1	275.17	OEM	0.4	Body	
36	E01	Remove/Replace	LT Mirror cover primed w/o signal lp	1	45.52	OEM	0.0	Body	0.7
37	E01		Overlap Minor Panel						(0.2)
38	E01		Add for Clear Coat						0.1
39	E01	Remove/Install	LT R&I trim panel				0.4	Body	
40	E01	Remove/Install	L Frt Door Decal				0.8	Body	
41	E01	Remove/Install	LT Handle, outside black				0.0	Body	
42	E01	Remove/Install	LT Handle, outside bezel primed				0.2	Body	
43	E01		REAR DOOR						
44	E01	Remove/Install	LT R&I door assy				0.7	Body	
45	E01		ROOF						
46	E01	Remove/Install	LT Roof molding sedan				0.3	Body	
47	E01		QUARTER PANEL						
48	E01	Blend	LT Quarter panel						0.8
49	E01	Remove/Install	LT Splash shield				0.3	Body	
50	S01	Sublet	Remove Glass	1	90.00	Other			
51	S01	Sublet	Install Glass	1	90.00	Other			
52	S01	Remove/Install	LT Qtr glass Ford black molding						
53	S01	Remove/Replace	Qtr Glass Adhesive	1	35.71	A/M			
54	E01		REAR LAMPS						
55	E01	Remove/Install	LT Tail lamp assy				0.3	Body	
56	E01	Remove/Install	RT Tail lamp assy				0.3	Body	
57	E01		REAR BUMPER						
58	E01	Remove/Install	R&I bumper cover				0.8	Body	
59	E01		VEHICLE DIAGNOSTICS						
60	E01	Remove/Replace	Pre-repair scan NOTE: Sublet	1	159.93	OEM	0.5	Mech	
61	E01	Remove/Replace	Post-repair scan NOTE: Sublet	1	66.60	OEM	0.5	Mech	
62	E01		MISCELLANEOUS OPERATIONS						
63	E01	Remove/Replace	Hazardous Waste Disposal	1	5.00	OEM			

4/25/2022 9:31:10 AM Page 2

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural

RO Number: 3083

2017 FORD Focus SE 4D SED 4-2.0L Flex Fuel Gasoline Direct Injection white

64	E01	Refinish	Clear Coat adj					0.6
65	E01	Refinish	Tint Color					0.5
66	E01	Remove/Replace	Restore Corrosion Protectiion	1	6.00	Other	0.2 Body	
67	E01	Refinish	Feather, Prime & Block					1.5
68	E01	Remove/Replace	Finish Sand and Buff	1	20.00	Other		1.0
69	E01	Remove/Replace	Mask For Overspray	1	5.00	A/M		0.2
70	E01	Remove/Replace	Rope Back Glass	1	15.00	Other	0.5 Body	

Estimate Totals	Discount \$	Markup \$	Rate \$	Total Hours	Total \$
Parts					921.16
Sublet/Miscellaneous					180.00
Labor, Body			64.00	16.8	1,075.20
Labor, Refinish			108.00	15.3	1,652.40
Labor, Mechanical			75.00	1.0	75.00
Subtotal					3,903.76
Sales Tax					0.00
Grand Total					3,903.76
Net Total					3,903.76

Estimate Version	Total \$
Original	3,774.24
Supplement S01	129,52
Insurance Total \$:	0.00
Received from Insurance \$:	
Balance due from Insurance \$:	0.00
Customer Total \$:	3,903.76
Received from Customer \$:	0.00
Balance due from Customer \$:	3,903.76

4/25/2022 9:31:10 AM

T = Taxable Item, RPD = Related Prior Damage, AA = Appearance Allowance, UPD = Unrelated Prior Damage, PDR = Paintless Dent Repair, A/M = Aftermarket, Rechr = Rechromed, Reman = Remanufactured, OEM = New Original Equipment Manufacturer, Recor = Re-cored, RECOND = Reconditioned, LKQ = Like Kind Quality or Used, Diag = Diagnostic, Elec = Electrical, Mech = Mechanical, Ref = Refinish, Struc = Structural