



Date: August 11, 2022

To: Tammy Hollingsworth, Auditor of State

Victoria Newton, Treasurer of State

Executive Council

From: Mariah Flowers, Fleet Manager

DAS Fleet Services

Department of Administrative Services

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	# 105143/Hail
Event Date	March 25, 2022
Summary	Vehicle #105143 sustained hail damage. (241986)
Amount Requested	\$2,173.00 - Estimate
Supporting Documentation	29C20 Email Notification, Accident Report, Repair Estimate(s), Photos

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you,

Mariah Flowers, Fleet Manager

DAS Fleet Services

Mariah.Flowers@iowa.gov

515-414-6582



Risk, DAS <das.risk@iowa.gov>

29C20

1 message

Risk, DAS <das.risk@iowa.gov>

Fri, Jul 1, 2022 at 2:43 PM

To: TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>, Tammy.Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicle 105143 sustained hail damage on 3/25/22. I will forward all information as soon as it is received.

All accidents must be reported via email or phone to Fleet Services within 24 hours. All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

Thank you,



DAS Fleet Services, Risk

Iowa Department of Administrative Services Division of Business and Property Services

Office: 515-725-2243 Das.Risk@iowa.gov https://das.iowa.gov

-- Forwarded message -----

From: Adams Jeannie <jadams@dps.state.ia.us>

Date: Wed, Jun 29, 2022 at 3:48 PM

Subject: FW: MEYERS - Vehicle Damage Report (See Attached)

To: Risk, DAS (das.risk@iowa.gov) <das.risk@iowa.gov>, vehicledamage <vehicledamage@dps.state.ia.us>

Please accept this notification on behalf of AD Meyers.

Thank you

Jeannie Adams ISP Fleet & Supply, Fleet Asset Manager Department of Public Safety 30 N.E. 48th Place Des Moines, Iowa 50313 Direct #: 515-725-0643

Cell Phone: 515-204-3019 Shop: 515-281-3277 Fax: 515-242-6321

Email: jadams@dps.state.ia.us<mailto:jadams@dps.state.ia.us>

[jobs]<https://dps.iowa.gov/divisons/administrative-services/dps-careers/47th-basic-academy>

From: Meyers Gerard <meyers@dps.state.ia.us> Sent: Wednesday, June 29, 2022 2:11 PM

To: Guill Bryan <guill@dps.state.ia.us>; Adams Jeannie <jadams@dps.state.ia.us>

Cc: Feddersen Paul <fedderse@dps.state.ia.us>

Subject: MEYERS - Vehicle Damage Report (See Attached)

Lt. Guill,

Please find a vehicle damage report attached for processing.

I have not submitted before so please advise what further steps I may need to take.

Thank you sir.

Gerard

[cid:image001.png@01D66429.72B9BC20]https://gcc02.safelinks.protection.outlook.com/? url=http%3A%2F%2Fwww.dps.state.ia.us%2FDCl%2Fsupportoperations%2FInformation%2Frecords% 2Findex.shtml&data=05%7C01%7Cjadams%40dps.state.ia.us%7Ca8595a31c3c64c66cbf508da5a0327fe% 7C8e7368ae110346c7aec2d08e01c2d874%7C0%7C0%7C637921267938844733%7CUnknown% 7CTWFpbGZsb3d8eyJWIjoiMC4wLjAwMDAiLCJQIjoiV2luMzIiLCJBTiI6Ik1haWwiLCJXVCI6Mn0%3D%7C3000% 7C%7C%7C&sdata=PLP3ike8XXcVGpKbybk9%2B1oEenv%2Bl3RT4ImtloloiGY%3D&reserved=0> Gerard F. Meyers | Assistant Director Division of Criminal Investigation Cyber Crime Bureau Iowa Department of Public Safety 215 East 7th Street | Des Moines, Iowa 50319 Direct: (515) 725-6053 | Fax: (515) 725-6020

Email: meyers@dps.state.ia.us<mailto:meyers@dps.state.ia.us>

NOTICE This email message (including any file attachments transmitted with it) is for the sole use of the intended recipient(s) and may contain confidential and legally privileged information. Any unauthorized use or disclosure of this email by an unintended recipient is prohibited. If you have received this e-mail in error please notify the sender by return e-mail and destroy all copies of the original message. No representation is made that this email or any attachments are free of viruses. Virus scanning is recommended and is the responsibility of the recipient.

9 attachments



image001.png 20K



1.jpg 2025K

2.jpg 3632K

State Vehicle Damage Report

Attach this completed form to an email along with the items identified below and send to: DPS - Vehicle Damage; DAS - Risk

- > One Repair Estimate from Approved State Bid Shop
- > DOT MARS Report (if reportable)
- > Memo from the Driver of the State Vehicle
- > 3-4 photos of the vehicle damage

***Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

STATE VEHICLE: (Mark if Act of Nature⊠) CASE #:

STATE VEHICLE. (Wark II Act of Nature) CASE #:								
Date:	06/25/2022		Time:	8:00	a.m.			
(Month/Day/Year)			(Time plus a.m./p.m.)					
Vehicle Plate #:	LBS	013	Vehicle Mileage:	2512				
Vehicle Description: (Yr/Make/Model/ & Vin#)	2022 / Chevrolet / Traverse LT / 1GNEVMKW8NJ108							
Assigned To:	AD Mey	Gerard rers	Badge #	I-142				
Driven By:	AD Gerard Meyers		Badge #	I-142				
Driver's Lic #:	Lic #: 239CC0681		Damage:	\$				
Vehicle Towed: No (Yes / No)			Towed By:					
Towed To:			Towing Cost:	\$				
Seat Belt: Yes (Yes / No)			Type of Vehicle: (Marked/Semi /Unmarked)	Unmark	ed			
Injured/Injuries:		None						
Occupants: (Other than driver)		None						

VEHICLE #2:

DL #:	State:
Vehicle Lic. #	State:
Driver's Name:	
Driver's Address:	
Owner's Name:	
Owner's Address:	

						20 20 20	
0 1 . DI							
Owner's Phone:							
Insurance Info: (Carrier/Policy #/Phone)							
Veh Description:					9		
(Yr/Make/Model & Vin#)	V.						
	Φ.						
Damage:	\$			Seat			No
Injured/Injuries:				(Yes /	NO)		
Occupants:			0 300		-		
(Other than driver)					· · · · · · · · · · · · · · · · · · ·		
Occupant(s) Wearing	ng Seat	Belt: (Yes/No)		Yes		
OTHER INFORMA	TION						
Witnesses:	TION.	Nor	16				
Accident Location:		NA	10	200			
(Street/Hwy)		147					
County:		Wa	rren				
Weather/Road Con	ditions:	Hail	I Storn	n			
Narrative: DPS Vel	hicle #10)5143	- On t	he mo	orning of	f Satu	rday, June 25,
2022 a large hail sto	orm mov	ed thr	ough	my ar	ea of re	sidenc	ce. I did not
inspect my vehicle	until a co	olleagu	ue obs	ervec	l minor h	nail da	mage to the
hood of my vehicle							
the minor damage.							
damage report in a						nage e	evaluation and
repair. Thank you.	AD Ger	ard F.	Meye	rs (I-	142).		
Property Damage o	ther that	n NA	Δ		7000		100.749
Vehicles:	tiloi tilai	1 137	X				
Cost:			\$				
Citations Issued To	None				0:-:		
(List Charge(s) and Statute	-	110110					
				We discon	0		
Investigating Officer	<u>:</u>		N	1A			
					-		
	g gr	_					
VEHICLE #3: (If ne		For m	ore v	ehicle	es, plea	se ma	ike extra
copies of this port	ion)			1			
DL #:				I S	tate:		

Vehicle Lic. #		State:	
Driver's Name:			
Driver's Address:			
Owner's Name:			
Owner's Address:			
Owner's Phone:			
Insurance Info: (Carrier/Policy #/Phone)			
Veh Description: (Yr/Make/Model & Vin#)			
Damage:	\$	Seat Belt: (Yes / No)	Yes
Injured/Injuries:			
Occupants: (Other than driver)			
Occupant(s) Wearing	ng Seat Belt: (Yes/No	Yes	

QUALITY CLAIMS SOLUTIONS

105 N Krohn Place SIOUX FALLS, SD 57103

Phone: (877) 237-3727, FAX:(866) 371-2844 qcs@qcsdirect.com

For:

QUALITY CLAIMS SOLUTIONS

DAS Fleet Services

Estimate of Record

Owner: IOWA STATE PATROL Job Number:

Written By: Wayne Malsam

IOWA STATE PATROL Insured:

Collision

Point of Impact: 27 Hail

Policy #:

UNKNOWN

8/1/2022 12:00 PM

Claim #:

APDSOI0241986-001

Workfile ID:

5a2a9510

Date of Loss: Days to Repair:

Owner:

Type of Loss:

IOWA STATE PATROL URBANDALE, IA 50323 Inspection Location:

Dent Eliminators Urbandale, IA 50322

Other

(515) 278-1537 Evening

Repair Facility:

VEHICLE

2022 CHEV Traverse LT2 AWD w/Cloth Interior (Fleet) 4D UTV 6-3.6L Gasoline Direct Injection

VIN:

1GNEVMKW8NJ108326

Production Date:

Interior Color:

License:

Odometer:

0

Exterior Color:

State:

Condition:

TRANSMISSION

Automatic Transmission

4 Wheel Drive

POWER

Power Steering Power Brakes

Power Windows Power Locks

Power Mirrors Heated Mirrors

Power Driver Seat

DECOR **Dual Mirrors Body Side Moldings** Privacy Glass

Console/Storage

CONVENIENCE

Air Conditioning Intermittent Wipers

Tilt Wheel Cruise Control Rear Defogger

Keyless Entry Alarm

Message Center

Steering Wheel Touch Controls

Rear Window Wiper Climate Control **Dual Air Condition** Backup Camera Parking Sensors

RADIO

AM Radio FM Radio Stereo

Search/Seek

Auxiliary Audio Connection

Satellite Radio **SAFETY**

Drivers Side Air Bag Passenger Air Bag Anti-Lock Brakes (4) 4 Wheel Disc Brakes

Traction Control Stability Control

Front Side Impact Air Bags Head/Curtain Air Bags Communications System

Hands Free Device

Xenon or L.E.D. Headlamps Blind Spot Detection

Lane Departure Warning

ROOF

Luggage/Roof Rack

SEATS Cloth Seats **Bucket Seats** 3rd Row Seat

WHEELS Aluminum/Alloy Wheels

PAINT

Clear Coat Paint **OTHER**

Signal Integrated Mirrors

Estimate of Record

Owner: IOWA STATE PATROL

Job Number:

2022 CHEV Traverse LT2 AWD w/Cloth Interior (Fleet) 4D UTV 6-3.6L Gasoline Direct Injection

Line	-	Oper	Description	Part Number	Qty	Extended Price \$		Labor	Paint
1	HOOD	1.							
2	*	Subl	Hood +25%		1	281.25	X		
3	#		2 o/s		1	80.00	X		
4		R&I	R&I hood assy					0.7	
5		R&I	Insulator					0.3	
6	FENDER								
7	*	Subl	LT Fender		1	100.00	X		
8		R&I	LT Fender liner					0.4	
9	FRONT DOOR								
10	*	Subl	LT Door shell +25%		1	125.00	X		
11	ROOF								
12	*	Subl	Roof panel w/o silver roof rails +25%		1	406.25	X		
13	*	R&I	Headliner w/o sunroof					<u>3.5</u>	
14	ELECTRICAL								
15		R&I	Antenna w/o digital audio					0.3	
16	PILLARS, ROC	KER &	FLOOR						
17	*	Subl	LT Uniside panel +25%		1	<u>187.50</u>	X		
18	*	Subl	RT Uniside panel +25%		1	125.00	X		
19	QUARTER PAN	IEL							
20	*	Subl	LT Quarter panel		1	225.00	X		
21	REAR LAMPS								
22		R&I	LT Tail lamp all					0.2	
23	LIFT GATE								
24	*	Subl	Lift gate		1	175.00	X		
25		R&I	Lower gate trim w/o power liftgate black					0.3	
26		R&I	Upper gate trim black					0.1	
27	*	R&I	Lift gate					1.2	
28		R&I	Spoiler					0.8	
				SUBTOTALS		1,705.00	****	7.8	0.0

Estimate of Record

Owner: IOWA STATE PATROL

Job Number:

2022 CHEV Traverse LT2 AWD w/Cloth Interior (Fleet) 4D UTV 6-3.6L Gasoline Direct Injection

ESTIMATE TOTALS

Category	Basis		Rate	Cost \$
Parts				0.00
Body Labor	7.8 hrs @	@	\$ 60.00 /hr	468.00
Miscellaneous				1,705.00
Subtotal				2,173.00
Total Cost of Repairs				2,173.00
Deductible				0.00
Total Adjustments	t			0.00
Net Cost of Repairs	70 a 35			2,173.00

MyPriceLink Estimate ID / Quote ID:

983455342522277888 /

THIS IS NOT AN AUTHORIZATION TO BEGIN REPAIRS.

SUPPLEMENTS - Please be advised that the INSURANCE COMPANY requires notice of any supplements prior to the work being performed. Failure to notify INSURANCE COMPANY and allow INSURANCE COMPANY to review the supplemental charges may result in non-payment of the supplemental items.

ESTIMATE AUDIT - THIS DOCUMENT IS NOT AN APPRAISAL. INQUIRIES SHOULD BE DIRECTED TO THE INSURANCE COMPANY LISTED AT THE TOP OF THIS DOCUMENT.

REPAIR SHOPS CAN CONTACT QCS AUDITOR FOR ANY REPAIR RELATED INQUIRIES AT 1-877-237-3727.