### OFFICE OF AUDITOR OF STATE



Rob Sand Auditor of State

State Capitol Building
Des Moines, Iowa 50319-0004
Telephone (515) 281-5834

October 14, 2025

Kristi Onstot Executive Council L O C A L

Subject: Hail Damage to Vehicle #363 on September 22, 2025

Department of Administrative Services Claim dated September 26, 2025

AOS Claim ID: 4175

In accordance with Executive Council policy, we have examined the claim for 29C.20 funds for the above-mentioned damage. It is our conclusion that the above damage incurred by the Department of Administrative Services is covered by Chapter 29C.20 of the Code of Iowa. Therefore, we recommend an Executive Council allocation in the amount of \$3,607.25, subject to an audit of actual invoices.

Sincerely,

Brian R. Brustkern, CPA

Bri R. Bris

Deputy Auditor of State

cc: Kyle Wear, Fleet Services CFO, Department of Administrative Services Ryan Betts, Fleet Services Risk Program Manager, Department of Administrative Services

Heather Hackbarth, Department of Management



KIM REYNOLDS, GOVERNOR CHRIS COURNOYER, LT. GOVERNOR

ADAM STEEN, DIRECTOR

Date: September 26, 2025

To: Tammy Hollingsworth, Auditor of State

Victoria Newton, Treasurer of State

**Executive Council** 

Re: ALLOCATION REQUEST - 29C20 Claim for Executive Council Consideration

Vehicle / Event	#363 / Hail
Event Date	September 22, 2025
Summary	Vehicle 363 - sustained hail damage (Claim # TBD)
Amount Requested	\$3,607.25 TOTAL
Supporting Documentation	29C20 Email Notification, Accident Report, & Repair Estimate

If you have any questions or are in need of additional information, please do not hesitate to contact me.

Thank you

Ryan Betts

DAS Fleet Risk Program Manager

ryan.betts1@iowa.gov

515-281-8008



Risk, DAS <das.risk@iowa.gov>

## Fwd: Trooper Costello #363 Hail Damage 9/22/25 2025022926

1 message

Risk, DAS <das.risk@iowa.gov>

Tue, Sep 23, 2025 at 10:29 AM

To: Tammy Hollingsworth <Tammy.Hollingsworth@aos.iowa.gov>, TOS ExecutiveCouncil <executivecouncil@tos.iowa.gov>

Please accept this email as initial 24 hr notification for AON, vehicle 363 sustained hail damage on 9/22/2025. I will forward all information as soon as it is received.

### **DAS Risk**

Central Procurement and Fleet Services Enterprise

Iowa Department of Administrative Services

510 E 12<sup>th</sup> St, Des Moines, IA 50319

515-281-8008 office

das.risk@iowa.gov

https://das.iowa.gov



All accidents must be reported via email or phone to Fleet Services within 24 hours. All accident reports and estimates are due within 72 hours of an accident. Agencies have 60 days to complete repairs to vehicles once approval is given.

----- Forwarded message ------

From: Leffler Kevin < leffler@dps.state.ia.us>

Date: Tue, Sep 23, 2025 at 10:20 AM

Subject: Trooper Costello #363 Hail Damage 9/22/25 2025022926

To: vehicledamage <vehicledamage@dps.state.ia.us>, DAS Risk <das.risk@iowa.gov>

Cc; Cunningham Michael <mcunning@dps.state.ia.us>, Cunningham Jeffrey <cunningh@dps.state.ia.us>, Luke Tracy

<tluke@dps.state.ia.us>

All.

While on patrol, Trooper Costello #363 received hail damage on his patrol car in Harrison County last night 9/22/25 around 2130.

All required information will be forthcoming.

Thanks,

### Sergeant Kevin Leffler ★141★

Iowa State Patrol Post 4

Iowa Department of Public Safety

3710 Highway 30 East

Denison, Iowa 51442

Office: 712-263-4621

Fax: 712-263-2325

leffler@dps.state.ia.us

https://dps.iowa.gov/

https://dpscareers.com/



\*\*NOTICE\*\* This e-mail message (including any file attachment transmitted with it) is for the sole use of the intended recipient(s) and may contain confidential and legally privileged information. Any unauthorized use or disclosure of this e-mail by an unintended recipient is prohibited. If you have received this e-mail in error, please notify the sender by return e-mail and destroy all copies of the original message. No representation is made that this e-mail or any attachments are free of viruses. Virus scanning is recommended and is the responsibility of the recipient.

# **State Vehicle Damage Report**

Attach this completed form to an email along with the items identified below and send to: Vehicledamage

- > One Repair Estimate from Approved State Bid Shop
- > DOT MARS Report (if reportable)
- > Memo from the Driver of the State Vehicle
- > 3-4 photos of the vehicle damage

\*\*\*Sworn Officers only: Complete a Line of Duty Form #432037 and send to DOT if 10-50 was reportable!!!

STATE VEHICLE: (Mark if Act of Nature ≥ ) CASE #: 2025022926

SIAIL VEINCE	(	iain ii Aot oi i	tatalco j onto E il i	LUZULZU		
Date: (Month/Day/Year)	9/22	/2025	Time: (Time plus a.m./p.m.)	9:30 p.m.		
Vehicle Plate #:	363		66,281			
Vehicle Description: (Yr/Make/Model/ & Vin#)		21 Dodge Charger 3CDXKG3MH644697				
Assigned To:	Trp.	Costello	Badge #	363		
Driven By:	Trp.	Costello	Badge #	363		
Driver's Lic #:	363		Damage:	\$3607.25		
Vehicle Towed: (Yes / No)	No		Towed By:	n/a		
Towed To:	n/a		Towing Cost:	\$0		
Seat Belt: (Yes / No)	Yes		Type of Vehicle: (Marked/Semi /Unmarked)			
Injured/Injuries:		no				
Occupants: (Other than driver)		none				

### **VEHICLE #2:**

DL #:	State:	
Vehicle Lic. #	State:	
Driver's Name:		
Driver's Address:		
Owner's Name:		
Owner's Address:		
Owner's Phone:		
Owner's Address:  Owner's Name: Owner's Address:		

Insurance Info: (Carrier/Policy #/Phone)				
Veh Description:				
(Yr/Make/Model & Vin#)				
Damage:	\$		Seat Belt:	
Injured/Injuries:	N/A		(Yes / No)	
Occupants:	N/A			
(Other than driver)				
Occupant(s) Wearir	ng Seat E	elt: (Yes/No	) No	
OTHER INFORMA	TION:			
Witnesses:	11011.	None		
Accident Location:			e 29 86mm	
(Street/Hwy)		Interstati	20 00111111	
County:		Harrison	County	
Weather/Road Con-	ditions:	Rain/Hai	I-Wet	
Narrative: Trooper		•	_	
				9:30 PM. Damaged
areas include hood,	the roof.	and each	roor quarter no	nel
	<i>'</i>		rear quarter pa	1101.
· · · · · · · · · · · · · · · · · · ·	ŕ		real quarter pa	
	,		real quarter pa	
· · · · · · · · · · · · · · · · · · ·	,		rear quarter pa	
			real quarter pa	
Property Damage o			real quarter pa	
Property Damage o Vehicles:		None	rear quarter pa	
Property Damage o Vehicles: Cost:	ther than		rear quarter pa	
Property Damage o Vehicles:	ther than	None	real quarter pa	
Property Damage o Vehicles: Cost: Citations Issued To	ther than	None	rear quarter pa	
Property Damage o Vehicles: Cost: Citations Issued To	ther than	None \$	Sgt. Leffler #14	
Property Damage o Vehicles: Cost: Citations Issued To (List Charge(s) and Statute	ther than	None \$		
Property Damage of Vehicles: Cost: Citations Issued To (List Charge(s) and Statute) Investigating Office	ther than	None \$		
Property Damage of Vehicles: Cost: Citations Issued To (List Charge(s) and Statute) Investigating Officer VEHICLE #3:	ther than	None \$	Sgt. Leffler #14	
Property Damage of Vehicles: Cost: Citations Issued To (List Charge(s) and Statute) Investigating Officer VEHICLE #3: DL #:	ther than	None \$	Sgt. Leffler #14	
Property Damage of Vehicles: Cost: Citations Issued To (List Charge(s) and Statute) Investigating Officer VEHICLE #3: DL #: Vehicle Lic. #	ther than	None \$	Sgt. Leffler #14	
Property Damage of Vehicles: Cost: Citations Issued To (List Charge(s) and Statute) Investigating Officer  VEHICLE #3: DL #: Vehicle Lic. # Driver's Name:	ther than	None \$	Sgt. Leffler #14	
Property Damage of Vehicles: Cost: Citations Issued To (List Charge(s) and Statute) Investigating Officer VEHICLE #3: DL #: Vehicle Lic. #	ther than	None \$	Sgt. Leffler #14	
Property Damage of Vehicles: Cost: Citations Issued To (List Charge(s) and Statute) Investigating Officer  VEHICLE #3: DL #: Vehicle Lic. # Driver's Name:	ther than	None \$	Sgt. Leffler #14	
Property Damage of Vehicles: Cost: Citations Issued To (List Charge(s) and Statute) Investigating Officer  VEHICLE #3: DL #: Vehicle Lic. # Driver's Name: Driver's Address:	ther than	None \$	Sgt. Leffler #14	

Owner's Phone:				
Insurance Info: (Carrier/Policy #/Phone)				
Veh Description: (Yr/Make/Model & Vin#)				
Damage:	\$	Seat (Yes / N		No
Injured/Injuries:				
Occupants: (Other than driver)				
Occupant(s) Wearing	ng Seat Belt: (Vas/Na		Yes	



# **MEMORANDUM**

TO:

Supervision

FROM:

Trp. Costello

DATE:

15:24

**SUBJECT:** 

Vehicle Damage

### Supervision,

On 9/22/2025, I Trooper Austin Costello with the Iowa State Patrol, was traveling while assisting a motorist, south bound on I29 at the 86 Mile Marker at around 2130 hours. While traveling, my vehicle was struck by hail causing damage to the hood, roof, and each rear quarter panel. Storm lake radio called for a severe thunderstorm with chances of ping pong size hail and wind gusts around 2130 hours for Western Harrison county

# All Makes Collision Center 524 23rd Ave Council Bluffs, IA 51501

Phone: (712) 256-3195

### \*\*\* PRELIMINARY ESTIMATE \*\*\*

09/29/2025 07:39 AM

Owner

Owner: state of iowa

**Control Information** 

Loss Date: 07:39 File #: 363 HAIL

Loss Type: Accounting #:

Inspection

Inspection Date: 09/29/2025 08:08 AM

Assigned Date/Time: 07:39 AM First Contact Date/Time: 07:39 AM Second Contact Date/Time: 07:39 AM

Appraiser Name: Kortnie Getzschman

Inspection Type:

Received Date/Time: 07:39 AM Appointment Date/Time: 07:39 AM

Appraiser License #2:

Repairer

Repairer: ALL MAKES COLLISION

Address: 524 23rd ave

City State Zip: COUNCIL BLUFFS, IA 51501

Email: KARL.AAAUTO@LIVE.COM

Contact: KARL GETZSCHMAN

Work/Day: (712)256-3195 Cell: (712)355-0860

Work/Day:

Repair Start Date/Time: 07:39 AM

Repair Complete Date/Time: 07:39 AM Target Complete Date/Time: 07:39 AM Vehicle Drop Off Date/Time: 07:39 AM Vehicle Pick Up Date/Time: 07:39 AM

Days To Repair: 2

Vehicle

2021 Dodge Charger Police 4 DR Sedan

6cyl Gasoline 3.6 8-Speed Automatic

Lic Expire:

VIN: 2C3CDXKG3MH644697

Veh Insp#: Mileage Type: Actual Condition: Code: N3183F

Ext. Refinish: Two-Stage Int. Refinish: Two-Stage

**Options** 

1st Row LCD Monitor(s)

AM/FM Radio

Auto Adjust Suspension

Black Grille Chrome Trim

Daytime Running Lights **Dual Airbags** 

2nd Row Head Airbags **Analog Gauges** 

Automatic Power Locks

**Bucket Seats** Color-Keyed Bumper(s) Driver Knee Airbag

**Dual Exhaust System** 

4-Wheel Drive Anti-Lock Brakes Auxiliary Audio Input Cargo Lamp Cruise Control

**Dual Air Conditioning** Dual Zone Auto A/C

Elect. Stability Control	Electric Steering	Electronic Compass
Fuel Door Release	Full Size Spare Tire	Halogen Headlights
Head Airbags	Heated W/S Wiper Washers	Heavy Duty Suspension
Intermittent Wipers	Keyless Entry System	Keyless Ignition System
LED Brakelights	Laminated Glass	Leather Steering Wheel
Lighted Entry System	Overhead Console	Paddle Shifter
Power Brakes	Power Door Locks	Power Drivers Seat
Power Mirrors	Power Steering	Power Windows
Pwr Accessory Outlet(s)	Rain-Sensing W/S Wipers	Rear View Camera
Rear Window Defroster	Reverse Sensing System	Roll Over Prot. System
Side Airbags	Stability Cntrl Suspensn	Steel Wheels
Strg Wheel Radio Control	Tachometer	Temperature Gauge(s)
Tilt & Telescopic Steer	Tinted Glass	Tire Pressure Monitor
Traction Control System	Trip Computer	Trunk/Cargo Organizer
Velour/Cloth Seats	Wireless Audio Streaming	Wireless Phone Connect

Damages						***************************************		***************************************
Line O	p Guide	MC	Description	MFR.Part No.	Price	ADJ% B%	Hours	R
Front Body	/ And Win	dshield	<u> 1</u>					
1 S	B 83		Panel,Hood Aluminum	Sublet Repair	\$550.00*	+25.00		SM
2 R	l 86		Pad,Insulator Hood	R & I Assembly			0.3	SM
3 S	B 103		Fender,Front LT	Sublet Repair	\$125.00*			SM
4 S	B 104		Fender,Front RT	Sublet Repair	\$100.00*			SM
Roof								
5 S	B 341		Panel,Roof	Sublet Repair	\$950.00*			SM
6 R	347		Roof Headliner R & I	R & I Assembly			5.1	SM
Quarter Ar	ıd Rocker	Panel						
7 S			Panel,Bodyside Front LT	Sublet Repair	\$125.00*	+25.00		SM
8 S	B 504		Panel, Bodyside Front RT	Sublet Repair	\$300.00*	+25.00		SM
9 S	B 1389		Pnl,Qtr (in Window Opn LT	Sublet Repair	\$350.00*			SM
10 S	B 1390		Pnl,Qtr (in Window Opn RT	Sublet Repair	\$200.00*			SM
Deck Lid A	nd Back (	Blass						
11 S			Lid,Rear Deck	Sublet Repair	\$350.00*			SM
12 R	1 620		Pnl,Lid Inner Trim	R & I Assembly			0.3	SM
12	Items			,				
Estimate	Total & E	ntries		937781545355354554556565345168465544685546565534664453446444		***************************************	nus and respectively.	***************************************
						***************************************		

Labor	Rate	Replace Repair Hrs Hrs	Total Hrs		
Sheet Metal (SM) Mech/Elec (ME) Frame (FR) Refinish (RF)	\$55.00 \$55.00 \$55.00 \$100.00	5.7	5.7	\$313.50	
Labor Total Sublet Repairs Gross Total Net Total			5.7 Hc	ours \$3,293.75	\$313.50 \$3,607.25 \$3,607.25

Alternate Parts Y/00/00/00/00 Cumulative 00/00/00/00 Zip Code: 51501 Default Rate Name Default

Audatex Estimating 8.2.530 ES 09/29/2025 08:11 AM REL 8.2.530 DT 09/01/2025

State Disclosure: Not Selected

© 2025 Audatex North America, LLC.

### Op Codes

= User-Entered Value ^ = Labor Matches System Assigned Rates E = Replace OEM NG = Replace NAGS

EC = Replace Economy OE = Replace PXN OE Srpls

UE = Replace OE Surplus ET = Partial Replace Labor EP = Replace PXN

TE = Partial Replace Price EU = Replace Recycled PM = Replace PXN Reman/Reblt UM = Replace Reman/Rebuilt L = Refinish PC = Replace PXN Reconditioned

UC = Replace Reconditioned TT = Two-Tone SB = Sublet Repair I = Repair N = Additional Labor BR = Blend Refinish

IT = Partial Repair CG = Chipguard RI = R & I Assembly

P = Check AA = Appearance Allowance RP = Related Prior Damage



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

### © 2025 Audatex North America, LLC.

AUDATEX is a trademark owned by Audatex North America, LLC. All rights reserved.

09/29/2025 08:11 AM Page 3 of 3